
## **■WAX AND SEALER**

Wax and sealer are applied to the hemmed portions of the hood, door panels and luggage compartment door to improve rust-resistant performance.

## **■UNDER COAT**

PVC (Polyvinyl Chloride) coating is applied to the under side of the body. A thick coating to improve rust resistant performance is applied to the bottom side of the fender apron and other parts which are subject to damage by flying stones, etc.


: PVC Coating Area
: PVC Coating Area
(Thick Coating)



152BO12

## ■ ANTI-CHIPPING APPLICATION

Soft-chip primer is applied to the hood.



143BO07