MANHOLE SURVEY REPORT

Drainage survey


2614 - Topographic survey - Elm Road plot - Elm Road, Durham - 6 November 2026

11
Manholes in total

6
Types

LABELLED MAP

54.77818, -1.58850



54.77422, -1.58163

Clean water · Surface water · Foul water · Fire water · Combined sewer · Unknown

Satellite imagery: Esri, Maxar, Earthstar Geographics. Positions in WGS84; grid squares match the scale bar.

MANHOLE INDEX

Ref	Type	Latitude	Longitude	Cover lev...	Invert lev...	Depth (m)	Condition
MH001	Clean water	54.776222	-1.587807	48.2	46.58	1.62	Fair
MH002	Surface water	54.776209	-1.587004	48.08	46.98	1.1	Good
MH003	Foul water	54.776200	-1.586201	47.96	46.11	1.85	Good
MH004	Clean water	54.776719	-1.585050				
MH005	Fire water	54.777413	-1.585030				
MH006	Surface water	54.776184	-1.584059	47.6	46.3	1.3	Good
MH007	Foul water	54.776175	-1.583256				

MH008	Combined sewer	54.776165	-1.582320				
MH009	Surface water	54.775885	-1.583390				
MH010	Unknown	54.775252	-1.585010				
MH011	Foul water	54.774990	-1.587138	47	44.95	2.05	Good

MH001 - CLEAN WATER

Position	54.7762224, -1.5878071
Description	Cast iron cover in the footpath
Cover level (m)	48.2
Invert level (m)	46.58
Depth (m)	1.62
Diameter (mm)	1050
Material	Precast concrete
Pipe direction	E
Pipe diameter (mm)	150
Pipes in	1
Pipes out	1
Condition	Fair
Accessibility	Accessible
Observations	Light silt in the channel
Recorded	31 Oct 2026 by Tom Fletcher
Edited by	Tom Fletcher, Ann Smith
Last updated	6 Nov 2026

MH002 - SURFACE WATER

Position	54.7762093, -1.5870040
Description	-
Cover level (m)	48.08
Invert level (m)	46.98
Depth (m)	1.1
Diameter (mm)	1050
Material	Brick
Pipe direction	W
Pipe diameter (mm)	150
Pipes in	2
Pipes out	1
Condition	Good
Accessibility	Accessible
Recorded	1 Nov 2026 by Ellie Moore
Edited by	Ellie Moore
Last updated	1 Nov 2026

MH003 - FOUL WATER

Position	54.7762000, -1.5862009
Description	-
Cover level (m)	47.96
Invert level (m)	46.11
Depth (m)	1.85
Diameter (mm)	1050
Material	Precast concrete
Pipe direction	N
Pipe diameter (mm)	150
Pipes in	1
Pipes out	1

Condition	Good
Accessibility	Accessible
Recorded	2 Nov 2026 by Josh Riley
Edited by	Josh Riley
Last updated	2 Nov 2026

MH004 - CLEAN WATER

Position	54.7767185, -1.5850499
Description	Cast iron cover in the footpath
Accessibility	Accessible
Recorded	3 Nov 2026 by Tom Fletcher
Edited by	Tom Fletcher
Last updated	3 Nov 2026

Notes

03/11/2026 Tom Fletcher: Cover seized - coming back with a lifter tomorrow

MH005 - FIRE WATER

Position	54.7774130, -1.5850298
Description	-
Accessibility	Accessible
Recorded	4 Nov 2026 by Ellie Moore
Edited by	Ellie Moore
Last updated	4 Nov 2026

MH006 - SURFACE WATER

Position	54.7761838, -1.5840595
Description	-
Cover level (m)	47.6
Invert level (m)	46.3
Depth (m)	1.3
Diameter (mm)	1050
Material	Brick
Pipe direction	W
Pipe diameter (mm)	150
Pipes in	2
Pipes out	1
Condition	Good
Accessibility	Accessible
Recorded	31 Oct 2026 by Josh Riley
Edited by	Josh Riley
Last updated	31 Oct 2026

Notes

31/10/2026 Josh Riley: Cover seized - coming back with a lifter tomorrow

MH007 - FOUL WATER

Position	54.7761745, -1.5832564
Description	Cast iron cover in the footpath
Recorded	1 Nov 2026 by Tom Fletcher
Edited by	Tom Fletcher
Last updated	1 Nov 2026

MH008 - COMBINED SEWER

Position	54.7761645, -1.5823195
Description	-
Recorded	2 Nov 2026 by Ellie Moore
Edited by	Ellie Moore
Last updated	2 Nov 2026

MH009 - SURFACE WATER

Position	54.7758852, -1.5833903
Description	-
Recorded	3 Nov 2026 by Josh Riley
Edited by	Josh Riley
Last updated	3 Nov 2026

MH010 - UNKNOWN

Position	54.7752524, -1.5850098
Description	Cast iron cover in the footpath
Recorded	4 Nov 2026 by Tom Fletcher
Edited by	Tom Fletcher
Last updated	4 Nov 2026

MH011 - FOUL WATER

Position	54.7749901, -1.5871378
Description	-
Cover level (m)	47
Invert level (m)	44.95
Depth (m)	2.05
Diameter (mm)	1050
Material	Precast concrete
Pipe direction	N
Pipe diameter (mm)	150
Pipes in	1
Pipes out	1
Condition	Good
Accessibility	Accessible
Recorded	31 Oct 2026 by Ellie Moore
Edited by	Ellie Moore
Last updated	31 Oct 2026

Notes

31/10/2026 Ellie Moore: Cover seized - coming back with a lifter tomorrow