
axial position of the quench front



decay heat flooding rate (cold) system pressure feedwater temperature 120% RNS standard 3.82 cm/s 4.15 bar 40 deg C



Fig. 133 FEBA: 5x5 RØD BUNDLE TEST SERIES 2, TEST-No. 229