
## axial position of the quench front



decay heat flooding rate (cold) system pressure feedwater temperature 120% ANS standard 5.72 cm/s 4.11 bar 40 deg C



Fig. 178 FEBA: 5x5 RØD BUNDLE TEST SERIES 2, TEST-No. 228