


cladding temperature







decay heat flooding rate (cold) system pressure feedwater temperature 120% ANS standard 5.72 cm/s 4.11 bar 40 deg C

Fig. 170 FEBA: 5x5 ROD BUNDLE, TEST SERIES 2, TEST-No. 228