
## axial position of the quench front



decay heat
flooding rate (cold)
system pressure
feedwater temperature

120% ANS standard 5.82 cm/s 1.99 bar 40 deg C



Fig. 163 FEBA: 5x5 ROD BUNDLE TEST SERIES 2, TEST-No. 233