
04.Chand Bibi's Tomb Place - Kalaburagi

District: Kalaburagi
Taluk: Kalaburagi
Locality: Dargah Sheriff

Geo - Coordinates: Lat : 17.3436 ° N Long : 76.8510 ° E





This tomb which was in a bad state of preservation, was later properly conserved. The deep crevices on the surface of the dome have been filled up with cement and concrete, toned to match with the original colour of the masonry. The turrets of the parapet have been restored. The floor under the dome was cleared of debris, leading to the discovery of old stone flooring in a well-preserved condition. No grave could be traced.



3D Point Cloud

