LOWER COLUMBIA RIVER GRP OCTOBER 2015

## Ridgefield Levee Breach #2

## LCR-95.0R

Position - Location:	45° 44.686', -122° 45.482'	45° 44' 41.2", -122° 45' 28.9"	45.74477, -122.75804	Vancouver
----------------------	----------------------------	--------------------------------	----------------------	-----------


Strategy Objective: Exclusion: Prevent oil from travelling through breach in dike to Post Office Lake.

Implementation:

From BL-LCR-97.7R, launch workboat to breach in dike at Ridgefield National Wildlife Refuge with 500ft. boom. Anchor to AP-1 and AP-2 using natural anchors, do not insert shoreside anchor posts. Anchor to AP-3 using Danforth or other acceptable anchor, and anchor every 100-150ft. along boom length or as appropriate for conditions. Notify Environmental Unit if deploying strategies in this area.

Staging Area:	Remote: Stage at SA-LCR-97.7R, Langsdorf Landing	
Site Safety:	Slips, trips, and falls. Water hazards. Blackberry brambles and vegetation.	
Field Notes:	Site is decommissioned dike road at Ridgefield National Wildlife Refuge where drainage has eroded the road and dike to create breach that could open to Post Office Lake at high water.	
Watercourse:	River - With Tidal Influence - Columbia River	

Resources at Risk: Sensitive Resources Nearby, Waterfowl and Shorebird Concentrations, Wildlife Refuge



## Recommended Equipment

4	Each	Anchor - Danforth (or other appropriate type)		
2	Each	Anchoring System(s)- Shoreside		
500	Feet	Boom - B3 (River Boom) or equivalent		
1	Each	Workboat(s) - of adequate size for type and amount of boom		

## **Recommended Personnel**

1 Boat Operator	
2 Laborer	
1 Supervisor	

APPENDIX 4A 389