LOWER COLUMBIA RIVER GRP OCTOBER 2015

Cape Disappointment State Park (WA)

LCR-2.2R

Position - Location: 46° 17.177′, -124° 3.062′	46° 17' 10.6", -124° 3' 3.7"	46.28629, -124.05104	Ilwaco
---	------------------------------	----------------------	--------

Strategy Objective: Collection: Collect oil on modified shoreline to prevent oil from travelling downstream.

Implementation:

From Cape Disappointment State Park Boat Launch, BL-LCR-2.2, Crew 2 launch workboat towing line attached to 600ft. boom staged in parking lot. Crew 1 remain onshore river right at staging area and feed boom across to Crew 2. Crew 2 anchor at AP-2 in channel center and every 100-150ft. along boom length or as appropriate for flow conditions. Crew 1 anchor at AP-1 on shore using shoreside anchor posts. Collect oil using vac truck staged in parking lot. Notify Environmental Unit if deploying strategies in this area.


Staging Area: Onsite: Stage onsite at SA-LCR-2.2R

Site Safety: Slips, trips, and falls. Water hazards. Use caution around pilings and other possible submerged hazards.

Field Notes: Site is a boat launch and parking area with breakwall protecting boat ramps.

Watercourse: River - With Tidal Influence - Columbia River

Resources at Risk: Marshland(s), Public Lands/Facilities, Recreational Use Area, Sensitive Resources Nearby, State Park



Recommended Equipment

7	Each	Anchor - Danforth (or other appropriate type)
1	Each	Anchoring System(s)- Shoreside
600	Feet	Boom - B2 (Contractor Boom) or equivalent
1	Each	Vac Truck or Skimmer and Storage
1	Each	Workboat(s) - of adequate size for type and amount of boom

Recommended Personnel

1	Boat Operator	
4	Laborer	
1	Supervisor	

APPENDIX 4A 185