
DTC	P0335	Crankshaft Position Sensor "A" Circuit
DTC	P0339	Crankshaft Position Sensor "A" Circuit Intermittent

#### **DESCRIPTION**

The Crankshaft Position (CKP) sensor system consists of a CKP sensor plate and a pickup coil. The sensor plate has 34 teeth and is installed on the crankshaft. The pickup coil is made of an iron core and a magnet.

The sensor plate rotates and, as each tooth passes through the pickup coil, a pulse signal is created. The pickup coil generates 34 signals per engine revolution. Based on these signals, the ECM calculates the crankshaft position and engine RPM. Using these calculations, the fuel injection time and ignition timing are controlled.

DTC No.	DTC Detection Conditions	Trouble Areas	
P0335	No Crankshaft Position (CKP) sensor signal to ECM while cranking (1 trip detection logic)     No CKP sensor signal to ECM at engine speed of 600 rpm or more (1 trip detection logic)	Open or short in CKP sensor circuit     CKP sensor     Sensor plate (CKP sensor plate)     ECM	
P0339	Under conditions (a), (b) and (c), no Crankshaft Position (CKP) sensor signal to ECM for 0.05 seconds or more (1 trip detection logic):  (a) Engine speed 1,000 rpm or more  (b) Starter signal OFF  (c) 3 seconds or more have elapsed since starter signal switched from ON to OFF	Open or short in CKP sensor circuit     CKP sensor     Sensor plate (CKP sensor plate)     ECM	



Reference: Inspection using an oscilloscope HINT:

- The correct waveform is shown on the left.
- G2 stands for the Camshaft Position (CMP) sensor signal, and NE+ stands for the CKP sensor signal.

Items	Contents	
Terminals	CH1: G2 - NE- CH2: NE+ - NE-	
Equipment Settings	5 V/Division, 20 ms/Division	
Conditions	Cranking or idling	

#### MONITOR DESCRIPTION

If there is no signal from the CKP sensor despite the engine revolving, the ECM interprets this as a malfunction of the sensor.

If the malfunction is not repaired successfully, a DTC is set 10 seconds after the engine is next started.

ES

#### **MONITOR STRATEGY**

Related DTCs	P0335: Crankshaft position sensor range check during cranking P0335: Crankshaft position sensor range check during engine running	
Required Sensors/Components (Main)	Crankshaft Position (CKP) sensor	
Required Sensors/Components (Related)	-	
Frequency of Operation	Continuous	
Duration	Conditions met for 3 times	
MIL Operation	Immediate	
Sequence of Operation	None	

### **TYPICAL ENABLING CONDITIONS**

Monitor runs whenever following DTCs not present	None
--	------

# ES

## Crankshaft Position Sensor Range Check during Cranking P0335:

Starter	ON
Minimum battery voltage while starter ON	Less than 11 V
Number of camshaft position sensor signal pulse	6 or more

### **Crankshaft Position Sensor Range Check during Engine Running P0335:**

Engine speed	600 rpm or more
Starter	OFF
Time after starter from ON to OFF	3 seconds or more

### **TYPICAL MALFUNCTION THRESHOLDS**

## Crankshaft Position Sensor Range Check during Cranking P0335:

Number of crankshaft position sensor signal pulse	132 or less, or 174 or more


### Crankshaft Position Sensor Range Check during Engine Running P0335:

CKP sensor signal	No signal
-------------------	-----------

#### **COMPONENT OPERATING RANGE**

CKP sensor	•	CKP sensor output voltage fluctuates while crankshaft revolving 34 CKP sensor signals per crankshaft revolution	
------------	---	---	--

#### WIRING DIAGRAM




#### HINT:

- If no problem is found by this diagnostic troubleshooting procedure, troubleshoot the engine mechanical systems.
- Check the engine speed. The engine speed can be checked by using an intelligent tester. To check, follow the operation below:
  - (a) Connect an intelligent tester to the DLC3.
  - (b) Start the engine.
  - (c) Turn the tester ON.
  - (d) Select the following menu items: DIAGNOSIS / ENHANCED OBD II / DATA LIST / PRIMARY / ENGINE SPD.

The engine speed may be indicated as zero despite the engine revolving normally. This is caused by a lack of NE signals from the Crankshaft Position (CKP) sensor. Alternatively, the engine speed may be indicated as lower than the actual engine speed, if the CKP sensor voltage output is insufficient.

Read freeze frame data using an intelligent tester. Freeze frame data record the engine condition when
malfunctions are detected. When troubleshooting, freeze frame data can help determine if the vehicle
was moving or stationary, if the engine was warmed up or not, if the air-fuel ratio was lean or rich, and
other data, from the time the malfunction occurred.

## 1 INSPECT CRANKSHAFT POSITION SENSOR (RESISTANCE)



- (a) Disconnect the C5 Crankshaft Position (CKP) sensor connector.
- (b) Measure the resistance between terminals 1 and 2. **Standard Resistance**

Tester Connections	Specified Conditions
1 - 2	1,630 to 2,740 Ω at cold
1 - 2	2,065 to 3,225 $\Omega$ at hot

#### HINT:

Terms cold and hot refer to the temperature of the coils. Cold means approximately -10° to 50°C (14°to 122°F). Hot means approximately 50° to 100°C (122° to 212°F).

(c) Reconnect the CKP sensor connector.




REPLACE CRANKSHAFT POSITION SENSOR

OK

2

### CHECK HARNESS AND CONNECTOR (CRANKSHAFT POSITION SENSOR - ECM)



- (a) Disconnect the C5 CKP sensor connector.
- (b) Disconnect the E4 ECM connector.
- (c) Check the resistance.

### Standard Resistance (Check for open)

Tester Connections	Specified Conditions
NE+ (C5-1) - NE+ (E4-27)	Below 1 Ω
NE- (C5-2) - NE- (E4-34)	Below 1 $\Omega$

#### Standard Resistance (Check for short)

Tester Connections	Specified Conditions
NE+ (C5-1) or NE+ (E4-27) - Body ground	10 kΩ or higher
NE- (C5-2) or NE- (E4-34) - Body ground	10 kΩ or higher


- (d) Reconnect the ECM connector.
- (e) Reconnect the CKP sensor connector.

NG\_\_

REPAIR OR REPLACE HARNESS OR CONNECTOR

OK

# 3 CHECK CRANKSHAFT POSITION SENSOR (SENSOR INSTALLATION)



(a) Check the CKP sensor installation.

OK:

Sensor is installed correctly.

NG

**SECURELY REINSTALL SENSOR** 



4 CHECK CRANKSHAFT TIMING PULLEY (TEETH OF PLATE)

(a) Check the teeth of the sensor plate.

OK:

Sensor plate does not have any cracks or deformation.

NG

REPLACE CRANKSHAFT POSITION SENSOR PLATE



**REPLACE ECM** 

ES