

United States Department of Agriculture Animal and Plant Health Inspection Service

35161729210355 Insp id

Inspection Report

Wild Animal Safari Inc

P O Box 1197

Pine Mountain, GA 31822

Customer ID: 32761

Certificate: 57-C-0221

Site: 001

WILD ANIMAL SAFARI INC

Type: ROUTINE INSPECTION

Date: 04-FEB-2016

3.125(a) REPEAT

FACILITIES, GENERAL.

The Rhino barn, housing one (1) Rhino, has several stand alone posts. These post go from the ground to the roof of the open front barn, serving as the structural stabilizers for the front of the barn. Several of these post have been chewed and rubbed by the Rhino to the point of being almost chewed in half. This is weakening the structural strength of the posts creating an unsafe environment for the Rhino. The outdoor housing facilities shall be structurally sound and shall be maintained in good repair to protect the animals from injury and to contain the animals.

3.127(c) REPEAT

FACILITIES, OUTDOOR.

In the drive through park, where the water buffalo are located next to the dam, there is a drainage hole in the ground. It is about 2 to 3 feet in depth and does not have a cover or barrier around it to prevent animal access. The sides of the hole are steep which would hinder a juvenile animal from being able to climb out. It also has a large metal drain pipe sticking out of the dirt that is rusty with sharp edges exposed. The location of the hole was marked by a piece of white PVC pipe that has fallen into the drain hole. Should a juvenile or small animal fall into the large hole, or a larger animal stumble on it they could potentially become injured from the fall, or become injured by the metal pipe edges. Any man made structure, or situation created, within the animal areas, shall be made safe to protect the welfare of the animals exposed.

The entire surface area of the small pen attached to the left side of the main enclosure for the lions has standing water and mud. This pen is lower then the other attached enclosures which allows the run-off water from the other enclosures to flow into it. There are no drainage pipes and the water is unable to drain freely from the sides resulting in standing water and mud. Poor drainage can lead to an increase in disease hazards, poor pest control and cause contamination of animals exposed to it, resulting in illness. Adequate drainage shall be provided to allow rapid removal of excess water and prevent accumulations thereby protecting the lions from disease hazard and contamination.

The dirt and sparsely grassed enclosure containing two (2) Tigers appears to be holding moisture in the front of and

Prepared By: BRENDA PIETROSANTE, A C I USDA, APHIS, Animal Care 09-FEB-2016

Title: ANIMAL CARE INSPECTOR 6011

Received by Title: GENERAL MANAGER Date:


09-FEB-2016



United States Department of Agriculture Animal and Plant Health Inspection Service

35161729210355 Insp_id

Inspection Report



Prepared By: BRENDA PIETROSANTE, A C I USDA, APHIS, Animal Care Date:

Title: ANIMAL CARE INSPECTOR 6011

Received by Title: GENERAL MANAGER Date: 09-FEB-2016

Page 2 of 2

09-FEB-2016



United States Department of Agriculture Animal and Plant Health Inspection Service

Customer: 32761 Inspection Date: 04-FEB-16

Species Inspected

Cust No	Cert No	Site	Site Name	Inspection
32761	57-C-0221	001	WILD ANIMAL SAFARI INC	04-FEB-16

Count	Scientific Name	Common Name	
000007	Antilope cervicapra	BLACKBUCK	
000001	Atelerix albiventris	HEDGEHOG	
000058	Axis axis	AXIS DEER / SPOTTED DEER / CHITAL	
000016	Bison bison	AMERICAN BISON	
000002	Bos frontalis	GAYAL/GAUR	
000018	Bos taurus	CATTLE / COW / OX / WATUSI	
000003	Boselaphus tragocamelus	NILGAI	
000020	Bubalus bubalis	ASIATIC WATER BUFFALO	
000001	C. pygerythrus	VERVET	
000001	Camelus dromedarius	DROMEDARY CAMEL	
000002	Canis lupus	GRAY WOLF / GREY WOLF / TIMBER WOLF	
000004	Capra hircus	DOMESTIC GOAT	
000001	Cebus capucinus	WHITE-HEADED / WHITE-THROATED CAPUCHIN	
000001	Ceratotherium simum	WHITE RHINOCEROS	
000002	Cercopithecus hamlyni	OWL-FACED MONKEY	
000030	Cervus c. canadensis	ELK	
000001	Cervus nippon	SIKA DEER	
000001	Choloepus hoffmanni	HOFFMANN'S TWO-TOED SLOTH	
000001	Crocuta crocuta	SPOTTED HYENA	
000007	Dolichotis patagonum	PATAGONIAN CAVY / MARA	
000012	Equus quagga	BURCHELL'S / GRANT'S / CHAPMAN'S / PLAINS ZEBRA	
000001	Genetta genetta	SMALL SPOTTED GENET	
000002	Giraffa camelopardalis	GIRAFFE	
000001	Hydrochaeris hydrochaeris	CAPYBARA	
000005	Lama glama	LLAMA	
000003	Lama pacos	ALPACA	
000002	Lemur catta	RING-TAILED LEMUR	
000001	Leptailurus serval	SERVAL	
000002	Lupus hallstromi	NEW GUINEA SINGING DOG	
000001	Macaca nigra	SULAWESI CRESTED MACAQUE	
000003	Nasua nasua	SOUTH AMERICAN COATI	
000002	Osphranter rufus	RED KANGAROO	
000039	Ovis aries aries	SHEEP INCLUDING ALL DOMESTIC BREEDS	
000003	Panthera leo	LION	
000001	Panthera leo x panthera tigris	LIGER	
000001	Panthera pardus	LEOPARD	
000002	Panthera tigris	TIGER	
000002	Papio anubis	OLIVE BABOON	
000002	Papio hamadryas	HAMADRYAS BABOON	
000001	Saguinus oedipus	COTTON-TOP TAMARIN	



000050

000002

000315

Sus scrofa domestica

Ursus americanus

Total

United States Department of Agriculture Animal and Plant Health Inspection Service

Customer: 32761 Inspection Date: 04-FEB-16

DOMESTIC PIG / POTBELLY PIG / MICRO PIG

NORTH AMERICAN BLACK BEAR

Species Inspected

Cust No	Cert No	Site	Site Name	Inspection
32761	57-C-0221	001	WILD ANIMAL SAFARI INC	04-FEB-16
Count	Scientific Name		Common Name	