

## United States Department of Agriculture Animal and Plant Health Inspection Service

205141016540901 Insp\_id

### **Inspection Report**

Bath Inc.

Customer ID: 323171

2000 E. Prospect Rd.

Certificate: 84-C-0127

Fort Collins, CO 80525

Site: 001

Bath, Inc.

Type: ROUTINE INSPECTION

Date: 22-JUL-2014

## 2.40(b)(2)

#### ATTENDING VETERINARIAN AND ADEQUATE VETERINARY CARE (DEALERS AND EXHIBITORS).

The two reindeer cows had overgrown hooves to the point that the front dewclaws made contact with the ground and, for the cow named Bossy, the front toes were starting to cross. Excessive hoof growth can contribute to abnormal gait which can cause a change in the toe joints and may contribute to osteoarthritis especially in older animals such as these.

The facility needs to have a better plan to manage the growth of the hooves to prevent them from getting too long instead of only once a year when the antler velvet is shed. The attending veterinarian was contacted immediately following the inspection to setup an appointment for hoof trimming and evaluation of the animals.

The program of veterinary care must include appropriate methods to prevent, control, diagnose, and treat diseases, injuries, and other conditions that may arise.

To be corrected by 7/31/2014.

#### 3.129(a)

#### FEEDING.

The hay and mineral block supplement for two reindeer cows are being fed directly on the ground. These food items can be easily contaminated by excreta in the pen and by the animals walking through the hay, which is directly in front of the water receptacle and the entrance to the shelter structure.

Contamination of feed can lead to intestinal parasitism or overgrowth of microorganisms which pose a risk to the health of these animals and feeding off the ground reduces this risk.

The food shall be wholesome, palatable, and free from contamination and of sufficient quantity and nutritive value to maintain all animals in good health.

To be corrected by 7/26/2014.

Prepared By: TRACY THOMPSON, D V M USDA, APHIS, Animal Care Date:

24-JUL-2014

Title: VETERINARY MEDICAL OFFICER 5044

Received by Title: GREENHOUSE GROWER Date: 24-JUL-2014


21 002 201



## United States Department of Agriculture Animal and Plant Health Inspection Service

**205141016540901** Insp\_id

## **Inspection Report**



Page 2 of 2

Received by Title: GREENHOUSE GROWER

Date:

24-JUL-2014



## United States Department of Agriculture Animal and Plant Health Inspection Service

Customer: 323171
Inspection Date: 22-JUL-14

# **Species Inspected**

Cust No	Cert No	Site	Site Name	Inspection
323171	84-C-0127	001	Bath, Inc.	22-JUL-14

CountScientific NameCommon Name000002Rangifer tarandusREINDEER

000002 Total