

www.vitrox.com

V810i S2EX Imaging





Automated Board Inspection

Imaging Introduction


Hardware and software that :

- Generate X-Radiation
- Capture Images
- Process Images




Imaging Process Flow

Automated Board Inspection




ABI Tomosynthesis

Automated Board Inspection




- As opposed to 5DX's Laminography, object/board is moving in Tomosynthesis during image acquisition while x-ray spot and detector (camera) are not.
- To obtain different angle images, multiple TDI cameras are installed at different angle with respect to the object. In this example 8 cameras are installed.



ABI Image Reconstruction Process

Automated Board Inspection




Step1: Digitally SHIFT image to the focal plane – Blue Square



Automated Board Inspection

Image Reconstruction Process




Step2: Digitally ADD the SHIFTED image



Automated Board Inspection

Image Reconstruction Process



Step 3: Reconstruct Yellow Triangle




Automated Board Inspection

X-Ray Digital Tomosynthesis

- Simple explanation of how it works:



Acquire multiple 2D projection images

Utilize parallax to separate Top side from Bottom side of PCB.



Top Side

Bottom Side



Step 1: Select image

Step 2: Align Image 2 and combine


Step 3: Align image 3 and combine

Resulting Combined Image: 1 + 2 + 3



X-Ray Digital Tomosynthesis


Automated Board Inspection





X-Ray Digital Tomosynthesis


Automated Board Inspection





Automated Board Inspection


X-Ray Digital Tomosynthesis





Automated Board Inspection


X-Ray Digital Tomosynthesis





Automated Board Inspection


X-Ray Digital Tomosynthesis





Automated Board Inspection


X-Ray Digital Tomosynthesis





Automated Board Inspection


X-Ray Digital Tomosynthesis





Automated Board Inspection


X-Ray Digital Tomosynthesis





Automated Board Inspection


X-Ray Digital Tomosynthesis






Automated Board Inspection

X-Ray Digital Tomosynthesis





Shift and Add

1) Shift to Align

2) Add and divide (average) to emphasis the desired area



Automated Board Inspection

Imaging Hardware Definition

X-Ray Tube - to generate X-Ray source where pass through scanning object to generate image (as emitter).

X-Ray Camera Array - As receiver to snap image projected X-Ray sources + scanning object. Acquires images and sends to IRPs via Ethernet cables and the Gigabit Switch

Camera Controller (Trigger board) – to provide Power and Triggers to Camera Array via Fire wire connections.

Gigabit Switch – Controls all image information between the Camera Array, the IRPs, and the System Controller

Image Reconstruction Processors – Reconstruct Digital images from the Camera Array

Y Axis Motion – Provides signals to Camera Controller to call cameras capture image

Digital I/O Assembly - Reads status of Camera Controller and controls Synthetic Triggers



Image Reconstruct Processor Driver

Automated Board Inspection






Image Reconstruct Processor Driver -
Installed at Main controller and main function to reconstruct image capture by 14 cameras 2D to 3D

Copyright © ViTrox All Rights Reserved.

ABI X-Ray Source Tab

Automated Board Inspection




- Manual power On/Off X-Ray tube power
- Checking tube healthy condition



X-Ray Camera Tab


Automated Board Inspection







X-Ray Tube Placement

Automated Board Inspection



20.06.2017 10:35





Top





Bottom



Hardware Overview - Trigger Board


Automated Board Inspection







Hardware Overview - Trigger Board

Automated Board Inspection



Fuse, 250vAC , 3A

Automated Board Inspection



Automated Board Inspection


Camera Head

Connect to Gigabit Switch

ID Jumper


Not in used

IR Sensor



Top

Connect to Trigger Board



Bottom



Automated Board Inspection

Hardware Overview - X-Ray Camera- Gen 1




Automated Board Inspection

Camera Head

Connect to Gigabit Switch


ID Jumper

IR Sensor





Top

Connect to Trigger Board



Bottom




Automated Board Inspection

Camera Head

Connect to Gigabit Switch


ID Jumper

IR Sensor





Top


Connect to Trigger Board




Bottom

Not in used










Y Axis Motion Hardware Overview

Automated Board Inspection



Linear Encoder Scale
(Glass Scale)

Y axis read head encoder


Y Axis Servo Motor

07.11.2017 10:49



Y Axis Motion Hardware Overview

Automated Board Inspection




Y Axis Kollmorgen
Assembly

Digital I/O Slide

10:07

Camera
Triggers Out
to Trigger
Board

Y-Axis
Encoder Read
Head







WEE KAH KHIM
Vice President & General Manager



GARY LEONG
Sales Director



周道南
Sales General Manager
(China & Taiwan)



SEOW ZI YANG
Business Development
Manager



FAHMI HELMI
Business Development
Manager