



22-Jul-26

JOB NO. S67824

CLAIM No. NRP267404872

IAG

LOCKED BAG 5050

PARRAMATTA NSW 2124

MR C JACKSON - 9 PASADENA ST, MONTEREY NSW 2217

Claim Received

Incident Type: DAMAGE

Estimator: Mick Short

Type of Make Safe: N/A

Contact: 0400 625 627

Specialist Report Type: N/A



S67824-JACKSON\FRONT\House

Property Details:

Detached Garage: NO

Sheds: NO

Swimming Pool: NO

Detached Granny Flat/Other building: NO

Client Discussion:

Estimator Mick met Mrs Jackson who explained how her husband tripped on a rug and put his head through the wall. This has created a hole in plaster wall.

Resultant Damage:

Office - hole in plaster wall.

Has the resultant damage to the property has been caused by a listed event? YES

Cause of Damage:

Accidental damage.

Maintenance Related Issues:

Not applicable.

Recommendation:

Accept

Repair Estimate (inc GST): \$2,522.44

Variances to Scope:

Comments:

Accept.

This report has been produced to facilitate claim resolution, is unbiased and objective, and is based on the information available at the time of writing.

Is Temporary Accommodation required immediately? NO

Estimate timeframe for immediate temporary accommodation: 0 Days

What temporary repairs are required to make the home liveable: N/A

Is Temporary Accommodation required DURING REPAIRS ONLY? NO

Estimate timeframe for temporary accommodation required during repairs: 0 Days

Works to be completed when insured is in temporary accommodation: N/A


Photos:



S67824-JACKSON\Desk & contents need moving



S67824-JACKSON\Hole in wall



S67824-JACKSON\Hole in wall2



S67824-JACKSON\Hole in wall3



S67824-JACKSON\Wall needs painting not ceiling

For and on behalf of

ENSURE CONSTRUCTIONS AND RESTORATION PTY LTD