

Traffic Accident Report


General Vehicle Information						
Make:	FORD	Body Type:	SUV	Fuel:	Petrol	
Model:	Explorer	Cylinders:	6	Transaxle:	4WD	
Reg. year:	2017	Seating Cap.:	7	Steering Pos.:	Left hand	
Model #:	FEX17	Odometer:	50452 km	Transmission:	Automatic	
Engine Number:	FEX17-5678	Rating CC:	1987cc	Colour:	White	
Reg. No.:	ТВА	Import Type:	United States of America	Body Grade:	2.01	

Brief Report of the Accident

On Saturday, April 29, 2021 the Ford (Car1) motor car was traveling along Mandela Highway in an easterly direction heading towards Spanish Town Road.

Whilst driving along the road way a horse run in the middle of the road causing the driver to swerve the car to avoid hitting the animal. Subsequently, the car hit the horse causing damages to the front and killing the animal.

Road Diagram



Record of Damages

Bonnet:	Minor damages (repairable)	Left Headlight:	No Damage
Right Fender:	Major Damages (Needs replacement)	Radiator:	Minor Damages
Left Fender:	No Damage	Engine Bay:	No Damage
Front Bumper:	Major Damages (Needs replacement)	Right Fog lights:	Major Damages (Needs replacement)
Crash Bar:	Minor damages (repairable)	Air bags:	Driver side -Deployed
Grill:	Minor damages (repairable)	Left and Right Rear door:	No Damage
Right Headlight:	Major Damages (Needs replacement)	Left and Right Front Door:	No Damage

Pictures of Damages











