

Supersonic Business Jet – Structures – Before and After



Before: Unrealistic deflections observed under spanwise-varying elliptic loading.



After: Major corrections made to algorithms show expected deflection under elliptic load.