
Vehicle Condition Report

The vehicle has major damage to the front and left side. The roof, windshield, hood, grill, front bumper, left fender, left front door, and left rear quarter panel are all damaged. The front right light is also damaged. The rear of the vehicle seems to be OK.

Front side



Roof Condition: Seems OK

Windshield Condition: Minor damage

Hood Condition: Major damage

Grill Condition: Major damage

Front Bumper Condition: Major damage


Right Mirror Condition: Not visible

Left Mirror Condition: Not visible


Front Right Light Condition: Major damage

Front Left Light Condition: Seems OK

Back side



Right side



Left side

