QA Bug Report for frugallogistics.in

Application: Frugal Logistics Pvt Ltd Website
Tested Page: Contact / Request Quote Form
Environment:
Browser: Google Chrome,microsoft edge
OS: Windows
Device: Desktop
URL: https://frugallogistics.in/contact

QA Testing Scope

The purpose of this testing activity was to evaluate the functional behavior, usability, technical structure, and performance of the Frugal Logistics website.

The following testing activities were performed during this QA evaluation:

• Functional testing of key user flows (Contact form and Request Quote form)

• Input validation testing for form fields

• Cross-device behavior testing (Desktop and Mobile view)

• HTML structure validation using W3C Nu HTML Validator

• Accessibility evaluation using WAVE Web Accessibility Tool

• Performance analysis using Chrome DevTools Lighthouse

• Network request inspection using Chrome Developer Tools

• Security header verification using HTTP Security Header Analyzer

• SEO technical inspection including sitemap.xml, robots.txt, and structured data

The goal of this testing process was to identify functional defects, usability issues,performance optimization opportunities, and technical improvements that may impact user experience or website reliability.

Testing Environment

Browser:

• Google Chrome

• Microsoft Edge

Operating System:

• Windows

Device:

• Desktop

• Mobile View (Chrome DevTools Device Emulator)

Testing Tools Used:

• Chrome Developer Tools (Console, Network, Performance)

• Lighthouse Performance Audit

• W3C Nu HTML Validator

• WAVE Web Accessibility Evaluation Tool

• SecurityHeaders.com Scanner

• Dead Link Checker

• PageSpeed Insights

Tested URLs:

• https://frugallogistics.in

• https://frugallogistics.in/contact

• https://frugallogistics.in/sitemap.xml

• https://frugallogistics.in/robots.txt

Executive Test Summary

A QA evaluation of the Frugal Logistics website was conducted to assess functional stability, usability, performance, accessibility, and technical implementation.

The testing process identified several functional issues primarily related to form validation and user interaction behavior. Additionally, a number of technical observations were identified relating to HTML structure, performance optimization opportunities, and accessibility improvements.

Overall Findings:

Total Bugs Identified: 7

• Medium Severity: 5

• Low Severity: 2

Technical Observations:

• Performance optimization opportunities identified

• Minor accessibility improvements required

• HTML semantic structure improvements recommended

Security Status:

A security header analysis confirmed that the website is properly configured with important security headers and received an A+ security rating.

Performance Overview:

The Lighthouse performance audit indicates that the website performs well overall, with opportunities for optimization related to image delivery, render-blocking resources, and unused JavaScript.

Accessibility Overview:

Minor accessibility issues were detected, including missing language attributes and incomplete heading hierarchy.

Overall Website Stability:

The website loads successfully and all network requests return successful responses. However, several user interaction issues were identified that may impact user experience and lead generation.

Bug 1 — Invalid Email Format Accepted by Contact Form

Severity: Medium
Priority: Medium
Type: Input Validation

Description

The contact form accepts invalid email formats and displays a successful submission message.

Steps to Reproduce

1. Open the Contact page.
2. Enter the following values:

Name: `xtr`
Email: `abc@gmail`
Phone Number: any value
Destination: `LONDON`
Drop Location: `CAPETOWN`

3. Click **Submit Now**.

Expected Result

The system should validate the email format and prompt the user to enter a valid email address (example: `user@example.com`).

Actual Result

The form is submitted successfully and displays **"Message sent successfully!"** even though the email format is invalid.

Impact

Incorrect contact information may be stored, preventing the company from contacting the user.

**** suitable screenshot for bug 1, bugs 2and bug 3 is shared below the details of bugs 2.**

Bug 2 — Phone Number Field Accepts Alphabetic Characters

Severity: Medium
Priority: Medium
Type: Input Validation

Description

The phone number field allows alphabetic characters and special characters instead of restricting input to numeric values.

Steps to Reproduce

1. Open the Contact page.
2. Enter the following in the phone number field:

dhrrrruvgr4fffWFF

3. Fill other required fields.
4. Submit the form.

Expected Result

The phone number field should accept only numeric characters or valid phone formats.

Actual Result

The system accepts alphabetic characters in the phone number field and allows form submission.

Impact

Invalid phone numbers may be stored in the database, leading to incorrect customer contact information.



Bug 3 — Success Message Persists Even When Form Becomes Invalid

Severity: Low
Priority: Low
Type: UI Feedback / State Issue

Description

After successful form submission, the message **“Message sent successfully!”** remains visible even when the user edits the form and enters invalid data.

Steps to Reproduce

1. Submit the form successfully.
2. Modify the email field to an invalid value such as:

abc

3. Observe the page.

Expected Result

The success message should disappear once the user modifies the form.

Actual Result

The success message remains visible even though the form now contains invalid input.

Impact

Users may believe the message was successfully sent while the form state is invalid.

Bug 4 — Multiple Clicks on "Submit Now" Redirect User to Home Page

Severity: Medium
Priority: Medium
Type: Form Handling / UX Issue

Description

The **"Submit Now"** button in the **Request a Free Quote** form allows multiple clicks without disabling the button or showing a loading indicator. When the submit button is clicked repeatedly, the website unexpectedly reloads and redirects the user to the homepage.

This behavior can confuse users and may result in duplicate submissions or loss of form data.

Steps to Reproduce

1. Open the Frugal Logistics website.

https://frugallogistics.in

2. Navigate to the **Request a Free Quote** form.
3. Enter valid data in the form fields.
4. Click the **"Submit Now"** button multiple times rapidly.
5. Observe the page behavior.

Expected Result

When the **Submit Now** button is clicked:

- The button should become **disabled** after the first click, or

- A **loading indicator** should appear while the form is processing, and
- The user should remain on the form page with a **success confirmation message** or proper submission response.

Actual Result

Clicking the **Submit Now** button multiple times causes the website to reload and redirect to the **homepage**, without showing any confirmation or submission feedback.

Impact

Users may experience confusion regarding whether the form submission was successful. Multiple clicks could also lead to duplicate submissions or loss of entered data.





Bug 5 — Console Warning for Unused CSS Preload

Severity: Low
Priority: Low
Type: Performance Warning

Description

Browser console displays warnings indicating that a CSS file was preloaded but not used within a short time after page load.

Console Log

The resource was preloaded using link preload but not used within a few seconds from the window's load event.

Expected Result

Preloaded resources should be used immediately or not preloaded.

Actual Result

Browser logs warnings regarding unused CSS preload resources.

Impact

May slightly impact page performance and resource loading efficiency.

Attachments



- Screenshot showing invalid email submission
- Screenshot showing console warnings.

Bug 6 — Phone Number Field Validation Inconsistent Between Desktop and Mobile

Severity: Medium
Priority: Medium
Type: Input Validation / Cross-Platform Consistency

Product
Frugal Logistics Pvt Ltd Website – Contact / Request Quote Form

Environment
Browser: Google Chrome
OS: Windows
Device: Desktop & Mobile View (Chrome DevTools Device Emulator)
URL: https://frugallogistics.in/contact

Description

The Phone Number field shows inconsistent validation behavior between the desktop and mobile versions of the website.

In the desktop version, the field allows alphabetic characters to be entered. In the mobile version, the field restricts input and appears to allow only numeric characters.

Steps to Reproduce

1. Open the Contact or Request Quote form on the desktop version of the website.
2. In the **Phone Number** field enter alphabetic characters such as:

abcde

3. Observe that the characters are accepted in the field.
4. Open the same page in **mobile view** (using Chrome DevTools device mode or a mobile device).
5. Try entering alphabetic characters in the **Phone Number** field.

Expected Result

The Phone Number field should enforce **consistent validation rules across all devices**, allowing only numeric input or valid phone number formats.

Actual Result

- Desktop version allows alphabetic characters in the phone number field.
- Mobile version restricts input to numeric characters.

Impact

Inconsistent validation across platforms may allow invalid phone numbers to be submitted by desktop users, resulting in inaccurate customer contact data.

Attachment

Screenshot showing mobile view of the form with Phone Number field behavior.



Bug 7 — "Request Quote" Button on Home Page Does Not Open Quote Form

Severity: Medium
Priority: Medium
Type: Functional / Navigation Issue

Description

The **"Request Quote"** button displayed on the homepage does not trigger any action when clicked. The button appears interactive but does not redirect the user to a quote form, contact form, or any relevant page.

This creates confusion for users attempting to request logistics services through the website.

Steps to Reproduce

1. Open the website homepage:

https://frugallogistics.in

2. Scroll to the section **"What Makes Us Special"**.
3. Click the **"REQUEST QUOTE"** button displayed below the section.
4. Observe the page behavior.

Expected Result

Clicking the **"Request Quote"** button should:

- Redirect the user to a **quote request form**, or
- Open a **contact/quotation form modal**, or
- Navigate to the **Contact / Request Quote page**.

Actual Result

Clicking the **"Request Quote"** button does not trigger any navigation or form display. The button appears clickable but performs no visible action.

Impact

Users attempting to request a quote may be unable to proceed, potentially leading to **lost customer inquiries and reduced conversion opportunities**.



Network Health Observation — No Failed Requests Detected

Severity: Informational
Priority: Low
Type: Network / Resource Loading

Product
Frugal Logistics Pvt Ltd Website

Environment
Browser: Google Chrome
OS: Windows
Device: Desktop
Tool Used: Chrome DevTools (Network Tab)

Description

Network inspection was performed using Chrome Developer Tools to monitor all resource requests made by the webpage during page load.

All network requests were observed to return successful responses, indicating that the webpage resources are loading correctly without failures.

Steps to Reproduce

1. Open the website in Google Chrome.
2. Press **F12** to open Developer Tools.
3. Navigate to the **Network** tab.
4. Refresh the webpage to capture all network requests.
5. Observe the **Status** column for response codes.

Expected Result

All critical resources such as HTML, CSS, JavaScript, images, and API calls should return successful HTTP response codes (typically **200**).

Actual Result

- All major resources returned **HTTP 200 (OK)** status.
- Analytics requests returned **HTTP 204 (No Content)** which is expected behavior.
- No **404 (Not Found)** or **500 (Server Error)** responses were observed.
- No failed API calls or missing resources detected.

Performance Summary

Total Network Requests: 124

Data Transferred: 71.7 KB

Total Resource Size: 5.4 MB

DOMContentLoaded Time: 723 ms

Page Load Time: 1.36 s

Total Network Activity Finish Time: ~1.3 minutes

Impact

No functional network issues were identified. The webpage loads all resources successfully without request failures.

Attachment

Screenshot of Network tab showing resource requests and response status codes.



Performance Optimization Observations (Lighthouse Desktop Audit)

Tool Used: Chrome DevTools Lighthouse
Device Mode: Desktop
Browser: Google Chrome

---

1. Render Blocking Resources Detected

Description
Lighthouse identified render-blocking resources that delay the initial page rendering.

Estimated Improvement
~80 ms faster rendering.

Impact
Render-blocking scripts or stylesheets can delay the first visual paint of the page.

Recommendation
Use techniques such as:

- `defer` or `async` attributes for JavaScript

- critical CSS loading
- lazy loading for non-critical assets

---

2. Image Delivery Optimization Opportunity

Description
Some images could be optimized for better delivery.

Estimated Savings

372 KiB

Impact
Large image sizes increase page load time, especially on slower connections.

Recommendation

- Compress images
- Use modern formats like **WebP or AVIF**
- Serve appropriately sized images for different devices

---

3. Network Dependency Tree Complexity

Description
Multiple resource dependencies were detected which may affect loading efficiency.

Impact
Long dependency chains can delay resource loading and increase render time.

Recommendation

- Reduce chained resource dependencies
- Load critical assets earlier

---

4. Inefficient Cache Lifetimes

Description
Some resources have short cache lifetimes.

Estimated Savings

5 KiB

Impact
Short cache durations cause browsers to re-download resources more often.

Recommendation

- Increase cache lifetime for static resources (CSS, JS, fonts)

---

5. Legacy JavaScript Detected

Description
The site includes JavaScript meant for older browsers.

Estimated Savings

14 KiB

Impact
Modern browsers do not require legacy code, which can increase bundle size.

Recommendation

Use modern JavaScript bundles optimized for modern browsers.

Diagnostics Observations

6. Unused JavaScript

Estimated Savings

110 KiB

Observation
Some JavaScript resources are loaded but not fully used during page rendering.

---

7. Main Thread Work Optimization

Observation

Main thread execution time recorded:

2.4 seconds

Heavy JavaScript processing can impact UI responsiveness.

---

8. Long Main Thread Tasks

Observation

6 long tasks detected

Long tasks block the browser from responding to user interactions.

QA Conclusion

The Lighthouse audit indicates that the website performs well overall but presents several opportunities for performance optimization, particularly in:

- image delivery optimization
- unused JavaScript reduction
- render-blocking resource management

These findings represent **optimization opportunities rather than functional defects**.

Attachment

Lighthouse audit screenshot.



QA Observation — Schema (JSON-LD)

Title
JSON-LD Structured Data Script Present but Empty

Description
During inspection of the page source using Chrome DevTools (Elements tab), a script tag with type `application/ld+json` was detected. However, the script block does not contain any structured data.

Example observed:

<script type="application/ld+json"></script>

No schema properties such as:

- `@context`
- `@type`
- `name`
- `url`
- `logo`

were found within the JSON-LD script.

Impact

Search engines rely on structured data to understand website entities such as:

- organization information
- services
- business details
- location data

Since the script is empty, search engines cannot extract structured metadata from the page.

Severity
Low (SEO Optimization Issue)

Recommendation

Implement valid JSON-LD structured data in the code.

This will improve search engine understanding and potential rich search results.

```
  <link rel="icon" href="/FrugalLogistics.ico">
  <link rel="apple-touch-icon" href="/FrugalLogistics.ico">
  <script type="application/ld+json">…</script>
  <script src="/_next/static/chunks/a6dad97d9634a72d.js" nomodule></script>
  <script src="/_next/static/chunks/6c4210d3d3193ab0.js"></script>
  <script src="/_next/static/chunks/243a18eeabdd37de.js"></script>
  <link rel="preload" href="/HomePageImges/herosection2.jpg" as="image">
</head>
```

HTML Validation (W3C)

Tool Used: W3C Nu HTML Validator
URL Tested: https://frugallogistics.in
Validation Method: Validate by URL

Bug 1 — Duplicate Meta Description

Two `<meta name="description">` tags appear in the document head.

What the validator says:

> A document must not include more than one meta element with its name attribute set to the value "description".

Search engines expect exactly one description tag to summarize the page. When there are two, crawlers may ignore them or choose arbitrarily, which weakens SEO control.

Write it in the report like this:

Title: Duplicate Meta Description Tag
Severity: Medium (SEO Issue)

Description:
HTML validation identified multiple `<meta name="description">` elements within the document head. According to HTML standards, only one description meta tag should be present per page.

Impact:
Search engines may ignore duplicate meta descriptions or select one unpredictably, affecting how the page appears in search results.

Recommendation:
Ensure only one `<meta name="description">` tag exists in the document head.

Bug 2 — Invalid Heading Hierarchy (h1 → h4)

The page jumps directly from `h1` to `h4`.

Validator message:

> The heading h4 follows the heading h1, skipping 2 heading levels.

Headings are supposed to form a logical outline like chapters in a book. Skipping levels breaks accessibility tools and weakens SEO structure.

Report entry:

Title: Incorrect Heading Hierarchy (h1 followed by h4)
Severity: Medium (Accessibility / SEO)

Description:
HTML validation detected a heading structure where an `h4` element appears immediately after an `h1`, skipping heading levels `h2` and `h3`.

Impact:
Improper heading structure can affect accessibility for screen readers and reduce semantic clarity for search engines.

Recommendation:
Maintain sequential heading order (h1 → h2 → h3 → h4).

Bug 3 — Invalid Heading Hierarchy (h2 → h4)

Validator message:

> The heading h4 follows the heading h2, skipping 1 heading level.

Report entry:

Title: Heading Level Skipped (h2 followed by h4)
Severity: Medium

Description:
HTML validation identified instances where h4 elements follow h2 headings without an intermediate h3.

Impact:
This breaks semantic structure and affects accessibility tools that rely on heading hierarchy.

Recommendation:
Ensure heading levels progress sequentially.

Bug 4 — Another h2 → h4 Skip

Same issue appears again in another section of the page.

You can document it as:

Title: Repeated Heading Hierarchy Violation
Severity: Medium

Description:
Additional instances of skipped heading levels were detected where h4 elements appear after h2.

Recommendation:
Review the heading structure across the page to maintain a proper semantic hierarchy.

Test Summary

The HTML validation process revealed structural markup issues including:

- duplicate meta description tag
- improper heading hierarchy (h1 → h4)
- multiple skipped heading levels (h2 → h4)

These issues do not break functionality but impact **SEO indexing, accessibility compliance, and HTML standards adherence**.

1. **Error** **A document must not include more than one `meta` element with its `name` attribute set to the value `description`.**
   From line 1, column 3748; to line 1, column 3987
   `ns</title><meta name="description" content="Frugal Logistics Pvt Ltd provides cost-effective and before-time d…Truck Load, Air Cargo services backed by our own IT infrastructure and real-time tracking system."/><meta`
2. **Error** **The heading `h4` (with computed level 4) follows the heading `h1` (with computed level 1), skipping 2 heading levels.**
   From line 1, column 13709; to line 1, column 13739
   `ter"><div><h4 class="font-semibold mb-2">OPENIN`
3. **Error** **The heading `h4` (with computed level 4) follows the heading `h2` (with computed level 2), skipping 1 heading level.**
   From line 1, column 19504; to line 1, column 19544
   `/div><div><h4 class="font-semibold text-[#2f3c88]">Single`
4. **Error** **The heading `h4` (with computed level 4) follows the heading `h2` (with computed level 2), skipping 1 heading level.**
   From line 1, column 45339; to line 1, column 45381
   `ocess.</p><h4 class="text-red-500 font-bold text-sm">— <!--`

Observation — Sitemap.xml

URL Tested:
https://frugallogistics.in/sitemap.xml

Observation

The sitemap file is accessible and correctly structured in XML format using the standard sitemap protocol:

xmlns="http://www.sitemaps.org/schemas/sitemap/0.9"

The sitemap includes multiple key website URLs such as:

- homepage
- about-us page
- services page
- contact page
- FAQs page
- privacy policy page

Each entry includes metadata fields including:

- `lastmod`
- `changefreq`
- `priority`

Impact

A properly configured sitemap helps search engines efficiently crawl and index website pages.

Result

Sitemap is present and correctly structured.

Severity

(No Issue Found)

This XML file does not appear to have any style information associated with it. The document tree is shown below.


```
▼<urlset xmlns="http://www.sitemaps.org/schemas/sitemap/0.9">
  ▼<url>
     <loc>https://frugallogistics.in</loc>
     <lastmod>2026-02-26T07:54:39.472Z</lastmod>
     <changefreq>daily</changefreq>
     <priority>1</priority>
   </url>
  ▼<url>
     <loc>https://frugallogistics.in/about-us</loc>
     <lastmod>2026-02-26T07:54:39.472Z</lastmod>
     <changefreq>monthly</changefreq>
     <priority>0.8</priority>
   </url>
  ▼<url>
     <loc>https://frugallogistics.in/services</loc>
     <lastmod>2026-02-26T07:54:39.472Z</lastmod>
     <changefreq>weekly</changefreq>
     <priority>0.9</priority>
   </url>
  ▼<url>
     <loc>https://frugallogistics.in/contact</loc>
     <lastmod>2026-02-26T07:54:39.472Z</lastmod>
     <changefreq>monthly</changefreq>
     <priority>0.7</priority>
   </url>
  ▼<url>
     <loc>https://frugallogistics.in/faqs</loc>
     <lastmod>2026-02-26T07:54:39.472Z</lastmod>
     <changefreq>monthly</changefreq>
     <priority>0.6</priority>
   </url>
  ▼<url>
     <loc>https://frugallogistics.in/privacy-policy</loc>
     <lastmod>2026-02-26T07:54:39.472Z</lastmod>
     <changefreq>yearly</changefreq>
     <priority>0.5</priority>
   </url>
  ▼<url>
     <loc>https://frugallogistics.in/delivery-disclaimer</loc>
     <lastmod>2026-02-26T07:54:39.472Z</lastmod>
     <changefreq>yearly</changefreq>
     <priority>0.5</priority>
   </url>
  ▼<url>
     <loc>https://frugallogistics.in/track</loc>
     <lastmod>2026-02-26T07:54:39.472Z</lastmod>
```

QA Observation — Robots.txt

URL Tested
https://frugallogistics.in/robots.txt

Observation

The robots.txt file is accessible and properly configured. The file allows standard search engine crawlers to access the entire website while restricting certain AI-related crawlers.

Key rules observed:

- General access allowed for search engines
- AI training crawlers (e.g., GPTBot, ClaudeBot, Amazonbot) are disallowed
- Sitemap location is declared

Impact

The configuration allows normal search engine indexing while preventing AI model training crawlers from scraping the site content.

Result

Robots.txt is present and correctly configured.

Severity

(no issue found)

```
# BEGIN Cloudflare Managed content

User-agent: *
Content-Signal: search=yes,ai-train=no
Allow: /

User-agent: Amazonbot
Disallow: /

User-agent: Applebot-Extended
Disallow: /

User-agent: Bytespider
Disallow: /

User-agent: CCBot
Disallow: /

User-agent: ClaudeBot
Disallow: /

User-agent: Google-Extended
Disallow: /

User-agent: GPTBot
Disallow: /

User-agent: meta-externalagent
Disallow: /

# END Cloudflare Managed Content

# Robots.txt for Frugal Logistics Pvt Ltd
# https://frugallogistics.in

User-agent: *
Allow: /

# Sitemaps
Sitemap: https://frugallogistics.in/sitemap.xml

# Disallow admin or private areas (if any in future)
# Disallow: /admin/
# Disallow: /api/

# Crawl-delay (optional, adjust if needed)
Crawl-delay: 1
```

Security Headers Analysis — HTTP Security Configuration

Severity: Informational
Priority: Low
Type: Security Configuration

Description

A security header scan was performed on the Frugal Logistics website using a standard HTTP security header analyzer. The website received an **A+ security rating**, indicating that the server is correctly configured with important security headers that help protect against common web vulnerabilities.

The scan confirms that the site is protected against attacks such as **clickjacking, MIME sniffing, insecure transport, and unauthorized resource loading**.

Steps to Reproduce

1. Open the security header scanning tool.

2. Enter the website URL:

https://frugallogistics.in

3. Run the security scan.

4. Observe the generated security report and configured HTTP security headers.

Observed Security Headers

The following security headers are properly implemented:

- **Strict-Transport-Security (HSTS)** – Forces HTTPS connections to prevent downgrade attacks.
- **Content-Security-Policy (CSP)** – Restricts loading of unauthorized scripts and resources.
- **X-Content-Type-Options** – Prevents MIME-type sniffing attacks.
- **X-Frame-Options** – Protects against clickjacking by restricting iframe embedding.
- **Referrer-Policy** – Controls how much referrer information is shared.
- **Permissions-Policy** – Restricts access to browser features such as geolocation.

Expected Result

The website should include proper HTTP security headers to protect users and enforce secure browser behavior.

Actual Result

All critical security headers are correctly configured.
The website received an **A+ security rating**, indicating strong security header implementation.

Impact

Properly configured security headers help protect the website against common client-side attacks and improve the overall security posture of the application.



Accessibility Issue — Missing Language Attribute and Improper Heading Structure

Severity: Low
Priority: Low
Type: Accessibility / Semantic HTML

Description

An accessibility evaluation of the Frugal Logistics website was performed using the **WAVE Web Accessibility Evaluation Tool**. The scan identified minor accessibility issues related to the language declaration and heading structure of the webpage.

Accessibility attributes help assistive technologies such as screen readers correctly interpret webpage content. Proper semantic HTML structure also improves SEO and usability.

The following issues were detected:

• Language attribute missing or invalid
• Missing first-level heading (H1)
• No defined page regions detected

Steps to Reproduce

1. Open the WAVE accessibility evaluation tool.

2. Enter the following website URL:

https://frugallogistics.in

3. Run the accessibility scan.

4. Review the accessibility report generated by the tool.

Expected Result

The webpage should include:

• A valid **language attribute** in the `<html>` tag (e.g., `lang="en"`).
• A properly defined **H1 heading** representing the main page title.
• Defined **page regions** such as `<header>`, `<main>`, `<nav>`, and `<footer>` to improve navigation for assistive technologies.

Actual Result

The accessibility scan reported the following issues:

• Language missing or invalid
• Missing first-level heading (H1)
• No page regions detected

Impact

These accessibility issues may affect users relying on assistive technologies such as screen readers. Proper semantic structure improves accessibility compliance, usability, and search engine interpretation of webpage content.



Few Recommendations-

Based on the testing results, the following improvements are recommended to enhance the reliability, usability, and performance of the Frugal Logistics website.

1. Improve Form Input Validation

Implement stricter validation for email and phone number fields to ensure only valid input formats are accepted. Both client-side and server-side validation should be enforced.

2. Prevent Multiple Form Submissions

The "Submit Now" button should be disabled after the first click or display a loading indicator while the request is processing to prevent duplicate submissions.

3. Fix Non-Responsive Call-to-Action Button

The "Request Quote" button on the homepage should correctly redirect users to the quote form or contact page to ensure users can submit inquiries.

4. Improve HTML Semantic Structure

The website should follow proper heading hierarchy (H1 → H2 → H3 → H4) and avoid duplicate meta description tags to improve accessibility and SEO.

5. Implement Structured Data

Valid JSON-LD structured data should be added to the website to help search engines understand business information and improve search visibility.

6. Optimize Website Performance

Performance can be improved by optimizing image delivery, reducing unused JavaScript, and minimizing render-blocking resources.

7. Enhance Accessibility Compliance

Add proper language attributes and semantic page regions such as <header>, <nav>, <main>, and <footer> to improve compatibility with assistive technologies.