QUALITY CONTROL & INSPECTION CERTIFICATE

GLASS BOTTLE ANOMALY DETECTION & QUALITY TRIAGE SYSTEM

REPORT ID: QC-64601
DATE: 2026-10-04 12:51:05

INSPECTION VERDICT: UNVALIDATED EXTERNAL INPUT — Unvalidated Input — Outside Domain

Visual Inspection & Polar Discontinuity Analysis



(a) Input Top-View | (b) Spatial Anomaly Map | (c) Polar Unwrapped Strip

Quantitative Metric Triage & Industrial Action

■■ DOMAIN WARNING: Automatic defect classification is not considered reliable for this input because the image is outside the validated inspection distribution. Human expert review is required.

Sample Filename	google_bottle_test.png
Input Compatibility Status	**OUTSIDE_DOMAIN** (0.0%) — *UNRELIABLE*
Human Review Required	**YES — Engineering Validation Required**
Operating QA Standard	**Commercial Beverage (Balanced)** (Threshold: 0.4263)
Anomaly Matching Score	0.9824
Defective Surface Area Ratio (DSAR)	**99.48%**
Anatomical Defect Zone	**Mouth / Rim Annulus**
Classified Defect Subtype	Unvalidated External Input (OOD)
Grading Classification	**Unvalidated Input — Outside Domain**
Overall Quality Score	**0.0 / 100**
Manufacturing Risk Profile	**100.0 / 100 (Unvalidated (OOD) Risk)**
Anomaly Pattern Cluster	Cluster 01 — Sealing Rim Discontinuity
Diagnostic Discovery Status	**UNKNOWN ANOMALY — REVIEW REQUIRED**

Grading Rationale	Input image is outside the validated top-down bottle inspection distribution. Automatic defect decision is not reliable. Human expert review is required.
Industrial Triage Action	**HOLD CONTAINER — Engineering Verification Required (Outside Validated Inspection Domain)**

Automated Vision Inspection Unit
PatchCore Deep Feature Engine v2.0

QA Supervisor Digital Signature
[Verified & Certified Automatic]