QUALITY CONTROL & INSPECTION CERTIFICATE

GLASS BOTTLE ANOMALY DETECTION & QUALITY TRIAGE SYSTEM

REPORT ID: QC-13217
DATE: 2026-10-04 10:57:06

INSPECTION VERDICT: **DEFECTIVE — Grade C — Critical Damage**

Visual Inspection & Polar Discontinuity Analysis



(a) Input Top-View | (b) Spatial Anomaly Map | (c) Polar Unwrapped Strip

Quantitative Metric Triage & Industrial Action

Sample Filename	test_sample.png
Operating QA Standard	**Commercial Beverage (Balanced)** (Threshold: 0.4263)
Anomaly Matching Score	0.8100
Defective Surface Area Ratio (DSAR)	**12.50%**
Anatomical Defect Zone	**Sealing Rim Annulus**
Classified Defect Subtype	Broken Large
Grading Classification	**Grade C — Critical Damage**
Overall Quality Score	**5.0 / 100**
Manufacturing Risk Profile	**95.0 / 100 (Critical Risk)**
Anomaly Pattern Cluster	Cluster 01 — Sealing Rim Discontinuity
Diagnostic Discovery Status	Confirmed Known Defect Pattern
Grading Rationale	Rim fracture
Industrial Triage Action	**Immediate Scrap**