

Bazaar / the street is the design

PRIMARY ARTISTIC AUTHORITY / bazaar_main_hall_reference.png



Layered architecture, occupied upper rooms, supported cloth and a clear walking path.

Revision 3 turns the independent review into dimensioned spatial proposals. Warm daylight and readable shade remain the direction.


Review S1/S2 roof composition, E1 Tea counterplay and conditional G1 first. Then review B18 as the complete-building pilot.

35 building/wall records /25 public spaces /9 additional groups. The founding image outranks the eight retained generated studies. No production models, map-spec changes, runtime edits or gameplay implementation in this revision.

Spatial sequence / one elevation trial / one conditional return

Read with S1/S2/E1/G1 in buildings.md. Footprints are observed; proposals are not live geometry.


01 / NORTH-UP ROUTE COMPOSITION



22 → 12 → 16 → 11 → 13 → 22 m

Main sequence: court / street / court / cloth arcade / gate / receiving court. Footprint widths, not clearances.

02 / E1 TEA PLAN: VIEW WITHOUT A NEW FLOOR




Slot y58..61

3.00 m long
Cap +2.50
1.10 above Tea

Shade y62.4 retained

Both end approaches remain.
No new stairs, bridge, one-way drop or player-only guard.

03 / G1 CONDITIONAL




x24..28 / y48..49

Height2.40 / opening7.00

Partial west-ray break. East rays remain open. Test only if baseline shows long retreat firing or poor reload escape.

04 / E1 CROSS SECTION AT y59.5 / ABSOLUTE z




Standing ray clears the cap; crouched ray intersects it in this idealized section. Actual weapon rays and nearby objects need M05/M06. Check jumping and both approaches.

Street depth from both directions

S1 / S2 / M: massing and silhouette proposals; floor footprints retained


SPICE / 12 m street



West caps8.79 /9.59 /8.19 across three parcels. East low cap5.59, northern setback room cap7.71. Existing narrow source heads west10.668 /east7.518 are replaced, not hidden behind extra copies.

Northbound Spice: close west trade awnings; middle east setback room; release to the off-axis fountain/civic stone. Southbound: north low west parcel frames layered cloth; tall middle room overlaps the retained Spawn-A corner kits and gate.

TEXTILE / 11 m street



West south cap8.19, northern Tea/shared wing cap9.59. East remains low5.59. Keep three arches plus the irregular intervening column. Shared Tea overlap requires M01 before roof export.

Northbound Textile: arches and conditional G1 foreground; shared Tea wing and cloth in the middle; Rug Gate at distance. Southbound: near rug canopy, lower southern west parcel, then Fountain release. Do not fill sky gaps with a continuous cloth ceiling.

M07: verify exact player-eye views near Spice(27,16)/(27,30), Textile(29.5,50)/(29.5,62), eye1.70, facing along each route. These are proposed measurement poses, not captured images. Test silhouette, shade and threat recognition in motion.

Tea / a view that exposes the player

E1-only comparison against baseline / no new floor or bridge



Current: terrace1.40, standing eye3.10, western wall7.00 plus roof. Tea house roof starts8.40 and its source head reaches12.068. The current raised route is strongly enclosed.

Trial: open-top3.00 m slot y58..61; retain masonry below2.50 and all tall flanks. Remove every coincident blocker in x10..11 above that cap. No retained invisible high screen.

Upper player(11.7,59.5), ground bot(6,59.5). Standing eye ray clears2.50; crouched Tea eye2.70 intersects the cap across its thickness. Weapon rays, bot behavior and nearby objects remain untested. Both end approaches stay usable.


Reject unreachable camping, asymmetric visual protection or a jump/drop exploit requiring a new traversal contract. Keep baseline if E1 fails. A second east platform and a new Textile/Dogleg connector are deferred, not production tasks.

Historical Tea capture: artifacts/map-shoot/unit-tea-terrace/stall-after. It predates the current spec hash; use as visual context only. Roof datums were independently rechecked against current source.

Complete assembly fit / central ownership / B18 pilot

Measured source bounds are labeled. Hidden access pockets are explanations, not modeled or playable interiors.

01 / CENTRAL BLOCK: TWO PUBLIC FACES




West x36..40.8 / east x36.2..41
Overlap4.60 / strips0.20 each

Souk massing owns common backing and roof in each wing. Court keeps its face modules. No bridge across the open link; no pair of full intersecting building exports. North access serves north wing only.

B18 full pilot includes packing01, original booth02, samples03, roof, end walls, supported awnings and ground contact. Three arches stay repaired.

02 / ACTUAL BOOTH ENVELOPE




Nominal arch2.60 x3.55

High width2.681056 / height3.639354
Depth -0.395..+0.896 from origin

Low bound below2.5: |X|≤0.93, front≤0.29 is a source assertion, not clearance approval. M02 samples arch spring, ledger, brace seats and all body sweeps. Original asset remains unchanged.

38,820 triangles /1 primitive /1 material

03 / B18 ROOF + WORKING SECTION



Room1.80 deep; top7.35

~0.84 roof access strip

Slab top4.76 / cap5.59

0.35 counter /0.80 working pocket

Pocket is a requested usable-depth test behind closed backing. If it cannot fit, use front-served locked display; no deeper shell or collider move.

Review response / composition and gameplay

Concrete dispositions; the independent design-review.md remains intact

Finding	Revision / rejection / test
P0-A Complete visible buildings	Adopt. All sheets now distinguish shell from actual roof profile. Context/access and critical sections are explicit for B04/B17, B12/B14-B16, B18, B21 and B24/B26. B18 has complete exterior/export ownership. Do not invent hidden rooms as production geometry. M01/M02 close mounting details.
P0-B Raised corridor	Confirmed: 192/3,148 m² of zone rectangles participate in Tea's rise, 80 m² flat at +1.4; not a quality score. E1 opens y=58..61 in the western screen to a parapet top +2.50. Ground bots gain a reciprocal angle; both end approaches remain. Reject stacked bridges for this batch: the resolver is a height field. Defer a second Dogleg platform until E1 demonstrates a useful decision.
P0-C Survival routes	Keep the existing graph; no authored dead-end zone does not prove good combat. G1 is a 4 x 1 x 2.4 m return at x=24..28, y=48..49, leaving a nominal 7 m passage. It breaks selected western rays, not the entire x=24..33 aligned strip. Test retreat/reload behavior before adding it. Defer the Textile-to-Dogleg connector: no demonstrated trap yet.
P1-D Cover	Keep eight cover anchors, two spawn covers and fountain in the baseline. Nominal tops 1.1-1.3 m do not certify crouch or bullet protection. M06 records collider and visible tops plus both eye rays and weapon rays, from reciprocal approach angles, for all 11 objects. No generic tall-crate rollout.
P1-E Skyline	Adopt S1/S2's broad parcel volumes and actual roof sections. Source evaluation puts Spice west's cap at +10.668, east +7.518, Tea +12.068, B18 +7.468; wall heights alone omitted these. Keep low eastern release except the selected Spice end room. No universal height increase.

Review response / support, ownership and fit

Concrete dispositions; the independent design-review.md remains intact

Finding	Revision / rejection / test
P1-F Unsupported shade	Confirmed height mismatch, not proof that every endpoint floats. Spice east ties 5.55-6.10 exceed its 4.5 m wall and 5.59 m parapet cap. Assets now assign backed roof brackets or lower ties per endpoint. M03 measures the real receiving material, lateral reach, sag and opening gaps; fixed endpoints are no longer absolute. No route poles.
P1-G Blank faces / implausible use	Replace blanket blank-face suppression with per-owner retain/remove choices. B14 becomes sealed retaining inspection panels, not 2.5 m-high under-terrace stores. B24/B26 are facade reliefs on implied off-map volumes. B21 retains human-scale openings and a 4.5 m wall with an explicit loft/roof-access composition. Keep sparse domestic evidence on visible returns and near-city shells; do not populate all backs.
P1-H Central block	Reject duplicate roofs as an established bug. Runtime already chooses the lexicographically first opposing massing for common backing/roof. Draw the two strips and y=39..44 link together; B17/Souk IDs own shared roof/backing for each wing. M01 verifies the visible 0.2 m outer strip relationship before any skin export. Preserve both IDs and repairs.
P1-I Asset fit / exports	Retain the bounded variants and the one fit-dependent extra booth candidate. Its actual GLB is 38,820 triangles, 2.681056 m measured width with a much narrower low cabinet; registry width 2.683 is rounded. M02 checks the full section, not a nominal 2.6 m arch. Complete building is the approval unit; named parts are export units. No distorted assets or repaired-arch suppression to force fit.
P2-J Warm light / scale	Founding image now opens the atlas. Historic neutral-daylight prompts remain verbatim as provenance, with an explicit superseding warm-light direction. M07 compares bot recognition in sun, shade and below cloth; material scale is reviewed at player distance. No claim that generated joinery is engine-ready.

Secondary references / 1-2

UNCHANGED GENERATED STUDIES / founding image retains primary authority



R01 / shop craft; S1 governs roofs

Adopt bounded construction and material strengths. Do not infer dimensions, support, collision, roof approval or warm-light settings from this generated image. Exact prompts and MD5 remain in references.md.



R02 / civic craft; retain off-axis fountain

Adopt bounded construction and material strengths. Do not infer dimensions, support, collision, roof approval or warm-light settings from this generated image. Exact prompts and MD5 remain in references.md.

Historic neutral-daylight and frozen-height prompts are preserved as provenance. Revision3 warm light, S1/S2 and named roof proposals supersede that design direction.

Secondary references / 3-4

UNCHANGED GENERATED STUDIES / founding image retains primary authority



R03 / trade distinction; S2 governs depth

Adopt bounded construction and material strengths. Do not infer dimensions, support, collision, roof approval or warm-light settings from this generated image. Exact prompts and MD5 remain in references.md.

R04 / preserve repaired portal

Adopt bounded construction and material strengths. Do not infer dimensions, support, collision, roof approval or warm-light settings from this generated image. Exact prompts and MD5 remain in references.md.

Historic neutral-daylight and frozen-height prompts are preserved as provenance. Revision3 warm light, S1/S2 and named roof proposals supersede that design direction.

Secondary references / 5-6

UNCHANGED GENERATED STUDIES / founding image retains primary authority



R05 / material craft; E1 tests enclosure

Adopt bounded construction and material strengths. Do not infer dimensions, support, collision, roof approval or warm-light settings from this generated image. Exact prompts and MD5 remain in references.md.

R06 / three trades; actual center booth unchanged

Adopt bounded construction and material strengths. Do not infer dimensions, support, collision, roof approval or warm-light settings from this generated image. Exact prompts and MD5 remain in references.md.

Historic neutral-daylight and frozen-height prompts are preserved as provenance. Revision3 warm light, S1/S2 and named roof proposals supersede that design direction.

Secondary references / 7-8

UNCHANGED GENERATED STUDIES / founding image retains primary authority



R07 / craft only; proportions rejected in B21

Adopt bounded construction and material strengths. Do not infer dimensions, support, collision, roof approval or warm-light settings from this generated image. Exact prompts and MD5 remain in references.md.

R08 / construction detail; not measured fit

Adopt bounded construction and material strengths. Do not infer dimensions, support, collision, roof approval or warm-light settings from this generated image. Exact prompts and MD5 remain in references.md.


Historic neutral-daylight and frozen-height prompts are preserved as provenance. Revision3 warm light, S1/S2 and named roof proposals supersede that design direction.

B01 / Spice Street west shop row

Three spice tenancies and two closed household/store access doors form one mixed-use block, with five aligned upper shutters.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 10.668



02 / CONTEXT PLAN + ROOF FOOTPRINTS


N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 10.668



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

S1 / M: THREE BROAD PARCELS

y15.44..21.56 /21.56..27.32 /27.32..30.56. Roof bases7.60 /8.40 /7.00; cap tops8.79 /9.59 /8.19. Replace narrow head, rear tier and bulkhead. Keep five upper closures and three trades. Household access stays closed. M03 ties; M07 both-direction views.


MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B02 / Spice Street east shop row


A low wholesale row has three closed entries and two blind panels, with one northern setback household/store room under S1.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE




z floor 0.00 / plotted max 7.710

02 / CONTEXT PLAN + ROOF FOOTPRINTS



03 / M03 EAST ROOF BRACKET AT y20.5808



Tie5.55. Upright x33.55;0.55 m outward reach to x33. Beam x33.45..36.75; knee bears at x34.5. All members outside the street body volume. Proposed0.14 m timber; actual bearing and fixing seats remain M03.

Wall4.50 / slab4.76 / bracket tie5.55. Partial-height section.

MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

S1 / M: NORTHERN SETBACK ROOM


Ground shell4.50 retained. Room x34.2..37.2,y24..30.56, roof7.00/cap7.71. Two closed windows y25.8/28.1,sill5.40/head6.65. South remains low. Roof-backed brackets support high eastern ties; M03 must establish real bearing.

B03 / Madrasa

One tall blind entrance arch and one stained clerestory face the fountain; a narrow south wing contains the closed service entrance.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 11.520



02 / CONTEXT PLAN + ROOF FOOTPRINTS


N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 11.520



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B04 + B17 / Merchant's house on the fountain

A merchant block has a quiet court loggia on its west front and a cloth-trade back on the Souk, with the existing cross-link between its wings.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 9.968



02 / CONTEXT PLAN + ROOF FOOTPRINTS


N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / OPPOSITE PUBLIC FACE / SAME WINGS

z floor 0.00 / plotted max 9.968



M01: TWO WINGS / ONE ROOF OWNER EACH

Shared shell union x36..41: overlap4.6 m, outer strips0.2 m.
Passage y39..44 stays open. Souk massing IDs own common roof/backing; court modules remain. North door serves north wing only; south is front-served locked stock. Retain repaired arches.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B05 / Rug arcade, west

Three rug-display arches and one pier form a shared commercial frontage; three upper screens belong only to the three arches.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 9.968



02 / CONTEXT PLAN + ROOF FOOTPRINTS


N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 9.968



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

S2 / M: SHARED TEA WING

South roof7.00/cap8.19. North y56.8..62.72 roof8.40/cap9.59 belongs to coupled B05/B12 volume. Existing overlap is not resolved by two independent exports. Keep three arches plus column; M01 shared backing/roof before production.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B06 / Rug arcade, east

A low arcade shares the west frontage rhythm but sells light fabric at its south bay and rugs farther north.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 7.468



02 / CONTEXT PLAN + ROOF FOOTPRINTS


N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 7.468



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

S2 / M: LOW EASTERN RELEASE

Keep4.50 roof base and5.59 parapet cap; remove narrow seeded head/rear tier only after silhouette approval. Southern booth remains M02/M03 fit-dependent. Complete retained packing north. No added upper windows or playable roof.

MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B07 / Rug merchant

One rug display and one closed north service door sit below two differently closed upper windows in the gate approach.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 8.870



02 / CONTEXT PLAN + ROOF FOOTPRINTS


N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 8.870



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B08 / Gatekeeper's house

One low gatekeeper dwelling has an offset closed entry and a small north window; its detached-looking south piece is a blank flank across the link.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 4.760



02 / CONTEXT PLAN + ROOF FOOTPRINTS


N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 4.760



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B09 / Caravanserai stores

Two equal locked stores alternate with three blind niches on a single storage-yard head.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 7.618



02 / CONTEXT PLAN + ROOF FOOTPRINTS


N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 7.618



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.


MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B10 / Caravan yard wall, south

A shallow garden enclosure south of West Mid Link holds one high blind niche.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE



03 / END PROFILE



z floor 0.00 / plotted max 7.918

REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.


No automatic blank-face deletion.

MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

02 / CONTEXT PLAN + ROOF FOOTPRINTS

z floor 0.00 / plotted max 7.918



Source shells / roofs; rust = design extent, not a live transform.


RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.

B11 / Caravan yard wall, north


The north enclosure continues the garden wall with a longer span and a warmer repaired plaster field.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE



z floor 0.00 / plotted max 7.918

02 / CONTEXT PLAN + ROOF FOOTPRINTS



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 7.918



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B12 / Tea house

A tea serving recess and a closed entrance sit under two shuttered upper rooms overlooking the raised terrace.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 1.40 / plotted max 12.068



02 / CONTEXT PLAN + ROOF FOOTPRINTS


N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 1.40 / plotted max 12.068



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

E1 CONTEXT / S2 SHARED BACK

All facade heights add local floor1.40. Roof base8.40; cap9.59; source head12.068. B05 overlaps behind this front; no independent whole-building export. E1 opens the opposite screen, not this house. Both end approaches and service cluster remain.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B13 / Back of the Spice Street shops

The service-yard enclosure uses three high blind panels and a stained base, with no public access on this side.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 7.918



02 / CONTEXT PLAN + ROOF FOOTPRINTS

N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 7.918



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B14 / Back of the caravan stores

Two small sealed inspection panels explain the retaining spine without inventing full-height storage under the ramp.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 10.118



02 / CONTEXT PLAN + ROOF FOOTPRINTS


N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 10.118



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

C: RETAINING INSPECTION PANELS

Two1.35 wide×0.85 high sealed panels at a2.328/6.984,sill0.25. No2.5 m under-terrace doors or upper vents. M02 verifies the local ramp profile; incompatible panel becomes masonry. Screen depth0.96, no warehouse interior.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B15 / Back of the tea house

Two high blind panels articulate the retaining/enclosure screen beside the terrace, with E1 opening a tested overlook.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 10.018



02 / CONTEXT PLAN + ROOF FOOTPRINTS


N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 10.018



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

E1 / G: OPEN-TOP OVERLOOK TRIAL

Cut all blockers above2.50 in x10..11,y58..61. Keep1.10 m parapet above Tea floor1.40 and tall flanks. Slot removes intersecting roof fixtures. Existing shade at y62.4 must bear on retained north flank. Baseline niches are excluded where slot cuts them. Test reciprocal fire and jumps.


MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.


B16 / North yard wall

The north retaining spine ends in two high blind panels under the existing tall coping.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE



03 / END PROFILE



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.


No automatic blank-face deletion.

MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

02 / CONTEXT PLAN + ROOF FOOTPRINTS

z floor 0.00 / plotted max 10.018



Source shells / roofs; rust = design extent, not a live transform.

RETAIN / OWNER-SPECIFIC FINISH


Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.

B18 / Dyers' arcade, east

Three low fabric bays share repaired stone arches; one approved cloth booth sits between a quiet packing bay and a distinct dye-sample seller.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 7.468



02 / CONTEXT PLAN + ROOF FOOTPRINTS


N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 7.468



REAR / EXPOSED PARTY WALL

B18: closed rear boundary; room vent0.58 x0.48 at y42.8, sill6.20. End walls retain bases, existing supported detail and complete roof returns. Roof door faces0.84 m access strip; no new ground entry.

No automatic blank-face deletion.

PILOT / C + M: THREE BUSINESSES

Packing01 / original booth02 / DY-S03. Retain repaired shell, slab4.76 and parapet5.59. Broad roof-access room x54.6..56.4,y40.9..44.7,base4.76/cap7.35 replaces seeded head/rear tier. Keep low service equipment. M02/M03/M05/M08 before completion.


MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B19 / Souk yard wall


One high niche resolves the low south enclosure at the Souk arrival.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE



02 / CONTEXT PLAN + ROOF FOOTPRINTS

z floor 0.00 / plotted max 7.918



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 7.918



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B20 / Dye works

A locked work door sits between two blind niches, with three vents above and dye work clustered at the edge.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 10.118



02 / CONTEXT PLAN + ROOF FOOTPRINTS


N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 10.118



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B21 / Dyers' house

A single-storey home steps down beside the workshop, with one centered closed door and two equal screened windows.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 7.518



02 / CONTEXT PLAN + ROOF FOOTPRINTS


N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 7.518



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

C + M: HUMAN-SCALE HOME, NOT R07 SCALE

Keep4.5 wall /2.25 door /0.85 window sills. Add one0.58×0.48 loft vent at a4.125,sill3.50. Roof slab4.76/cap5.59 retained; remove seeded towers, hatch top4.94 at x42.4..43.4,y23..24. Workshop party wall stays taller. Later study, not first pilot.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B22 / Backs onto Dyers Alley

Four evenly distributed high blind niches break a long service enclosure without adding fake access.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 7.918



02 / CONTEXT PLAN + ROOF FOOTPRINTS

N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 7.918



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B23 / Dye works cart gate


The Dogleg west service wall ends in a tall sealed loading niche, with two high vents and an otherwise quiet working face.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 7.000



02 / CONTEXT PLAN + ROOF FOOTPRINTS



Implied building depth4.2. Boundary remains sealed. Hidden volume is explanatory, not a new runtime footprint. M04 owns the west gate frame measurement.

y48..62 / east face x53 / west face x46

03 / END PROFILE

z floor 0.00 / plotted max 7.000



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

M04 / REPAIRED BLIND GATE RETAINED

Existing code-boundary gate is not a thin replacement arch. Drawing locates its center a12.056 only; outer frame/top remain M04. Keep sealed backing and wet-work edge; no new doorway, shortened gate or clear-sightline claim.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B24 / Dogleg house


One centered household door and paired windows make the Dogleg east wall read as one dwelling.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 7.000



02 / CONTEXT PLAN + ROOF FOOTPRINTS



Implied building depth4.2. Boundary remains sealed. Hidden volume is explanatory, not a new runtime footprint. M04 owns the west gate frame measurement.

y48..62 / east face x53 / west face x46

03 / END PROFILE

z floor 0.00 / plotted max 7.000



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RELIEF ON IMPLIED OFF-MAP HOUSE

Source boundary face, not a0.35 m-deep dwelling. Dashed volume extends x53..57.2,y48..62 for access explanation only. No new footprint/doorway opens the boundary. M05/M06 measure the actual dogleg and north turn.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B25 / Hammam

A tall bath hall has one heavy closed entry and high clerestories, with a small service wing across the link.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 9.020



02 / CONTEXT PLAN + ROOF FOOTPRINTS


N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 9.020



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.


MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B26 / North Court house, south


A quiet single-storey dwelling faces the court with a centered closed door and paired dark windows.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE



z floor 0.00 / plotted max 7.918

02 / CONTEXT PLAN + ROOF FOOTPRINTS



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE



z floor 0.00 / plotted max 7.918

REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RELIEF / MATERIAL CONTRADICTION RESOLVED

Keep0.96 support shell and listed cut stone. Implied house x53..57.2,y63.44..71 is explanatory only. Retain centered closed door and paired windows. No new production volume until near-city fit is measured.


MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B27 / Dyers yard wall, North Court


Two blind niches frame a workshop-yard drying rack with service access elsewhere.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE



02 / CONTEXT PLAN + ROOF FOOTPRINTS

z floor 0.00 / plotted max 7.918



N ↑

Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 7.918



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.


MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B28 / North Court yard wall, north


Two high niches continue the court enclosure below an unbroken coping.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE



02 / CONTEXT PLAN + ROOF FOOTPRINTS

z floor 0.00 / plotted max 7.918



N ↑

Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 7.918



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.


MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B29 / North Court yard wall, south


One high niche ends the southern court enclosure beside the dogleg arrival.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE



02 / CONTEXT PLAN + ROOF FOOTPRINTS

z floor 0.00 / plotted max 7.918



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 7.918



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.


MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B30 / Garden wall closing the north-west link


A garden wall gives the north-west approach one centered high niche and a continuous cap.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE



z floor 0.00 / plotted max 7.918

02 / CONTEXT PLAN + ROOF FOOTPRINTS



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE



z floor 0.00 / plotted max 7.918

REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.


MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B31 / Garden wall closing the north-east link


A quieter matching garden wall terminates the north-east approach with one high niche.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE



02 / CONTEXT PLAN + ROOF FOOTPRINTS

z floor 0.00 / plotted max 7.918



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 7.918



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B32 / Spawn A edge wall, west

The existing merchant return is the south corner front of the west spice block, not a freestanding compound facade.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 7.600



02 / PLAN + ROOF OWNERSHIP

D 2 m

Solid fill = retained nontraversable volume.
Dashed inset = existing roof setback.



03 / END PROFILE

z floor 0.00 / plotted max 7.600



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN VISIBLE KIT / SUPPORT DISTINCT

Visible kit3.5×2×7.6; support shell2.64×0.96×4.9. Source anchor owns exact transform. Keep complete return kit and attached Spice block. No duplicate skin or shelf in the gate turn. M05 checks full body sweep.

MOUNTING / APPROVAL


Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B33 / Spawn A edge wall, east

A broader south corner front begins the east spice block with one display and one closed entrance.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE


z floor 0.00 / plotted max 7.600



02 / PLAN + ROOF OWNERSHIP

D 2 m

Solid fill = retained nontraversable volume.
Dashed inset = existing roof setback.



03 / END PROFILE

z floor 0.00 / plotted max 7.600



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN VISIBLE KIT / SUPPORT DISTINCT

Visible kit5.5×2×7.6; support shell4.62×0.96×4.9. Source anchor owns exact transform. Keep complete return kit and attached Spice block. No duplicate skin or new booth. M05 checks full body sweep.


MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

B34 / Spawn B edge wall, west

A small quiet enclosure wing frames the north arrival without competing with the Rug Gate.

01 / PUBLIC FACE + ACTUAL ROOF PROFILE



03 / END PROFILE



z floor 0.00 / plotted max 7.918

REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.


No automatic blank-face deletion.

MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

02 / CONTEXT PLAN + ROOF FOOTPRINTS

z floor 0.00 / plotted max 7.918



Source shells / roofs; rust = design extent, not a live transform.

RETAIN / OWNER-SPECIFIC FINISH


Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.

B35 / Spawn B edge wall, east

A longer quiet enclosure wing balances the northern gate arrival with one offset-in-plan but centered-on-wall niche.


01 / PUBLIC FACE + ACTUAL ROOF PROFILE

z floor 0.00 / plotted max 7.918



02 / CONTEXT PLAN + ROOF FOOTPRINTS

N ↑



Source shells / roofs; rust = design extent, not a live transform.

03 / END PROFILE

z floor 0.00 / plotted max 7.918



REAR / EXPOSED PARTY WALL

Retain useful source high closures and supported projections on inhabited faces. Enclosure backs stay quiet. Hidden shared surfaces get no second mesh. Context plan distinguishes relief from full volume.

No automatic blank-face deletion.

RETAIN / OWNER-SPECIFIC FINISH

Retain the measured shell and source roof silhouette. Public bays follow this card; useful supported return/service evidence remains. No new route, upper floor or repeated extra niche. Read the district response schedule for this owner and close M02/M05/M07 before a complete-building task.

MOUNTING / APPROVAL

Opening shapes are schematic; retained repaired frames are not redesigned. Source roof boxes are a static survey, not a live scene or clearance pass. Dimensions and relationships: buildings.md; assemblies/export bounds: assets.md.

Finite asset assignments

Five complete-assembly families; same variants and membership as before

Variant	Exact intended placements	Qty
SH-L louvered teal	Spice west STORY_1_WINDOW_01/03; Tea east STORY_1_WINDOW_01	3
SH-P paneled walnut	Spice west STORY_1_WINDOW_02/05; Rug west STORY_1_WINDOW_01	3
SH-W woven infill	Spice west STORY_1_WINDOW_04; Tea east STORY_1_WINDOW_02	2
SC-D diamond lattice	Dyers Alley west-north BAY_WINDOW_S/N	2
SC-V vertical slats	Textile west STORY_1_WINDOW_01/03/04	3
SC-C fine crossed lattice	Souk west STORY_1_WINDOW_01/02; Souk west-north STORY_1_WINDOW_01; Fountain east-north STORY_1_WINDOW_01	4
SP-D spice drawers	Spice west GROUND_01	1
SP-G grain balance	Spice west GROUND_03	1
SP-A apothecary	Spice west GROUND_04	1
RG-H hanging gallery	Textile west GROUND_01; Textile east GROUND_03	2
RG-R roll chest	Textile west GROUND_03; Rug west GROUND_01	2
DY-S sample counter	Souk east GROUND_03; Souk west GROUND_01	2
Original approved textile booth	Souk east GROUND_02 retained; Textile east GROUND_01 proposed	2

B18 / export boundaries 1

Complete building is the approval unit. Fixed-origin components are export units.

Visual export / retained system	Origin and boundary	Visible replacement / exclusion
b18-dye-counter.glb (DY-S)	Base-center/rear mounting plane on GROUND_03, y44.82, exact depth offset from M02;1.80 x 0.35 x 2.25	Replace only north kiosk counter/stock/rail/grille selectors in P-DYE. Retain north arch, threshold, backing, independent awning and sign.
b18-packing-finish.glb only if needed	GROUND_01 bay axis y35.18, base0, measured rear plane. Requested maximum1.80 W x 0.45 D x 1.80 H,0.90 counter	Complete the retained packing cabinet with closed lower stock and three tied cloth bolts, rear rail1.65. Reuse source geometry where it already satisfies the envelope; export only changed cabinet parts. Do not introduce a new family or generic variation. Retain its repaired arch and independent awning.
b18-roof-access.glb	Local origin at design(54.6,40.9,4.76); local x runs east, local y north, local z up before standard GLB conversion. Envelope1.80 east-west x 3.80 north-south x 2.59 high including cap	New broad roof-access room ending at7.35, with closed roof door and one rear vent per B18. Suppress only B18 roof-silhouette-head/cap/rear-tier/rear-cap. Keep slab, parapets, full-footprint coping and low service cluster. No duplicate roof slab under the room or open interior.

B18 / export boundaries 2

Complete building is the approval unit. Fixed-origin components are export units.

Visual export / retained system	Origin and boundary	Visible replacement / exclusion
b18-finish.glb only for needed local repairs	Shell center at design(55.1,40,0); boundaries x53..57.2,y33.28..46.72, original4.5 wall. Reuse source materials	Only named wall/roof junction or supported attachment pieces after M02/M03. Retain runtime wall infill, corner piers, repaired arches, backings and collision. Material-only work needs no new mesh. Never replace the entire frontage because a finish is difficult to mask.
Original center booth	Retain actual PLACE_TEXTILE_BOOTH / DYE_E_TEXTILE_BOOTH, asset origin,1:1 orientation and material	No export, redesign, translation, scaling or suppression changes. Existing booth-specific exception remains.
Bay awnings01/03 and shared canopy	Retain existing source assemblies at measured support datums	No double covers, no canopy inside the booth export. Finish supports under those exact owners; no blanket awning suppression.

Owner dispositions / 1-6

All B/P/O cards remain in buildings.md; these are the review-specific decisions.

Owners	Concrete disposition / evidence needed
B01/B02/P02	S1 retains three west trades/two household doors; east doors serve sacks/handcarts. M03 ties, M07 two-direction skyline review; no blanket street narrowing.
B03/B04/B17/P03/P19	Repaired arches and open mid link retained. Resolve wing access above and shared roof in assembly-fit. M06 tests Fountain's four-way pressure and x=26..32 escape band.
B05/B06/P04	S2; packing bays complete, actual column preserved. Extra booth remains fit-dependent. G1 conditional; connector deferred unless repeated trap evidence.
B07/B08/P05	Keep west display/service split and Gatekeeper's separated wings/full pilaster. M05 and M07 review both upper-link approaches, gate soffit and receiving view.
B09-B11/P08	Retain locked handcart stores and yard enclosure; cart handling is a 0.8 m door-service floor plus measured turning pocket, not a wagon court claim. Keep ramp entry and mid-link options. M05/M07 decide wall hierarchy.
B12-B16/P07/P09-P13	E1 first, B14 corrected panels, Tea source shade and end grades retained. B13 keeps its three existing blind panels as enclosure joints rather than adding decoration. No niche production batch until Service's moving sequence is reviewed.

Owner dispositions / 7-12

All B/P/O cards remain in buildings.md; these are the review-specific decisions.

Owners	Concrete disposition / evidence needed
B18/B19/P15	B18 complete-building pilot. B19 is a 4.2 m-long, 4.9 m-high wall; preserve open turn. Souk north end remains solid with zero fake arches. M06 checks emerging mid-link pressure; M02/M03 handle trade/support fit.
B20-B22/P14	Wet work against east wall and workshop edge, quiet home retained. B22 keeps source high panel positions and full repairs; no extra niches for density. M05 maps racks/vats against body volume; localized dye wear follows their positions.
B23/B24/P16	Code-boundary skins with implied use, never independent thin buildings. M04 actual gate; M06 measures whether a dogleg sightline exists before adding one. M05 tests inside north turn.
B25-B29/P17	Bath, domestic edge and drying yard remain distinct. Keep open release and edge work access. Drainage is flush joint/base wear toward existing low points; no invented trench/outfall. M05/M06 inspect each mouth and escape.
B30/B31/P24/P25	Preserve repaired full-height niches and link walls; M05 checks NW service turn and NE workstation separately. No symmetrical dressing rollout.
B32/B33/P01/P22/P23	Retain complete Spawn-A kits, label visible versus support bounds. Three exits remain. M05 protects both inside turns; M06 validates actual initial placement/fallback behavior.

Owner dispositions / 13-18

All B/P/O cards remain in buildings.md; these are the review-specific decisions.

Owners	Concrete disposition / evidence needed
B34/B35/P06	Quiet receiving wings retained; do not call central gate the only escape because side links exist. M07 reviews exit recognition with O06; M06 treats B spawns independently from A.
P18/P20/P21	Mid link5 x 5; West Upper2 m long/4.5 m wide; East Upper7 x 5, clear3.5. Preserve unequal geometry. M05/M06 compare emerging threat and bot congestion, not nominal symmetry.
O01/O02/O03	Keep closed city gate, unequal domestic parcels and dye-process rear. These supply construction/occupation precedent; no changed meshes. M05 verifies source kits' full body envelope.
O04/O05/O06	Preserve open Spice/Rug portals and stepped receiving backdrop. M07 checks both-direction layer overlap and closed off-map access cues, M06 visibility around transitions.
O07	All14 overheads get endpoint/low-sag/support records; assets.md names the high-tie revisions. Retain hanging textiles and sky gaps, not arbitrary unsupported endpoints.
O08/O09	Keep sealed collision boundary and120 deterministic shells. Near visible ring0 north/east silhouettes may retain or receive two backed upper service closures per selected shell after M07 selects actual visible shell IDs; no new placement until those IDs are recorded. Distant shells remain economical. No blanket120-shell window export or blanket removal of inhabited context.

One small graybox batch / 1

A baseline / B E1 only / C G1 only if triggered; do not combine alternatives first

Snapshot / bounded sample	Exact trial	Evidence and decision
A: current map	Run 12 canonical routes plus bot smoke once. Two 90-second holds at Tea (wave 1 and wave 7/tier 3 baseline), then leave by both ends. Main, Service and Dyers circuits: one 90-second run each at each pressure, including reload and reversal.	Record contacts <8 / 8-18 / >18 m, first incoming shot, damage, contact breaks, route dwell, pressure timing, bot arrival directions and usable escape windows. Save actual seed, start, profile and fallback use; do not assume a seed override exists.
B: A + E1 only	Cut all visual, projectile and LOS blockers in the specified western slot above +2.50; retain both grades and approaches. Repeat Tea holds/traversals with the same controls, tier, pressure and seed when available.	Standing and crouched reciprocal shots at (11.7,59.5) and ground (6,59.5), plus bots from both ramp/stairs. Keep only if the overlook offers a useful exposure/retreat choice and bots can challenge it. Reject grounding defects, one-way visual protection, unreachable camping or a new jump/drop exploit.

Record actual seed/profile/start, early and later pressure, contact distances, damage, escape choice, bot arrival and fallback. Repeat an ambiguous comparison once, then leave it unresolved. No live test was run by this design revision.

One small graybox batch / 2

A baseline / B E1 only / C G1 only if triggered; do not combine alternatives first

Snapshot / bounded sample	Exact trial	Evidence and decision
C: A + G1 only, conditional on A	Test only if A repeatedly yields easy long shots during retreat or no useful reload break at Textile south. Add the one matched solid return, then repeat main circuit/reversal and Fountain-to-Textile approaches both ways.	Keep only if measured contact breaks/escape choices improve without persistent congestion or unavoidable corner damage. If x=28..33 still dominates firing, reject this candidate as insufficient; do not silently add a second obstruction.
Each changed snapshot	Repeat canonical routes/bot smoke, then moving body sweeps in the changed area. Check both starts with three recorded spawn selections and six later-wave turnovers across Fountain/Tea/North.	Initial final placement: existing zero-visible/opposite-half/24 m expectations. Later waves follow their own runtime rules. Record fallback, first sight/shot and escape directions. Do not infer safety from spawn-center distance.

Record actual seed/profile/start, early and later pressure, contact distances, damage, escape choice, bot arrival and fallback. Repeat an ambiguous comparison once, then leave it unresolved. No live test was run by this design revision.

Measurements before dependent production / 1

Proposed does not mean fitted, playable, approved or performance-verified.

ID	Required measurement / output	Affected choice
M01	B04/B17 oblique plan/section with actual shared backing, roof owner, 0.2 m offset strips and y=39..44 passage; B05/B06/B12 overlaps also marked	No independent intersecting building exports; use the current shared-shell solution
M02	At floor, counter, shelf, arch spring, ledger and braces: usable width/depth, backing/wall plane, threshold, model low/high bounds and all fixture/collider AABBs	B18 pilot first; each later window/counter/booth gets its own fit record. 0.08 m lateral opening / 0.12 m canopy-opening / 0.05 m placement / 0.08 m fixture gaps remain floors
M03	Both ends of all six canopies/eight lines: support x/y/z, actual receiving member, ledger/brace reach, minimum sag, hem, opening/cloth overlaps	Resolve Spice/Textile high eastern ties; verify Tea support remains outside E1; canopy poles never enter paths
M04	Dogleg gate frame outer width/top, backing, actual wall interval and rack/vat/workstation envelopes	Retain repaired gate; no unmeasured thin substitute or reopened boundary

Measurements before dependent production / 2

Proposed does not mean fitted, playable, approved or performance-verified.

ID	Required measurement / output	Affected choice
M05	Standing/crouched/jumping and diagonal turn sweeps at E1/G1, Tea transitions, B18 bays, Dogleg edges, both north turns and Spawn-A kits	Keep 6 / 4.5 / 4 / 3.5 m floors and entire body volume; camera-only clearance is insufficient
M06	Collider/visible tops and reciprocal eye/weapon rays for eight covers, two spawn covers and fountain; matched survival telemetry	Decide partial cover versus concealment, G1 value, Fountain exposure and long-lane kiting. No cover resize by implication
M07	North/south Spice and Textile sequence; moving bots at 8, 18 and approximately 30 m in sun/shade/cloth; two first-look human navigation passes if available, one mobile	Test warm-light readability, business versus route signs, roof overlap, maintained sky gaps and false doors. No sun angle/exposure values invented
M08	Same-pose draws, triangles and CPU, then desktop/mobile combat profile for selected pilot	Existing 1,500 draws / 2.2M triangles / 12.5 ms desktop median CPU; mobile 500 draws / 1.3M triangles / 30 FPS. Measure net suppression cost and repeat a >10% CPU regression once

Review boundary / stop here

Recommended sequence: graybox decision, then complete B18 pilot

Review the spatial design and explicit test candidates first. S1/S2 establish broad roof steps; E1 challenges Tea from the ground; G1 is a conditional partial ray break. The original three-route graph stays until evidence supports a change.

Read the complete schedules and tests in README.md, buildings.md and assets.md. The independent review and all reference images remain intact.

The following pilot is B18: three trades around the actual approved booth, retained repaired arch masonry, complete supported awnings, broad roof-access room, outer corners, rear ownership and flush ground contact. M02/M03/M05 must close fit before modeling.

Source snapshot: dev-4 / f0dab246d209705ee038290c1cd6d40c9b3daed4. Spec hash starts eb1dcf02 and matches the existing compiled map. Current source roofs were evaluated in memory, not regenerated to disk.

Only design documents and drawings changed. No asset production, map-spec edit, runtime geometry, gameplay implementation, branch switch, commit or deployment. No claim of new gameplay, traversal or performance verification.

Status: proposed for owner review. Implementation is deferred. This atlas is presentation evidence; it does not own implemented map state.