

boiling (Figure 8(d)).




Figure 8. Comparison of the bubble ebullition cycle and boiling behavior of the textured PDMS-coated