




Fig. 1. Comparison of literature values for falling film enhancement factor K_{ff} for plain tubes for R-134a at saturation temperatures close to 5 °C.