







(a) Polished




(b) Roughened




(c) LbL – top view




(d) LbL – cross-section



(e) CuO – top view



(f) CuO – cross-section



(g) nanoFLUX

Fig. 2. SEM images of test section surfaces (a and b taken from Bock et al. [26]).

of the nanoparticles could have limited the porosity pro-

test section length by