





Fig. 2. SEM images of the (A) bare copper surface and (B) sand blasted copper.

3. Result and discussion

diamond and Cu [14]. In Fig. 3(A), some cracks formed during the interaction of the diamond with the Cu substrate.