




Fig. 4. XRD patterns of the diamond coating on (A) untreated copper and (B) sandblasted copper.