




Fig. 5. SEM images of CNT coating (A) on diamond coated Cu, (B) on bare Cu, (C) on diamond coated Cu after tap water test, and (D) on bare copper after tap water test.