




Fig. 4. Images obtained at 8000 frames per second depicting the effect of surface roughness and heat flux upon the nucleation behavior of vapor bubbles on a heated wall. The scale is shown below the photos.