





(a)



(b)

Fig. 3. Photos of completed boiling test pieces: (a) surface 1, polished – reverse side, and (b) surface 4, 100- μm particle abraded – top side.

liquid pool temperature was required from of a uniform temperature stratification in the requirements were n

3.1. Sealing

The chamber was thick (except for the form an airtight thermal wall material due to its chemical inertness, along The four walls were E-214HP) known to liquids, and were held by gaskets separated the floor screws from floor and joints when assembled. The doors measuring 76 cm were located in the floor in the ceiling. These doors had o-rings. The transparent in the center of the chamber a similar o-ring. Each door was held in place by the facility box.

3.2. Thermal control

The walls, floor, and channels through which the fluid passed in order to form a secondary fluid loop, a cooling of the chamber and necessary. An immer