




Fig. 6. Apparent boiling curves (heat flux uncorrected) measured by the $400 \mu m \times 25 \text{ mm}$ ITO heater/sensor test strip of surface 5. Good repeatability was obtained between tests.