




Fig. 10. (a) Comparison of boiling curves for bare and fully CNT-coated silicon surfaces, and (b) corresponding boiling photographs.