Ocular Visit

Network Team

Date:	February 5, 2026
Title:	Technical Inspection For Network Infrastructure
Location:	Robinsons Metro East
Address:	Marcos Highway, Brgy. Dela Paz, Pasig City
Coordinates	14°37′09″N 121°06′00″E
Name of Engineer:	Jake Mamaril

Tasks

- Ask Mall's Operations Manager/ Lead IT/ Engineer for ISP Building Infastructure
- Test cellular signal strength for major carriers.
- Verify the location of the MDF/ IDF/ MTTC/ Auxiliary Room or the nearest path to connect.

1. Mall Infrastructure

Action		**Details & Verification**		
Internet Provision		*Yellow Box*	*Conduit*	*Notes*
		None	None	No Yellow box and existing provisions
ISP Provider Feasibility		*Copper*	*Fiber*	*Notes*
	PLDT	✔	None	The Mall has a copper facility for PLDT but no copper provisions on the site , need an end to end Copper Layout from MDF to Client TTC
	Eastern	None	✔	The Mall has a facility for fiber connection end to end process process FOC layout from MDF to Client TTC

	Radius	None	✔	The Mall has a facility for fiber connection end to end process process FOC layout from MDF to Client TTC
	Converge	None	None	
Open for outside facilty build?		No		
Starlink		Not Feasible		

2. Cellular Signal Strength

Network	Technology 4G / 5G	Download	Upload	Latency	Notes
Smart	LTE	8.94	0.99	135	Low Bandwidth
Globe	LTE	12.0	2.82	22	Low Bandwidth
Gomo	N/A	N/a	N/a	N/a	-
Dito	LTE	44.3	39.8	26	Acceptable speed

3. Next Steps/ Action Items

Remarks - Bullet List
- For Joint activity visit with Contractor for PLDT - For table top assessment for PLDT if fiber facility ready


3:05
LTE 62
SPEEDTEST
DOWNLOAD Mbps
UPLOAD Mbps
8.94
0.99
Ping ms 39 494 --
Jitter ms 135
Detailed Result
Test Again
Smart
NEWCOMERS
GET A CHANCE TO ENJOY UP TO
10,420P
1.5% REBATE
Based on valid plays
How likely is it that you would recommend Smart to a friend or colleague?
0 1 2 3 4 5 6 7 8 9 10
Not at all likely
Extremely Likely
Speed
Video
Downdetector
Map
VPN


3:04
LTE 62
SPEEDTEST
DOWNLOAD Mbps
UPLOAD Mbps
12.0
2.82
Ping ms 25 265 578
Jitter ms 22
Detailed Result
Test Again
Globe
Test ID: 6951095227
How would you rate Globe?
Speed
Video
Downdetector
Map
VPN


3:01
LTE 62
SPEEDTEST
DOWNLOAD Mbps
UPLOAD Mbps
44.3
39.8
Ping ms 22 1048 165
Jitter ms 26
Detailed Result
Test Again
DITO
Test ID: 6951093727
Service Status
Gmail
View all outages on Downdetector
How would you rate DITO?
Speed
Video
Downdetector
Map
VPN

4. Document Signature

DISCLAIMER:

- All information in this report has been reviewed and approved by the relevant team.
- By accepting or signing it, the recipient confirms that the details are accurate and complete to the best of their knowledge.
- Any corrections or additional information should be promptly communicated for necessary updates.

Network Engineer	**Date**
Jake Mamaril	
Network Supervisor	**Date**
Pocholo Bautista	
Senior IT Manager	**Date**
Jonathan Castillo	