


VehicleError 03 | Fold 2 | C-R2 Δ FDE=+7.634 m | boston-seaport
Scene ID: 5560a973257e407b8d5bf9fb92b1e0f3
Actor ID: 5560a973257e407b8d5bf9fb92b1e0f3|0733312030d04531ae62435b1b32afce|52d6ae5896eb40298eff87826fcaa24b



lane
lane_connector
drivable_area
carpark_area
All six frozen candidates
R2 Top1 (k4)
Oracle candidate (k3)
C Raw Top1 (k0)
GT (offline reference)
Observed t0

Mode	FDE (m)	C Raw p	C Cal p	Lane mean (m)	Heading err (rad)	Drivable inside	Carpark inside
k0 C	45.040	0.791	0.313	22.755	1.533	1.000	missing
k1	20.178	0.000	0.080	9.967	0.051	1.000	missing
k2	49.940	0.000	0.098	22.391	1.517	1.000	missing
k3 O	5.877	0.000	0.020	13.947	0.041	1.000	missing
k4 R2	37.406	0.209	0.304	22.940	1.560	1.000	missing
k5	29.907	0.000	0.185	23.667	1.566	1.000	missing