


Stage12A — OOF Development Evidence; GT/oracle are offline references

VehicleError 06 | Fold 2 | C-R2 Δ FDE=+7.335 m | singapore-onenorth
Scene ID: f0294478e1994642bac453f1e84610df
Actor ID: f0294478e1994642bac453f1e84610df|ad9a4ac746ed482d9011da67b95d0364|12558ad4435445f1b8199696c9af6622



Mode	FDE (m)	C Raw p	C Cal p	Lane mean (m)	Heading err (rad)	Drivable inside	Carpark inside
k0 C	48.126	0.981	0.287	29.083	1.106	0.833	missing
k1	24.801	0.000	0.090	16.847	0.014	1.000	missing
k2	53.853	0.000	0.144	26.785	1.126	0.750	missing
k3 O	10.990	0.000	0.028	10.152	0.019	1.000	missing
k4 R2	40.790	0.019	0.261	14.901	0.459	0.833	missing
k5	33.803	0.000	0.190	13.654	0.463	0.917	missing