


Open Claw – Assembly



Cables · 180 total, 60 length groups

Sort the unlabelled cables off the factory pallet by length, then engrave the listed `<joint>.<slot>` labels onto each cable's two ends. Each row gives one length and the cable-end label pairs you stamp onto the cables of that length. Apex-attached cables (red rows) are unique singletons — one cable per row, no triple compression.

Struts · 46 pages, one per push interval

One A4 page per push strut, in length order. Each page shows the strut with its two end joints, an exploded diagram of the connector-disc stack at each end (slot numbers, rotational angles, signed bend angles), and the `<joint>.<slot>` cable target every disc connects to. Use these once the cables are labelled, when you thread each end through the connector slots.


LENGTH (MM)	QTY	CABLE ENDS (ENGRAVE THESE)		
142	3	BAA.2:BX1Z4.3	BAB.2:CX1Z4.3	BAC.2:AX1Z4.3
184	3	BAB.3:BX2Z2.3	BAC.3:CX2Z2.3	BAA.3:AX2Z2.3
272	3	TAA.4:AX1Z0.3	TAB.4:BX1Z0.3	TAC.4:CX1Z0.3
292	3	AX1Z1.3:AX3Z4.3	BX1Z1.3:BX3Z4.3	CX1Z1.3:CX3Z4.3
344	3	CX2Z5.3:CX4Z2.3	BX2Z5.3:BX4Z2.3	AX2Z5.3:AX4Z2.3
457	3	CX1Z3.3:CX3Z0.3	BX1Z3.3:BX3Z0.3	AX1Z3.3:AX3Z0.3
600	3	BX2Z1.3:BX4Z4.3	AX2Z1.3:AX4Z4.3	CX2Z1.3:CX4Z4.3
654	3	T0A.4:CX1Z2.3	T0C.4:BX1Z2.3	T0B.4:AX1Z2.3
700	3	TAC.3:AX2Z4.3	TAB.3:CX2Z4.3	TAA.3:BX2Z4.3
733	3	BX2Z0.1:BX1Z5.2	CX2Z0.1:CX1Z5.2	AX2Z0.1:AX1Z5.2
738	3	CX3Z2.1:CX2Z3.2	AX3Z2.1:AX2Z3.2	BX3Z2.1:BX2Z3.2
741	3	CX3Z2.2:CX2Z1.1	BX3Z2.2:BX2Z1.1	AX3Z2.2:AX2Z1.1
745	3	CX2Z0.2:CX1Z3.1	AX2Z0.2:AX1Z3.1	BX2Z0.2:BX1Z3.1
750	6	CX4Z0.2:CX3Z3.1 CX3Z4.1:CX2Z1.2	BX4Z0.2:BX3Z3.1 AX3Z4.1:AX2Z1.2	AX4Z0.2:AX3Z3.1 BX3Z4.1:BX2Z1.2
756	3	CX4Z4.2:CX3Z5.2	AX4Z4.2:AX3Z5.2	BX4Z4.2:BX3Z5.2
763	3	CX1Z2.1:B0A.2	AX1Z2.1:B0B.2	BX1Z2.1:B0C.2
765	6	BX2Z4.2:BX1Z5.1 AX3Z0.2:AX2Z3.1	CX2Z4.2:CX1Z5.1 BX3Z0.2:BX2Z3.1	AX2Z4.2:AX1Z5.1 CX3Z0.2:CX2Z3.1
766	3	CX1Z4.1:TAB.2	BX1Z4.1:TAA.2	AX1Z4.1:TAC.2
769	3	AX2Z3.3:AX4Z0.3	BX2Z3.3:BX4Z0.3	CX2Z3.3:CX4Z0.3
777	3	AX3Z0.1:AX2Z5.4	CX3Z0.1:CX2Z5.4	BX3Z0.1:BX2Z5.4
778	3	AX4Z2.4:AX3Z1.1	CX4Z2.4:CX3Z1.1	BX4Z2.4:BX3Z1.1
780	3	AX1Z2.4:TAC.1	BX1Z2.4:TAA.1	CX1Z2.4:TAB.1
790	6	CX2Z2.1:CX1Z3.4 CX3Z4.2:CX2Z5.1	AX2Z2.1:AX1Z3.4 BX3Z4.2:BX2Z5.1	BX2Z2.1:BX1Z3.4 AX3Z4.2:AX2Z5.1

LENGTH (MM)	QTY	CABLE ENDS (ENGRAVE THESE)
801	3	AX1Z0.4:B0B.1 CX1Z0.4:B0A.1 BX1Z0.4:B0C.1
805	3	CX2Z4.1:CX1Z1.4 BX2Z4.1:BX1Z1.4 AX2Z4.1:AX1Z1.4
834	6	CX2Z2.4:CX1Z1.1 AX2Z2.4:AX1Z1.1 BX2Z2.4:BX1Z1.1 CX1Z0.1:BAC.4 AX1Z0.1:BAA.4 BX1Z0.1:BAB.4
838	3	BX1Z4.4:BAB.1 CX1Z4.4:BAC.1 AX1Z4.4:BAA.1
841	3	CX4Z0.1:CX3Z5.4 BX4Z0.1:BX3Z5.4 AX4Z0.1:AX3Z5.4
877	3	CX4YZ0.1:CX4Z5.1 AX4YZ0.1:AX4Z5.1 BX4YZ0.1:BX4Z5.1
880	3	BX3Z1.3:BX4Z5.2 CX3Z1.3:CX4Z5.2 AX3Z1.3:AX4Z5.2
883	3	AX3Z3.3:AX4Z3.1 CX3Z3.3:CX4Z3.1 BX3Z3.3:BX4Z3.1
888	3	BX4Z2.1:BX3Z3.4 CX4Z2.1:CX3Z3.4 AX4Z2.1:AX3Z3.4
890	3	CX4YZ0.2:CX4Z3.2 AX4YZ0.2:AX4Z3.2 BX4YZ0.2:BX4Z3.2
892	3	AX4Z4.1:AX3Z1.4 CX4Z4.1:CX3Z1.4 BX4Z4.1:BX3Z1.4
893	3	CX4YZ0.3:CX4Z1.2 AX4YZ0.3:AX4Z1.2 BX4YZ0.3:BX4Z1.2
955	1	YZ0.1:T0B.1
959	1	YZ0.2:T0A.1
963	1	YZ0.3:T0C.1
966	3	B0C.4:BX2Z0.3 B0B.4:AX2Z0.3 B0A.4:CX2Z0.3
1016	3	AX3Z5.3:AX4Z1.1 BX3Z5.3:BX4Z1.1 CX3Z5.3:CX4Z1.1
1024	3	AX1Z5.3:AX3Z2.3 BX1Z5.3:BX3Z2.3 CX1Z5.3:CX3Z2.3
1190	3	BX1Z4.2:BX1Z1.2 CX1Z4.2:CX1Z1.2 AX1Z4.2:AX1Z1.2
1269	3	AX2Z2.2:AX2Z5.2 BX2Z2.2:BX2Z5.2 CX2Z2.2:CX2Z5.2
1271	3	BX1Z0.2:BX1Z3.2 AX1Z0.2:AX1Z3.2 CX1Z0.2:CX1Z3.2
1276	3	BX4Z0.4:BX4Z3.4 CX4Z0.4:CX4Z3.4 AX4Z0.4:AX4Z3.4
1279	3	AX4Z2.2:AX4Z5.4 BX4Z2.2:BX4Z5.4 CX4Z2.2:CX4Z5.4
1281	3	CX4Z4.4:CX4Z1.4 AX4Z4.4:AX4Z1.4 BX4Z4.4:BX4Z1.4

LENGTH (MM)	QTY	CABLE ENDS (ENGRAVE THESE)		
1288	3	AX1Z2.2:AX1Z5.4	BX1Z2.2:BX1Z5.4	CX1Z2.2:CX1Z5.4
1300	3	CX2Z0.4:CX2Z3.4	AX2Z0.4:AX2Z3.4	BX2Z0.4:BX2Z3.4
1305	3	AX2Z4.4:AX2Z1.4	CX2Z4.4:CX2Z1.4	BX2Z4.4:BX2Z1.4
1307	3	CX4YZ1.1:CX4Z1.3	AX4YZ1.1:AX4Z1.3	BX4YZ1.1:BX4Z1.3
1314	3	CX4YZ1.2:CX4Z3.3	AX4YZ1.2:AX4Z3.3	BX4YZ1.2:BX4Z3.3
1318	3	CX4YZ1.3:CX4Z5.3	AX4YZ1.3:AX4Z5.3	BX4YZ1.3:BX4Z5.3
1362	1	YZ1.1:T0C.3		
1363	3	BX3Z4.4:BX3Z1.2	CX3Z4.4:CX3Z1.2	AX3Z4.4:AX3Z1.2
1368	1	YZ1.2:T0A.3		
1369	3	BX3Z2.4:BX3Z5.1	CX3Z2.4:CX3Z5.1	AX3Z2.4:AX3Z5.1
1374	1	YZ1.3:T0B.3		
1383	3	AX3Z0.4:AX3Z3.2	CX3Z0.4:CX3Z3.2	BX3Z0.4:BX3Z3.2
1410	3	B0A.3:T0B.2	B0C.3:T0A.2	B0B.3:T0C.2

YZ0:YZ1

Strut · 1791 mm





Joint YZ0 ↓ BOTTOM

HERE	BEND	ROT	THERE
YZ0.1	-30°	106°	T0B.1
YZ0.2	-30°	346°	T0A.1
YZ0.3	-30°	226°	T0C.1


Joint YZ1 ↑ TOP

HERE	BEND	ROT	THERE
YZ1.1	-49°	134°	T0C.3
YZ1.2	-49°	014°	T0A.3
YZ1.3	-49°	254°	T0B.3



CX4YZ0 : CX4YZ1

Strut · 1792 mm





Joint CX4YZ0 ↑ TOP

HERE	BEND	ROT	THERE
CX4YZ0.1	-30°	184°	CX4Z5.1
CX4YZ0.2	-30°	306°	CX4Z3.2
CX4YZ0.3	-30°	071°	CX4Z1.2


Joint CX4YZ1 ↓ BOTTOM

HERE	BEND	ROT	THERE
CX4YZ1.1	-49°	289°	CX4Z1.3
CX4YZ1.2	-49°	054°	CX4Z3.3
CX4YZ1.3	-49°	176°	CX4Z5.3



AX4YZ0 : AX4YZ1

Strut · 1792 mm





Joint AX4YZ0 ↑ TOP

HERE	BEND	ROT	THERE
AX4YZ0.1	-30°	184°	AX4Z5.1
AX4YZ0.2	-30°	306°	AX4Z3.2
AX4YZ0.3	-30°	071°	AX4Z1.2


Joint AX4YZ1 ↓ BOTTOM

HERE	BEND	ROT	THERE
AX4YZ1.1	-49°	289°	AX4Z1.3
AX4YZ1.2	-49°	054°	AX4Z3.3
AX4YZ1.3	-49°	176°	AX4Z5.3



BX4YZ0 : BX4YZ1

Strut · 1792 mm





Joint BX4YZ0 ↑ TOP

HERE	BEND	ROT	THERE
BX4YZ0.1	-30°	184°	BX4Z5.1
BX4YZ0.2	-30°	306°	BX4Z3.2
BX4YZ0.3	-30°	071°	BX4Z1.2


Joint BX4YZ1 ↓ BOTTOM

HERE	BEND	ROT	THERE
BX4YZ1.1	-49°	289°	BX4Z1.3
BX4YZ1.2	-49°	054°	BX4Z3.3
BX4YZ1.3	-49°	176°	BX4Z5.3



AX4Z2 : AX4Z3

Strut · 1912 mm





Joint AX4Z2 ↑ TOP

HERE	BEND	ROT	THERE
AX4Z2.1	-68°	301°	AX3Z3.4
AX4Z2.2	-49°	173°	AX4Z5.4
AX4Z2.3	+12°	320°	AX2Z5.3
AX4Z2.4	-30°	115°	AX3Z1.1


Joint AX4Z3 ↓ BOTTOM

HERE	BEND	ROT	THERE
AX4Z3.1	-68°	059°	AX3Z3.3
AX4Z3.2	-68°	266°	AX4YZ0.2
AX4Z3.3	+12°	204°	AX4YZ1.2
AX4Z3.4	-49°	006°	AX4Z0.4



BX4Z2 : BX4Z3

Strut · 1912 mm





Joint BX4Z2 ↑ TOP

HERE	BEND	ROT	THERE
BX4Z2.1	-68°	301°	BX3Z3.4
BX4Z2.2	-49°	173°	BX4Z5.4
BX4Z2.3	+12°	320°	BX2Z5.3
BX4Z2.4	-30°	115°	BX3Z1.1


Joint BX4Z3 ↓ BOTTOM

HERE	BEND	ROT	THERE
BX4Z3.1	-68°	059°	BX3Z3.3
BX4Z3.2	-68°	266°	BX4YZ0.2
BX4Z3.3	+12°	204°	BX4YZ1.2
BX4Z3.4	-49°	006°	BX4Z0.4



CX4Z2 : CX4Z3

Strut · 1912 mm




Joint CX4Z2 ↑ TOP

HERE	BEND	ROT	THERE
CX4Z2.1	-68°	301°	CX3Z3.4
CX4Z2.2	-49°	173°	CX4Z5.4
CX4Z2.3	+12°	320°	CX2Z5.3
CX4Z2.4	-30°	115°	CX3Z1.1


Joint CX4Z3 ↓ BOTTOM

HERE	BEND	ROT	THERE
CX4Z3.1	-68°	059°	CX3Z3.3
CX4Z3.2	-68°	266°	CX4YZ0.2
CX4Z3.3	+12°	204°	CX4YZ1.2
CX4Z3.4	-49°	006°	CX4Z0.4

Joint CX4Z2




Joint CX4Z3



BX4Z4 : BX4Z5

Strut · 1918 mm





Joint BX4Z4 ↑ TOP

HERE	BEND	ROT	THERE
BX4Z4.1	-68°	277°	BX3Z1.4
BX4Z4.2	-30°	094°	BX3Z5.2
BX4Z4.3	+12°	311°	BX2Z1.3
BX4Z4.4	-49°	161°	BX4Z1.4


Joint BX4Z5 ↓ BOTTOM

HERE	BEND	ROT	THERE
BX4Z5.1	-68°	283°	BX4YZ0.1
BX4Z5.2	-68°	083°	BX3Z1.3
BX4Z5.3	+12°	217°	BX4YZ1.3
BX4Z5.4	-49°	017°	BX4Z2.2



CX4Z4 : CX4Z5

Strut · 1918 mm




Joint CX4Z4 ↑ TOP

HERE	BEND	ROT	THERE
CX4Z4.1	-68°	277°	CX3Z1.4
CX4Z4.2	-30°	094°	CX3Z5.2
CX4Z4.3	+12°	311°	CX2Z1.3
CX4Z4.4	-49°	161°	CX4Z1.4


Joint CX4Z5 ↓ BOTTOM

HERE	BEND	ROT	THERE
CX4Z5.1	-68°	283°	CX4YZ0.1
CX4Z5.2	-68°	083°	CX3Z1.3
CX4Z5.3	+12°	217°	CX4YZ1.3
CX4Z5.4	-49°	017°	CX4Z2.2

Joint CX4Z4




Joint CX4Z5



AX4Z4 : AX4Z5

Strut · 1918 mm





Joint AX4Z4 ↑ TOP

HERE	BEND	ROT	THERE
AX4Z4.1	-68°	277°	AX3Z1.4
AX4Z4.2	-30°	094°	AX3Z5.2
AX4Z4.3	+12°	311°	AX2Z1.3
AX4Z4.4	-49°	161°	AX4Z1.4


Joint AX4Z5 ↓ BOTTOM

HERE	BEND	ROT	THERE
AX4Z5.1	-68°	283°	AX4YZ0.1
AX4Z5.2	-68°	083°	AX3Z1.3
AX4Z5.3	+12°	217°	AX4YZ1.3
AX4Z5.4	-49°	017°	AX4Z2.2



AX4Z0 : AX4Z1

Strut · 1953 mm





Joint AX4Z0 ↑ TOP

HERE	BEND	ROT	THERE
AX4Z0.1	-68°	325°	AX3Z5.4
AX4Z0.2	-30°	135°	AX3Z3.1
AX4Z0.3	+12°	008°	AX2Z3.3
AX4Z0.4	-49°	199°	AX4Z3.4


Joint AX4Z1 ↓ BOTTOM

HERE	BEND	ROT	THERE
AX4Z1.1	-68°	035°	AX3Z5.3
AX4Z1.2	-68°	241°	AX4YZ0.3
AX4Z1.3	+12°	174°	AX4YZ1.1
AX4Z1.4	-49°	339°	AX4Z4.4



BX4Z0 : BX4Z1

Strut · 1953 mm





Joint BX4Z0 ↑ TOP

HERE	BEND	ROT	THERE
BX4Z0.1	-68°	325°	BX3Z5.4
BX4Z0.2	-30°	135°	BX3Z3.1
BX4Z0.3	+12°	008°	BX2Z3.3
BX4Z0.4	-49°	199°	BX4Z3.4


Joint BX4Z1 ↓ BOTTOM

HERE	BEND	ROT	THERE
BX4Z1.1	-68°	035°	BX3Z5.3
BX4Z1.2	-68°	241°	BX4YZ0.3
BX4Z1.3	+12°	174°	BX4YZ1.1
BX4Z1.4	-49°	339°	BX4Z4.4



CX4Z0 : CX4Z1

Strut · 1953 mm





Joint CX4Z0 ↑ TOP

HERE	BEND	ROT	THERE
CX4Z0.1	-68°	325°	CX3Z5.4
CX4Z0.2	-30°	135°	CX3Z3.1
CX4Z0.3	+12°	008°	CX2Z3.3
CX4Z0.4	-49°	199°	CX4Z3.4


Joint CX4Z1 ↓ BOTTOM

HERE	BEND	ROT	THERE
CX4Z1.1	-68°	035°	CX3Z5.3
CX4Z1.2	-68°	241°	CX4YZ0.3
CX4Z1.3	+12°	174°	CX4YZ1.1
CX4Z1.4	-49°	339°	CX4Z4.4



CX3Z0 : CX3Z1

Strut · 1983 mm




Joint CX3Z0 ↑ TOP

HERE	BEND	ROT	THERE
CX3Z0.1	-68°	112°	CX2Z5.4
CX3Z0.2	-12°	304°	CX2Z3.1
CX3Z0.3	+12°	068°	CX1Z3.3
CX3Z0.4	-49°	203°	CX3Z3.2


Joint CX3Z1 ↓ BOTTOM

HERE	BEND	ROT	THERE
CX3Z1.1	-68°	253°	CX4Z2.4
CX3Z1.2	-49°	308°	CX3Z4.4
CX3Z1.3	+12°	186°	CX4Z5.2
CX3Z1.4	-30°	036°	CX4Z4.1

Joint CX3Z0




Joint CX3Z1



BX3Z0 : BX3Z1

Strut · 1983 mm




Joint BX3Z0 ↑ TOP

HERE	BEND	ROT	THERE
BX3Z0.1	-68°	112°	BX2Z5.4
BX3Z0.2	-12°	304°	BX2Z3.1
BX3Z0.3	+12°	068°	BX1Z3.3
BX3Z0.4	-49°	203°	BX3Z3.2


Joint BX3Z1 ↓ BOTTOM

HERE	BEND	ROT	THERE
BX3Z1.1	-68°	253°	BX4Z2.4
BX3Z1.2	-49°	308°	BX3Z4.4
BX3Z1.3	+12°	186°	BX4Z5.2
BX3Z1.4	-30°	036°	BX4Z4.1

Joint BX3Z0




Joint BX3Z1



AX3Z0 : AX3Z1

Strut · 1983 mm





Joint AX3Z0 ↑ TOP

HERE	BEND	ROT	THERE
AX3Z0.1	-68°	112°	AX2Z5.4
AX3Z0.2	-12°	304°	AX2Z3.1
AX3Z0.3	+12°	068°	AX1Z3.3
AX3Z0.4	-49°	203°	AX3Z3.2


Joint AX3Z1 ↓ BOTTOM

HERE	BEND	ROT	THERE
AX3Z1.1	-68°	253°	AX4Z2.4
AX3Z1.2	-49°	308°	AX3Z4.4
AX3Z1.3	+12°	186°	AX4Z5.2
AX3Z1.4	-30°	036°	AX4Z4.1



BX1Z0 : BX1Z1

Strut · 1989 mm





Joint BX1Z0 ↑ TOP

HERE	BEND	ROT	THERE
BX1Z0.1	-68°	144°	BAB.4
BX1Z0.2	-49°	233°	BX1Z3.2
BX1Z0.3	+12°	157°	TAB.4
BX1Z0.4	-12°	338°	B0C.1


Joint BX1Z1 ↓ BOTTOM

HERE	BEND	ROT	THERE
BX1Z1.1	-68°	206°	BX2Z2.4
BX1Z1.2	-30°	274°	BX1Z4.2
BX1Z1.3	+12°	163°	BX3Z4.3
BX1Z1.4	-30°	005°	BX2Z4.1



AX1Z0:AX1Z1

Strut · 1989 mm





Joint AX1Z0 ↑ TOP

HERE	BEND	ROT	THERE
AX1Z0.1	-68°	144°	BAA.4
AX1Z0.2	-49°	233°	AX1Z3.2
AX1Z0.3	+12°	157°	TAA.4
AX1Z0.4	-12°	338°	BOB.1


Joint AX1Z1 ↓ BOTTOM

HERE	BEND	ROT	THERE
AX1Z1.1	-68°	206°	AX2Z2.4
AX1Z1.2	-30°	274°	AX1Z4.2
AX1Z1.3	+12°	163°	AX3Z4.3
AX1Z1.4	-30°	005°	AX2Z4.1



CX1Z0 : CX1Z1

Strut · 1989 mm





Joint CX1Z0 ↑ TOP

HERE	BEND	ROT	THERE
CX1Z0.1	-68°	144°	BAC.4
CX1Z0.2	-49°	233°	CX1Z3.2
CX1Z0.3	+12°	157°	TAC.4
CX1Z0.4	-12°	338°	BOA.1


Joint CX1Z1 ↓ BOTTOM

HERE	BEND	ROT	THERE
CX1Z1.1	-68°	206°	CX2Z2.4
CX1Z1.2	-30°	274°	CX1Z4.2
CX1Z1.3	+12°	163°	CX3Z4.3
CX1Z1.4	-30°	005°	CX2Z4.1



BX3Z4 : BX3Z5

Strut · 1996 mm





Joint BX3Z4 ↑ TOP

HERE	BEND	ROT	THERE
BX3Z4.1	-49°	067°	BX2Z1.2
BX3Z4.2	-30°	258°	BX2Z5.1
BX3Z4.3	+30°	029°	BX1Z1.3
BX3Z4.4	-49°	166°	BX3Z1.2


Joint BX3Z5 ↓ BOTTOM

HERE	BEND	ROT	THERE
BX3Z5.1	-49°	339°	BX3Z2.4
BX3Z5.2	-49°	281°	BX4Z4.2
BX3Z5.3	+12°	209°	BX4Z1.1
BX3Z5.4	-30°	069°	BX4Z0.1



AX3Z4 : AX3Z5

Strut · 1996 mm





Joint AX3Z4 ↑ TOP

HERE	BEND	ROT	THERE
AX3Z4.1	-49°	067°	AX2Z1.2
AX3Z4.2	-30°	258°	AX2Z5.1
AX3Z4.3	+30°	029°	AX1Z1.3
AX3Z4.4	-49°	166°	AX3Z1.2


Joint AX3Z5 ↓ BOTTOM

HERE	BEND	ROT	THERE
AX3Z5.1	-49°	339°	AX3Z2.4
AX3Z5.2	-49°	281°	AX4Z4.2
AX3Z5.3	+12°	209°	AX4Z1.1
AX3Z5.4	-30°	069°	AX4Z0.1



CX3Z4 : CX3Z5

Strut · 1996 mm





Joint CX3Z4 ↑ TOP

HERE	BEND	ROT	THERE
CX3Z4.1	-49°	067°	CX2Z1.2
CX3Z4.2	-30°	258°	CX2Z5.1
CX3Z4.3	+30°	029°	CX1Z1.3
CX3Z4.4	-49°	166°	CX3Z1.2


Joint CX3Z5 ↓ BOTTOM

HERE	BEND	ROT	THERE
CX3Z5.1	-49°	339°	CX3Z2.4
CX3Z5.2	-49°	281°	CX4Z4.2
CX3Z5.3	+12°	209°	CX4Z1.1
CX3Z5.4	-30°	069°	CX4Z0.1



AX2Z4:AX2Z5

Strut · 2005 mm





Joint AX2Z4 ↑ TOP

HERE	BEND	ROT	THERE
AX2Z4.1	-68°	212°	AX1Z1.4
AX2Z4.2	-12°	039°	AX1Z5.1
AX2Z4.3	+30°	271°	TAC.3
AX2Z4.4	-49°	141°	AX2Z1.4


Joint AX2Z5 ↓ BOTTOM

HERE	BEND	ROT	THERE
AX2Z5.1	-68°	156°	AX3Z4.2
AX2Z5.2	-49°	066°	AX2Z2.2
AX2Z5.3	+12°	188°	AX4Z2.3
AX2Z5.4	-30°	334°	AX3Z0.1



BX2Z4 : BX2Z5

Strut · 2005 mm




Joint BX2Z4 ↑ TOP

HERE	BEND	ROT	THERE
BX2Z4.1	-68°	212°	BX1Z1.4
BX2Z4.2	-12°	039°	BX1Z5.1
BX2Z4.3	+30°	271°	TAA.3
BX2Z4.4	-49°	141°	BX2Z1.4


Joint BX2Z5 ↓ BOTTOM

HERE	BEND	ROT	THERE
BX2Z5.1	-68°	156°	BX3Z4.2
BX2Z5.2	-49°	066°	BX2Z2.2
BX2Z5.3	+12°	188°	BX4Z2.3
BX2Z5.4	-30°	334°	BX3Z0.1

Joint BX2Z4




Joint BX2Z5



CX2Z4 : CX2Z5

Strut · 2005 mm





Joint CX2Z4 ↑ TOP

HERE	BEND	ROT	THERE
CX2Z4.1	-68°	212°	CX1Z1.4
CX2Z4.2	-12°	039°	CX1Z5.1
CX2Z4.3	+30°	271°	TAB.3
CX2Z4.4	-49°	141°	CX2Z1.4


Joint CX2Z5 ↓ BOTTOM

HERE	BEND	ROT	THERE
CX2Z5.1	-68°	156°	CX3Z4.2
CX2Z5.2	-49°	066°	CX2Z2.2
CX2Z5.3	+12°	188°	CX4Z2.3
CX2Z5.4	-30°	334°	CX3Z0.1



AX3Z2 : AX3Z3

Strut · 2006 mm





Joint AX3Z2 ↑ TOP

HERE	BEND	ROT	THERE
AX3Z2.1	-49°	028°	AX2Z3.2
AX3Z2.2	-30°	237°	AX2Z1.1
AX3Z2.3	+30°	333°	AX1Z5.3
AX3Z2.4	-68°	132°	AX3Z5.1


Joint AX3Z3 ↓ BOTTOM

HERE	BEND	ROT	THERE
AX3Z3.1	-49°	309°	AX4Z0.2
AX3Z3.2	-49°	016°	AX3Z0.4
AX3Z3.3	+30°	240°	AX4Z3.1
AX3Z3.4	-30°	094°	AX4Z2.1



BX3Z2 : BX3Z3

Strut · 2006 mm





Joint BX3Z2 ↑ TOP

HERE	BEND	ROT	THERE
BX3Z2.1	-49°	028°	BX2Z3.2
BX3Z2.2	-30°	237°	BX2Z1.1
BX3Z2.3	+30°	333°	BX1Z5.3
BX3Z2.4	-68°	132°	BX3Z5.1


Joint BX3Z3 ↓ BOTTOM

HERE	BEND	ROT	THERE
BX3Z3.1	-49°	309°	BX4Z0.2
BX3Z3.2	-49°	016°	BX3Z0.4
BX3Z3.3	+30°	240°	BX4Z3.1
BX3Z3.4	-30°	094°	BX4Z2.1



CX3Z2 : CX3Z3

Strut · 2006 mm





Joint CX3Z2 ↑ TOP

HERE	BEND	ROT	THERE
CX3Z2.1	-49°	028°	CX2Z3.2
CX3Z2.2	-30°	237°	CX2Z1.1
CX3Z2.3	+30°	333°	CX1Z5.3
CX3Z2.4	-68°	132°	CX3Z5.1


Joint CX3Z3 ↓ BOTTOM

HERE	BEND	ROT	THERE
CX3Z3.1	-49°	309°	CX4Z0.2
CX3Z3.2	-49°	016°	CX3Z0.4
CX3Z3.3	+30°	240°	CX4Z3.1
CX3Z3.4	-30°	094°	CX4Z2.1



AX2Z2 : AX2Z3

Strut · 2025 mm





Joint AX2Z2 ↑ TOP

HERE	BEND	ROT	THERE
AX2Z2.1	-68°	273°	AX1Z3.4
AX2Z2.2	-49°	191°	AX2Z5.2
AX2Z2.3	+30°	312°	BAA.3
AX2Z2.4	-30°	109°	AX1Z1.1


Joint AX2Z3 ↓ BOTTOM

HERE	BEND	ROT	THERE
AX2Z3.1	-49°	111°	AX3Z0.2
AX2Z3.2	-12°	273°	AX3Z2.1
AX2Z3.3	+12°	154°	AX4Z0.3
AX2Z3.4	-49°	023°	AX2Z0.4



BX2Z2 : BX2Z3

Strut · 2025 mm




Joint BX2Z2 ↑ TOP

HERE	BEND	ROT	THERE
BX2Z2.1	-68°	273°	BX1Z3.4
BX2Z2.2	-49°	191°	BX2Z5.2
BX2Z2.3	+30°	312°	BAB.3
BX2Z2.4	-30°	109°	BX1Z1.1


Joint BX2Z3 ↓ BOTTOM

HERE	BEND	ROT	THERE
BX2Z3.1	-49°	111°	BX3Z0.2
BX2Z3.2	-12°	273°	BX3Z2.1
BX2Z3.3	+12°	154°	BX4Z0.3
BX2Z3.4	-49°	023°	BX2Z0.4

Joint BX2Z2




Joint BX2Z3



CX2Z2 : CX2Z3

Strut · 2025 mm




Joint CX2Z2 ↑ TOP

HERE	BEND	ROT	THERE
CX2Z2.1	-68°	273°	CX1Z3.4
CX2Z2.2	-49°	191°	CX2Z5.2
CX2Z2.3	+30°	312°	BAC.3
CX2Z2.4	-30°	109°	CX1Z1.1


Joint CX2Z3 ↓ BOTTOM

HERE	BEND	ROT	THERE
CX2Z3.1	-49°	111°	CX3Z0.2
CX2Z3.2	-12°	272°	CX3Z2.1
CX2Z3.3	+12°	154°	CX4Z0.3
CX2Z3.4	-49°	023°	CX2Z0.4

Joint CX2Z2




Joint CX2Z3



AX1Z4:AX1Z5

Strut · 2032 mm





Joint AX1Z4 ↓ BOTTOM

HERE	BEND	ROT	THERE
AX1Z4.1	-49°	050°	TAC.2
AX1Z4.2	-49°	165°	AX1Z1.2
AX1Z4.3	+30°	101°	BAC.2
AX1Z4.4	-30°	254°	BAA.1


Joint AX1Z5 ↑ TOP

HERE	BEND	ROT	THERE
AX1Z5.1	-49°	262°	AX2Z4.2
AX1Z5.2	-12°	092°	AX2Z0.1
AX1Z5.3	+12°	200°	AX3Z2.3
AX1Z5.4	-49°	354°	AX1Z2.2



CX1Z4 : CX1Z5

Strut · 2032 mm





Joint CX1Z4 ↓ BOTTOM

HERE	BEND	ROT	THERE
CX1Z4.1	-49°	050°	TAB.2
CX1Z4.2	-49°	165°	CX1Z1.2
CX1Z4.3	+30°	101°	BAB.2
CX1Z4.4	-30°	254°	BAC.1


Joint CX1Z5 ↑ TOP

HERE	BEND	ROT	THERE
CX1Z5.1	-49°	262°	CX2Z4.2
CX1Z5.2	-12°	092°	CX2Z0.1
CX1Z5.3	+12°	200°	CX3Z2.3
CX1Z5.4	-49°	354°	CX1Z2.2



BX1Z4 : BX1Z5

Strut · 2032 mm





Joint BX1Z4 ↓ BOTTOM

HERE	BEND	ROT	THERE
BX1Z4.1	-49°	050°	TAA.2
BX1Z4.2	-49°	165°	BX1Z1.2
BX1Z4.3	+30°	101°	BAA.2
BX1Z4.4	-30°	254°	BAB.1


Joint BX1Z5 ↑ TOP

HERE	BEND	ROT	THERE
BX1Z5.1	-49°	262°	BX2Z4.2
BX1Z5.2	-12°	092°	BX2Z0.1
BX1Z5.3	+12°	200°	BX3Z2.3
BX1Z5.4	-49°	354°	BX1Z2.2



AX2Z0 : AX2Z1

Strut · 2040 mm





Joint AX2Z0 ↑ **TOP**

HERE	BEND	ROT	THERE
AX2Z0.1	-49°	350°	AX1Z5.2
AX2Z0.2	-30°	154°	AX1Z3.1
AX2Z0.3	+30°	039°	B0B.4
AX2Z0.4	-49°	247°	AX2Z3.4


Joint AX2Z1 ↓ **BOTTOM**

HERE	BEND	ROT	THERE
AX2Z1.1	-30°	070°	AX3Z2.2
AX2Z1.2	-30°	238°	AX3Z4.1
AX2Z1.3	+12°	117°	AX4Z4.3
AX2Z1.4	-49°	324°	AX2Z4.4



BX2Z0 : BX2Z1

Strut · 2040 mm





Joint BX2Z0 ↑ TOP

HERE	BEND	ROT	THERE
BX2Z0.1	-49°	350°	BX1Z5.2
BX2Z0.2	-30°	154°	BX1Z3.1
BX2Z0.3	+30°	039°	B0C.4
BX2Z0.4	-49°	247°	BX2Z3.4


Joint BX2Z1 ↓ BOTTOM

HERE	BEND	ROT	THERE
BX2Z1.1	-30°	070°	BX3Z2.2
BX2Z1.2	-30°	238°	BX3Z4.1
BX2Z1.3	+12°	117°	BX4Z4.3
BX2Z1.4	-49°	324°	BX2Z4.4



CX2Z0 : CX2Z1

Strut · 2040 mm





Joint CX2Z0 ↑ TOP

HERE	BEND	ROT	THERE
CX2Z0.1	-49°	350°	CX1Z5.2
CX2Z0.2	-30°	153°	CX1Z3.1
CX2Z0.3	+30°	039°	B0A.4
CX2Z0.4	-49°	247°	CX2Z3.4


Joint CX2Z1 ↓ BOTTOM

HERE	BEND	ROT	THERE
CX2Z1.1	-30°	070°	CX3Z2.2
CX2Z1.2	-30°	238°	CX3Z4.1
CX2Z1.3	+12°	117°	CX4Z4.3
CX2Z1.4	-49°	324°	CX2Z4.4



AX1Z2 : AX1Z3

Strut · 2049 mm





Joint AX1Z2 ↑ TOP

HERE	BEND	ROT	THERE
AX1Z2.1	-30°	353°	B0B.2
AX1Z2.2	-49°	085°	AX1Z5.4
AX1Z2.3	+49°	336°	T0B.4
AX1Z2.4	-12°	185°	TAC.1


Joint AX1Z3 ↓ BOTTOM

HERE	BEND	ROT	THERE
AX1Z3.1	-49°	329°	AX2Z0.2
AX1Z3.2	-49°	058°	AX1Z0.2
AX1Z3.3	+49°	280°	AX3Z0.3
AX1Z3.4	-30°	142°	AX2Z2.1



BX1Z2 : BX1Z3

Strut · 2049 mm





Joint BX1Z2 ↑ TOP

HERE	BEND	ROT	THERE
BX1Z2.1	-30°	353°	B0C.2
BX1Z2.2	-49°	085°	BX1Z5.4
BX1Z2.3	+49°	336°	T0C.4
BX1Z2.4	-12°	185°	TAA.1


Joint BX1Z3 ↓ BOTTOM

HERE	BEND	ROT	THERE
BX1Z3.1	-49°	329°	BX2Z0.2
BX1Z3.2	-49°	058°	BX1Z0.2
BX1Z3.3	+49°	280°	BX3Z0.3
BX1Z3.4	-30°	142°	BX2Z2.1



CX1Z2 : CX1Z3

Strut · 2049 mm





Joint CX1Z2 ↑ TOP

HERE	BEND	ROT	THERE
CX1Z2.1	-30°	353°	B0A.2
CX1Z2.2	-49°	085°	CX1Z5.4
CX1Z2.3	+49°	336°	T0A.4
CX1Z2.4	-12°	185°	TAB.1


Joint CX1Z3 ↓ BOTTOM

HERE	BEND	ROT	THERE
CX1Z3.1	-49°	329°	CX2Z0.2
CX1Z3.2	-49°	058°	CX1Z0.2
CX1Z3.3	+49°	280°	CX3Z0.3
CX1Z3.4	-30°	142°	CX2Z2.1



BAC : BOC

Strut · 2353 mm





Joint BAC ↓ **BOTTOM**

HERE	BEND	ROT	THERE
BAC.1	-68°	178°	CX1Z4.4
BAC.2	-49°	097°	AX1Z4.3
BAC.3	+12°	231°	CX2Z2.3
BAC.4	-12°	007°	CX1Z0.1


Joint BOC ↑ **TOP**

HERE	BEND	ROT	THERE
BOC.1	-68°	109°	BX1Z0.4
BOC.2	-30°	279°	BX1Z2.1
BOC.3	-30°	022°	T0A.2
BOC.4	-12°	169°	BX2Z0.3



BAB : BOB

Strut · 2353 mm





Joint BAB ↓ **BOTTOM**

HERE	BEND	ROT	THERE
BAB.1	-68°	178°	BX1Z4.4
BAB.2	-49°	097°	CX1Z4.3
BAB.3	+12°	231°	BX2Z2.3
BAB.4	-12°	007°	BX1Z0.1


Joint BOB ↑ **TOP**

HERE	BEND	ROT	THERE
BOB.1	-68°	109°	AX1Z0.4
BOB.2	-30°	279°	AX1Z2.1
BOB.3	-30°	022°	T0C.2
BOB.4	-12°	169°	AX2Z0.3



BAA : B0A

Strut · 2353 mm





Joint BAA ↓ **BOTTOM**

HERE	BEND	ROT	THERE
BAA.1	-68°	178°	AX1Z4.4
BAA.2	-49°	097°	BX1Z4.3
BAA.3	+12°	231°	AX2Z2.3
BAA.4	-12°	007°	AX1Z0.1


Joint B0A ↑ **TOP**

HERE	BEND	ROT	THERE
B0A.1	-68°	109°	CX1Z0.4
B0A.2	-30°	279°	CX1Z2.1
B0A.3	-30°	022°	T0B.2
B0A.4	-12°	169°	CX2Z0.3



TAC:TOC

Strut · 2404 mm





Joint TAC ↓ **BOTTOM**

HERE	BEND	ROT	THERE
TAC.1	-49°	049°	AX1Z2.4
TAC.2	-12°	203°	AX1Z4.1
TAC.3	+30°	098°	AX2Z4.3
TAC.4	-30°	293°	CX1Z0.3


Joint TOC ↑ **TOP**

HERE	BEND	ROT	THERE
TOC.1	-68°	082°	YZ0.3
TOC.2	-49°	272°	B0B.3
TOC.3	+12°	012°	YZ1.1
TOC.4	-30°	179°	BX1Z2.3



TAA:T0A

Strut · 2404 mm





Joint TAA ↓ BOTTOM

HERE	BEND	ROT	THERE
TAA.1	-49°	049°	BX1Z2.4
TAA.2	-12°	203°	BX1Z4.1
TAA.3	+30°	098°	BX2Z4.3
TAA.4	-30°	293°	AX1Z0.3


Joint T0A ↑ TOP

HERE	BEND	ROT	THERE
T0A.1	-68°	082°	YZ0.2
T0A.2	-49°	272°	B0C.3
T0A.3	+12°	012°	YZ1.2
T0A.4	-30°	179°	CX1Z2.3



TAB:TOB

Strut · 2404 mm



Joint TAB ↓ **BOTTOM**

HERE	BEND	ROT	THERE
TAB.1	-49°	049°	CX1Z2.4
TAB.2	-12°	203°	CX1Z4.1
TAB.3	+30°	098°	CX2Z4.3
TAB.4	-30°	293°	BX1Z0.3

Joint TOB ↑ **TOP**

HERE	BEND	ROT	THERE
TOB.1	-68°	082°	YZ0.1
TOB.2	-49°	272°	B0A.3
TOB.3	+12°	012°	YZ1.3
TOB.4	-30°	179°	AX1Z2.3

