


# AX4YZ0 ↔ AX4YZ1

Vertical bottom strut · Leg A · 1792 mm





Joint AX4YZ0 ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -30° | 184° | AX4Z5 s1    |
| 2    | -30° | 306° | AX4Z3 s2    |
| 3    | -30° | 071° | AX4Z1 s2    |


Joint AX4YZ1 ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 289° | AX4Z1 s3    |
| 2    | -49° | 054° | AX4Z3 s3    |
| 3    | -49° | 176° | AX4Z5 s3    |



# AX4Z2 ↔ AX4Z3

Leg A · **twist 4** (with AX4Z0↔AX4Z1, AX4Z4↔AX4Z5) · 1912 mm





Joint AX4Z2 ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 301° | AX3Z3 s4    |
| 2    | -49° | 173° | AX4Z5 s4    |
| 3    | +12° | 320° | AX2Z5 s3    |
| 4    | -30° | 115° | AX3Z1 s1    |


Joint AX4Z3 ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 059° | AX3Z3 s3    |
| 2    | -68° | 266° | AX4YZ0 s2   |
| 3    | +12° | 204° | AX4YZ1 s2   |
| 4    | -49° | 006° | AX4Z0 s4    |



# AX4Z4 ↔ AX4Z5

Leg A · **twist 4** (with AX4Z0↔AX4Z1, AX4Z2↔AX4Z3) · 1918 mm





## Joint AX4Z4 ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 277° | AX3Z1 s4    |
| 2    | -30° | 094° | AX3Z5 s2    |
| 3    | +12° | 311° | AX2Z1 s3    |
| 4    | -49° | 161° | AX4Z1 s4    |


## Joint AX4Z5 ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 283° | AX4YZ0 s1   |
| 2    | -68° | 083° | AX3Z1 s3    |
| 3    | +12° | 217° | AX4YZ1 s3   |
| 4    | -49° | 017° | AX4Z2 s2    |



# AX4Z0 ↔ AX4Z1

Leg A · **twist 4** (with AX4Z2↔AX4Z3, AX4Z4↔AX4Z5) · 1953 mm





Joint AX4Z0    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 325° | AX3Z5 s4    |
| 2    | -30° | 135° | AX3Z3 s1    |
| 3    | +12° | 008° | AX2Z3 s3    |
| 4    | -49° | 199° | AX4Z3 s4    |


Joint AX4Z1    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 035° | AX3Z5 s3    |
| 2    | -68° | 241° | AX4YZ0 s3   |
| 3    | +12° | 174° | AX4YZ1 s1   |
| 4    | -49° | 339° | AX4Z4 s4    |



# AX3Z0 ↔ AX3Z1

Leg A · **twist 3** (with AX3Z2↔AX3Z3, AX3Z4↔AX3Z5) · 1983 mm





## Joint AX3Z0    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 112° | AX2Z5 s4    |
| 2    | -12° | 304° | AX2Z3 s1    |
| 3    | +12° | 068° | AX1Z3 s3    |
| 4    | -49° | 203° | AX3Z3 s2    |


## Joint AX3Z1    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 253° | AX4Z2 s4    |
| 2    | -49° | 308° | AX3Z4 s4    |
| 3    | +12° | 186° | AX4Z5 s2    |
| 4    | -30° | 036° | AX4Z4 s1    |



# AX1Z0 ↔ AX1Z1

Leg A · **twist 1** (with AX1Z2↔AX1Z3, AX1Z4↔AX1Z5) · 1989 mm





Joint AX1Z0    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 144° | BAA s4      |
| 2    | -49° | 233° | AX1Z3 s2    |
| 3    | +12° | 157° | TAA s4      |
| 4    | -12° | 338° | BOB s1      |


Joint AX1Z1    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 206° | AX2Z2 s4    |
| 2    | -30° | 274° | AX1Z4 s2    |
| 3    | +12° | 163° | AX3Z4 s3    |
| 4    | -30° | 005° | AX2Z4 s1    |



# AX3Z4 ↔ AX3Z5

Leg A · **twist 3** (with AX3Z0↔AX3Z1, AX3Z2↔AX3Z3) · 1996 mm





## Joint AX3Z4 ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 067° | AX2Z1 s2    |
| 2    | -30° | 258° | AX2Z5 s1    |
| 3    | +30° | 029° | AX1Z1 s3    |
| 4    | -49° | 166° | AX3Z1 s2    |


## Joint AX3Z5 ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 339° | AX3Z2 s4    |
| 2    | -49° | 281° | AX4Z4 s2    |
| 3    | +12° | 209° | AX4Z1 s1    |
| 4    | -30° | 069° | AX4Z0 s1    |



# AX2Z4 ↔ AX2Z5

Leg A · **twist 2** (with AX2Z0↔AX2Z1, AX2Z2↔AX2Z3) · 2005 mm





## Joint AX2Z4 ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 212° | AX1Z1 s4    |
| 2    | -12° | 039° | AX1Z5 s1    |
| 3    | +30° | 271° | TAC s3      |
| 4    | -49° | 141° | AX2Z1 s4    |

## Joint AX2Z5 ↓ BOTTOM


| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 156° | AX3Z4 s2    |
| 2    | -49° | 066° | AX2Z2 s2    |
| 3    | +12° | 188° | AX4Z2 s3    |
| 4    | -30° | 334° | AX3Z0 s1    |





# AX3Z2 ↔ AX3Z3

Leg A · **twist 3** (with AX3Z0↔AX3Z1, AX3Z4↔AX3Z5) · 2006 mm





Joint AX3Z2    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 028° | AX2Z3 s2    |
| 2    | -30° | 237° | AX2Z1 s1    |
| 3    | +30° | 333° | AX1Z5 s3    |
| 4    | -68° | 132° | AX3Z5 s1    |


Joint AX3Z3    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 309° | AX4Z0 s2    |
| 2    | -49° | 016° | AX3Z0 s4    |
| 3    | +30° | 240° | AX4Z3 s1    |
| 4    | -30° | 094° | AX4Z2 s1    |



# AX2Z2 ↔ AX2Z3

Leg A · **twist 2** (with AX2Z0↔AX2Z1, AX2Z4↔AX2Z5) · 2025 mm





Joint AX2Z2    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 273° | AX1Z3 s4    |
| 2    | -49° | 191° | AX2Z5 s2    |
| 3    | +30° | 312° | BAA s3      |
| 4    | -30° | 109° | AX1Z1 s1    |


Joint AX2Z3    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 111° | AX3Z0 s2    |
| 2    | -12° | 273° | AX3Z2 s1    |
| 3    | +12° | 154° | AX4Z0 s3    |
| 4    | -49° | 023° | AX2Z0 s4    |



# AX1Z4 ↔ AX1Z5

Leg A · **twist 1** (with AX1Z0↔AX1Z1, AX1Z2↔AX1Z3) · 2032 mm





## Joint AX1Z4 ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 050° | TAC s2      |
| 2    | -49° | 165° | AX1Z1 s2    |
| 3    | +30° | 101° | BAC s2      |
| 4    | -30° | 254° | BAA s1      |


## Joint AX1Z5 ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 262° | AX2Z4 s2    |
| 2    | -12° | 092° | AX2Z0 s1    |
| 3    | +12° | 200° | AX3Z2 s3    |
| 4    | -49° | 354° | AX1Z2 s2    |



# AX2Z0 ↔ AX2Z1

Leg A · **twist 2** (with AX2Z2↔AX2Z3, AX2Z4↔AX2Z5) · 2040 mm





Joint AX2Z0    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 350° | AX1Z5 s2    |
| 2    | -30° | 154° | AX1Z3 s1    |
| 3    | +30° | 039° | B0B s4      |
| 4    | -49° | 247° | AX2Z3 s4    |

Joint AX2Z1    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -30° | 070° | AX3Z2 s2    |
| 2    | -30° | 238° | AX3Z4 s1    |
| 3    | +12° | 117° | AX4Z4 s3    |
| 4    | -49° | 324° | AX2Z4 s4    |



# AX1Z2 ↔ AX1Z3

Leg A · **twist 1** (with AX1Z0↔AX1Z1, AX1Z4↔AX1Z5) · 2049 mm





## Joint AX1Z2 ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -30° | 353° | B0B s2      |
| 2    | -49° | 085° | AX1Z5 s4    |
| 3    | +49° | 336° | T0B s4      |
| 4    | -12° | 185° | TAC s1      |


## Joint AX1Z3 ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 329° | AX2Z0 s2    |
| 2    | -49° | 058° | AX1Z0 s2    |
| 3    | +49° | 280° | AX3Z0 s3    |
| 4    | -30° | 142° | AX2Z2 s1    |



# BX4YZ0 ↔ BX4YZ1

Vertical bottom strut · Leg B · 1792 mm





Joint BX4YZ0    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -30° | 184° | BX4Z5 s1    |
| 2    | -30° | 306° | BX4Z3 s2    |
| 3    | -30° | 071° | BX4Z1 s2    |


Joint BX4YZ1    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 289° | BX4Z1 s3    |
| 2    | -49° | 054° | BX4Z3 s3    |
| 3    | -49° | 176° | BX4Z5 s3    |



# BX4Z2 ↔ BX4Z3

Leg B · **twist 4** (with BX4Z0↔BX4Z1, BX4Z4↔BX4Z5) · 1912 mm





Joint BX4Z2    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 301° | BX3Z3 s4    |
| 2    | -49° | 173° | BX4Z5 s4    |
| 3    | +12° | 320° | BX2Z5 s3    |
| 4    | -30° | 115° | BX3Z1 s1    |


Joint BX4Z3    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 059° | BX3Z3 s3    |
| 2    | -68° | 266° | BX4YZ0 s2   |
| 3    | +12° | 204° | BX4YZ1 s2   |
| 4    | -49° | 006° | BX4Z0 s4    |



# BX4Z4 ↔ BX4Z5

Leg B · **twist 4** (with BX4Z0↔BX4Z1, BX4Z2↔BX4Z3) · 1918 mm





Joint BX4Z4    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 277° | BX3Z1 s4    |
| 2    | -30° | 094° | BX3Z5 s2    |
| 3    | +12° | 311° | BX2Z1 s3    |
| 4    | -49° | 161° | BX4Z1 s4    |

Joint BX4Z5    ↓ BOTTOM


| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 283° | BX4YZ0 s1   |
| 2    | -68° | 083° | BX3Z1 s3    |
| 3    | +12° | 217° | BX4YZ1 s3   |
| 4    | -49° | 017° | BX4Z2 s2    |





# BX4Z0 ↔ BX4Z1

Leg B · **twist 4** (with BX4Z2↔BX4Z3, BX4Z4↔BX4Z5) · 1953 mm





Joint BX4Z0    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 325° | BX3Z5 s4    |
| 2    | -30° | 135° | BX3Z3 s1    |
| 3    | +12° | 008° | BX2Z3 s3    |
| 4    | -49° | 199° | BX4Z3 s4    |


Joint BX4Z1    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 035° | BX3Z5 s3    |
| 2    | -68° | 241° | BX4YZ0 s3   |
| 3    | +12° | 174° | BX4YZ1 s1   |
| 4    | -49° | 339° | BX4Z4 s4    |



# BX3Z0 ↔ BX3Z1

Leg B · **twist 3** (with BX3Z2↔BX3Z3, BX3Z4↔BX3Z5) · 1983 mm





Joint BX3Z0    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 112° | BX2Z5 s4    |
| 2    | -12° | 304° | BX2Z3 s1    |
| 3    | +12° | 068° | BX1Z3 s3    |
| 4    | -49° | 203° | BX3Z3 s2    |


Joint BX3Z1    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 253° | BX4Z2 s4    |
| 2    | -49° | 308° | BX3Z4 s4    |
| 3    | +12° | 186° | BX4Z5 s2    |
| 4    | -30° | 036° | BX4Z4 s1    |



# BX1Z0 ↔ BX1Z1

Leg B · **twist 1** (with BX1Z2↔BX1Z3, BX1Z4↔BX1Z5) · 1989 mm





Joint BX1Z0    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 144° | BAB s4      |
| 2    | -49° | 233° | BX1Z3 s2    |
| 3    | +12° | 157° | TAB s4      |
| 4    | -12° | 338° | BOC s1      |


Joint BX1Z1    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 206° | BX2Z2 s4    |
| 2    | -30° | 274° | BX1Z4 s2    |
| 3    | +12° | 163° | BX3Z4 s3    |
| 4    | -30° | 005° | BX2Z4 s1    |



# BX3Z4 ↔ BX3Z5

Leg B · **twist 3** (with BX3Z0↔BX3Z1, BX3Z2↔BX3Z3) · 1996 mm





## Joint BX3Z4 ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 067° | BX2Z1 s2    |
| 2    | -30° | 258° | BX2Z5 s1    |
| 3    | +30° | 029° | BX1Z1 s3    |
| 4    | -49° | 166° | BX3Z1 s2    |


## Joint BX3Z5 ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 339° | BX3Z2 s4    |
| 2    | -49° | 281° | BX4Z4 s2    |
| 3    | +12° | 209° | BX4Z1 s1    |
| 4    | -30° | 069° | BX4Z0 s1    |



# BX2Z4 ↔ BX2Z5

Leg B · **twist 2** (with BX2Z0↔BX2Z1, BX2Z2↔BX2Z3) · 2005 mm





## Joint BX2Z4 ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 212° | BX1Z1 s4    |
| 2    | -12° | 039° | BX1Z5 s1    |
| 3    | +30° | 271° | TAA s3      |
| 4    | -49° | 141° | BX2Z1 s4    |


## Joint BX2Z5 ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 156° | BX3Z4 s2    |
| 2    | -49° | 066° | BX2Z2 s2    |
| 3    | +12° | 188° | BX4Z2 s3    |
| 4    | -30° | 334° | BX3Z0 s1    |



# BX3Z2 ↔ BX3Z3

Leg B · **twist 3** (with BX3Z0↔BX3Z1, BX3Z4↔BX3Z5) · 2006 mm





Joint BX3Z2    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 028° | BX2Z3 s2    |
| 2    | -30° | 237° | BX2Z1 s1    |
| 3    | +30° | 333° | BX1Z5 s3    |
| 4    | -68° | 132° | BX3Z5 s1    |


Joint BX3Z3    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 309° | BX4Z0 s2    |
| 2    | -49° | 016° | BX3Z0 s4    |
| 3    | +30° | 240° | BX4Z3 s1    |
| 4    | -30° | 094° | BX4Z2 s1    |



# BX2Z2 ↔ BX2Z3

Leg B · **twist 2** (with BX2Z0↔BX2Z1, BX2Z4↔BX2Z5) · 2025 mm





Joint BX2Z2    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 273° | BX1Z3 s4    |
| 2    | -49° | 191° | BX2Z5 s2    |
| 3    | +30° | 312° | BAB s3      |
| 4    | -30° | 109° | BX1Z1 s1    |


Joint BX2Z3    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 111° | BX3Z0 s2    |
| 2    | -12° | 273° | BX3Z2 s1    |
| 3    | +12° | 154° | BX4Z0 s3    |
| 4    | -49° | 023° | BX2Z0 s4    |



# BX1Z4 ↔ BX1Z5

Leg B · **twist 1** (with BX1Z0↔BX1Z1, BX1Z2↔BX1Z3) · 2032 mm





## Joint BX1Z4 ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 050° | TAA s2      |
| 2    | -49° | 165° | BX1Z1 s2    |
| 3    | +30° | 101° | BAA s2      |
| 4    | -30° | 254° | BAB s1      |

## Joint BX1Z5 ↑ TOP


| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 262° | BX2Z4 s2    |
| 2    | -12° | 092° | BX2Z0 s1    |
| 3    | +12° | 200° | BX3Z2 s3    |
| 4    | -49° | 354° | BX1Z2 s2    |





# BX2Z0 ↔ BX2Z1

Leg B · **twist 2** (with BX2Z2↔BX2Z3, BX2Z4↔BX2Z5) · 2040 mm





Joint **BX2Z0**    **↑ TOP**

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 350° | BX1Z5 s2    |
| 2    | -30° | 154° | BX1Z3 s1    |
| 3    | +30° | 039° | B0C s4      |
| 4    | -49° | 247° | BX2Z3 s4    |

Joint **BX2Z1**    **↓ BOTTOM**

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -30° | 070° | BX3Z2 s2    |
| 2    | -30° | 238° | BX3Z4 s1    |
| 3    | +12° | 117° | BX4Z4 s3    |
| 4    | -49° | 324° | BX2Z4 s4    |



# BX1Z2 ↔ BX1Z3

Leg B · **twist 1** (with BX1Z0↔BX1Z1, BX1Z4↔BX1Z5) · 2049 mm





Joint BX1Z2    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -30° | 353° | B0C s2      |
| 2    | -49° | 085° | BX1Z5 s4    |
| 3    | +49° | 336° | T0C s4      |
| 4    | -12° | 185° | TAA s1      |


Joint BX1Z3    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 329° | BX2Z0 s2    |
| 2    | -49° | 058° | BX1Z0 s2    |
| 3    | +49° | 280° | BX3Z0 s3    |
| 4    | -30° | 142° | BX2Z2 s1    |



# CX4YZ0 ↔ CX4YZ1

Vertical bottom strut · Leg C · 1792 mm





Joint CX4YZ0    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -30° | 184° | CX4Z5 s1    |
| 2    | -30° | 306° | CX4Z3 s2    |
| 3    | -30° | 071° | CX4Z1 s2    |


Joint CX4YZ1    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 289° | CX4Z1 s3    |
| 2    | -49° | 054° | CX4Z3 s3    |
| 3    | -49° | 176° | CX4Z5 s3    |



# CX4Z2 ↔ CX4Z3

Leg C · **twist 4** (with CX4Z0↔CX4Z1, CX4Z4↔CX4Z5) · 1912 mm





Joint CX4Z2    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 301° | CX3Z3 s4    |
| 2    | -49° | 173° | CX4Z5 s4    |
| 3    | +12° | 320° | CX2Z5 s3    |
| 4    | -30° | 115° | CX3Z1 s1    |


Joint CX4Z3    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 059° | CX3Z3 s3    |
| 2    | -68° | 266° | CX4YZ0 s2   |
| 3    | +12° | 204° | CX4YZ1 s2   |
| 4    | -49° | 006° | CX4Z0 s4    |



# CX4Z4 ↔ CX4Z5

Leg C · **twist 4** (with CX4Z0↔CX4Z1, CX4Z2↔CX4Z3) · 1918 mm





Joint CX4Z4    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 277° | CX3Z1 s4    |
| 2    | -30° | 094° | CX3Z5 s2    |
| 3    | +12° | 311° | CX2Z1 s3    |
| 4    | -49° | 161° | CX4Z1 s4    |


Joint CX4Z5    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 283° | CX4YZ0 s1   |
| 2    | -68° | 083° | CX3Z1 s3    |
| 3    | +12° | 217° | CX4YZ1 s3   |
| 4    | -49° | 017° | CX4Z2 s2    |



# CX4Z0 ↔ CX4Z1

Leg C · **twist 4** (with CX4Z2↔CX4Z3, CX4Z4↔CX4Z5) · 1953 mm





Joint CX4Z0 ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 325° | CX3Z5 s4    |
| 2    | -30° | 135° | CX3Z3 s1    |
| 3    | +12° | 008° | CX2Z3 s3    |
| 4    | -49° | 199° | CX4Z3 s4    |


Joint CX4Z1 ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 035° | CX3Z5 s3    |
| 2    | -68° | 241° | CX4YZ0 s3   |
| 3    | +12° | 174° | CX4YZ1 s1   |
| 4    | -49° | 339° | CX4Z4 s4    |



# CX3Z0 ↔ CX3Z1

Leg C · **twist 3** (with CX3Z2↔CX3Z3, CX3Z4↔CX3Z5) · 1983 mm





## Joint CX3Z0 ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 112° | CX2Z5 s4    |
| 2    | -12° | 304° | CX2Z3 s1    |
| 3    | +12° | 068° | CX1Z3 s3    |
| 4    | -49° | 203° | CX3Z3 s2    |


## Joint CX3Z1 ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 253° | CX4Z2 s4    |
| 2    | -49° | 308° | CX3Z4 s4    |
| 3    | +12° | 186° | CX4Z5 s2    |
| 4    | -30° | 036° | CX4Z4 s1    |



# CX1Z0 ↔ CX1Z1

Leg C · **twist 1** (with CX1Z2↔CX1Z3, CX1Z4↔CX1Z5) · 1989 mm





Joint CX1Z0    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 144° | BAC s4      |
| 2    | -49° | 233° | CX1Z3 s2    |
| 3    | +12° | 157° | TAC s4      |
| 4    | -12° | 338° | B0A s1      |

Joint CX1Z1    ↓ BOTTOM


| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 206° | CX2Z2 s4    |
| 2    | -30° | 274° | CX1Z4 s2    |
| 3    | +12° | 163° | CX3Z4 s3    |
| 4    | -30° | 005° | CX2Z4 s1    |





# CX3Z4 ↔ CX3Z5

Leg C · **twist 3** (with CX3Z0↔CX3Z1, CX3Z2↔CX3Z3) · 1996 mm





Joint CX3Z4    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 067° | CX2Z1 s2    |
| 2    | -30° | 258° | CX2Z5 s1    |
| 3    | +30° | 029° | CX1Z1 s3    |
| 4    | -49° | 166° | CX3Z1 s2    |


Joint CX3Z5    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 339° | CX3Z2 s4    |
| 2    | -49° | 281° | CX4Z4 s2    |
| 3    | +12° | 209° | CX4Z1 s1    |
| 4    | -30° | 069° | CX4Z0 s1    |



# CX2Z4 ↔ CX2Z5

Leg C · **twist 2** (with CX2Z0↔CX2Z1, CX2Z2↔CX2Z3) · 2005 mm





Joint CX2Z4    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 212° | CX1Z1 s4    |
| 2    | -12° | 039° | CX1Z5 s1    |
| 3    | +30° | 271° | TAB s3      |
| 4    | -49° | 141° | CX2Z1 s4    |


Joint CX2Z5    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 156° | CX3Z4 s2    |
| 2    | -49° | 066° | CX2Z2 s2    |
| 3    | +12° | 188° | CX4Z2 s3    |
| 4    | -30° | 334° | CX3Z0 s1    |



# CX3Z2 ↔ CX3Z3

Leg C · **twist 3** (with CX3Z0↔CX3Z1, CX3Z4↔CX3Z5) · 2006 mm





Joint CX3Z2    ↑ TOP

| SLOT | BEND        | ROT         | CONNECTS TO |
|------|-------------|-------------|-------------|
| 1    | $-49^\circ$ | $028^\circ$ | CX2Z3 s2    |
| 2    | $-30^\circ$ | $237^\circ$ | CX2Z1 s1    |
| 3    | $+30^\circ$ | $333^\circ$ | CX1Z5 s3    |
| 4    | $-68^\circ$ | $132^\circ$ | CX3Z5 s1    |


Joint CX3Z3    ↓ BOTTOM

| SLOT | BEND        | ROT         | CONNECTS TO |
|------|-------------|-------------|-------------|
| 1    | $-49^\circ$ | $309^\circ$ | CX4Z0 s2    |
| 2    | $-49^\circ$ | $016^\circ$ | CX3Z0 s4    |
| 3    | $+30^\circ$ | $240^\circ$ | CX4Z3 s1    |
| 4    | $-30^\circ$ | $094^\circ$ | CX4Z2 s1    |



# CX2Z2 ↔ CX2Z3

Leg C · **twist 2** (with CX2Z0↔CX2Z1, CX2Z4↔CX2Z5) · 2025 mm





Joint CX2Z2    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 273° | CX1Z3 s4    |
| 2    | -49° | 191° | CX2Z5 s2    |
| 3    | +30° | 312° | BAC s3      |
| 4    | -30° | 109° | CX1Z1 s1    |


Joint CX2Z3    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 111° | CX3Z0 s2    |
| 2    | -12° | 272° | CX3Z2 s1    |
| 3    | +12° | 154° | CX4Z0 s3    |
| 4    | -49° | 023° | CX2Z0 s4    |



# CX1Z4 ↔ CX1Z5

Leg C · **twist 1** (with CX1Z0↔CX1Z1, CX1Z2↔CX1Z3) · 2032 mm





## Joint CX1Z4 ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 050° | TAB s2      |
| 2    | -49° | 165° | CX1Z1 s2    |
| 3    | +30° | 101° | BAB s2      |
| 4    | -30° | 254° | BAC s1      |


## Joint CX1Z5 ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 262° | CX2Z4 s2    |
| 2    | -12° | 092° | CX2Z0 s1    |
| 3    | +12° | 200° | CX3Z2 s3    |
| 4    | -49° | 354° | CX1Z2 s2    |



# CX2Z0 ↔ CX2Z1

Leg C · **twist 2** (with CX2Z2↔CX2Z3, CX2Z4↔CX2Z5) · 2040 mm





Joint CX2Z0    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 350° | CX1Z5 s2    |
| 2    | -30° | 153° | CX1Z3 s1    |
| 3    | +30° | 039° | B0A s4      |
| 4    | -49° | 247° | CX2Z3 s4    |


Joint CX2Z1    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -30° | 070° | CX3Z2 s2    |
| 2    | -30° | 238° | CX3Z4 s1    |
| 3    | +12° | 117° | CX4Z4 s3    |
| 4    | -49° | 324° | CX2Z4 s4    |



# CX1Z2 ↔ CX1Z3

Leg C · **twist 1** (with CX1Z0↔CX1Z1, CX1Z4↔CX1Z5) · 2049 mm





Joint CX1Z2    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -30° | 353° | B0A s2      |
| 2    | -49° | 085° | CX1Z5 s4    |
| 3    | +49° | 336° | T0A s4      |
| 4    | -12° | 185° | TAB s1      |


Joint CX1Z3    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 329° | CX2Z0 s2    |
| 2    | -49° | 058° | CX1Z0 s2    |
| 3    | +49° | 280° | CX3Z0 s3    |
| 4    | -30° | 142° | CX2Z2 s1    |



# YZ0 ↔ YZ1

Apex strut • 1791 mm





## Joint YZ0 ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -30° | 106° | T0B s1      |
| 2    | -30° | 346° | T0A s1      |
| 3    | -30° | 226° | T0C s1      |

## Joint YZ1 ↑ TOP


| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 134° | T0C s3      |
| 2    | -49° | 014° | T0A s3      |
| 3    | -49° | 254° | T0B s3      |





# BAC ↔ BOC

Hub strut · 2353 mm





## Joint BAC    ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 178° | CX1Z4 s4    |
| 2    | -49° | 097° | AX1Z4 s3    |
| 3    | +12° | 231° | CX2Z2 s3    |
| 4    | -12° | 007° | CX1Z0 s1    |


## Joint BOC    ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 109° | BX1Z0 s4    |
| 2    | -30° | 279° | BX1Z2 s1    |
| 3    | -30° | 022° | T0A s2      |
| 4    | -12° | 169° | BX2Z0 s3    |



# BAB ↔ BOB

Hub strut · 2353 mm





## Joint BAB ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 178° | BX1Z4 s4    |
| 2    | -49° | 097° | CX1Z4 s3    |
| 3    | +12° | 231° | BX2Z2 s3    |
| 4    | -12° | 007° | BX1Z0 s1    |


## Joint BOB ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 109° | AX1Z0 s4    |
| 2    | -30° | 279° | AX1Z2 s1    |
| 3    | -30° | 022° | TOC s2      |
| 4    | -12° | 169° | AX2Z0 s3    |



# BAA ↔ BOA

Hub strut · 2353 mm





## Joint BAA ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 178° | AX1Z4 s4    |
| 2    | -49° | 097° | BX1Z4 s3    |
| 3    | +12° | 231° | AX2Z2 s3    |
| 4    | -12° | 007° | AX1Z0 s1    |


## Joint BOA ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 109° | CX1Z0 s4    |
| 2    | -30° | 279° | CX1Z2 s1    |
| 3    | -30° | 022° | T0B s2      |
| 4    | -12° | 169° | CX2Z0 s3    |



# TAC ↔ TOC

Hub strut · 2404 mm





## Joint TAC ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 049° | AX1Z2 s4    |
| 2    | -12° | 203° | AX1Z4 s1    |
| 3    | +30° | 098° | AX2Z4 s3    |
| 4    | -30° | 293° | CX1Z0 s3    |


## Joint TOC ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 082° | YZ0 s3      |
| 2    | -49° | 272° | B0B s3      |
| 3    | +12° | 012° | YZ1 s1      |
| 4    | -30° | 179° | BX1Z2 s3    |



# TAA ↔ TOA

Hub strut · 2404 mm





## Joint TAA ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 049° | BX1Z2 s4    |
| 2    | -12° | 203° | BX1Z4 s1    |
| 3    | +30° | 098° | BX2Z4 s3    |
| 4    | -30° | 293° | AX1Z0 s3    |


## Joint TOA ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 082° | YZ0 s2      |
| 2    | -49° | 272° | B0C s3      |
| 3    | +12° | 012° | YZ1 s2      |
| 4    | -30° | 179° | CX1Z2 s3    |



# TAB ↔ TOB

Hub strut · 2404 mm



## Joint TAB ↓ BOTTOM

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -49° | 049° | CX1Z2 s4    |
| 2    | -12° | 203° | CX1Z4 s1    |
| 3    | +30° | 098° | CX2Z4 s3    |
| 4    | -30° | 293° | BX1Z0 s3    |

## Joint TOB ↑ TOP

| SLOT | BEND | ROT  | CONNECTS TO |
|------|------|------|-------------|
| 1    | -68° | 082° | YZ0 s1      |
| 2    | -49° | 272° | B0A s3      |
| 3    | +12° | 012° | YZ1 s3      |
| 4    | -30° | 179° | AX1Z2 s3    |

