


8. Level 3 Repair


8-1. Block Diagram


SM-R730V Block Diagram



8-2. PCB Diagrams


8-2-1. Top





8-3. Flow Chart of Troubleshooting

Equipments



↑ Oscilloscope



↑ Digital Multimeter



↑ Power Supply



↑ + driver, ESD Safe Tweezer






↑ N4010A Wireless Connectivity Analyzer




↑ Soldering iron


8-3-1. Power On









8-3-2. Initial (Lock up)








8-3-3. Charging Part











8-3-4. BT/WIFI







8-3-5. MOTOR







8-3-6. LCD









8-3-7. TSP









8-3-8. CDMA USPCS TX






8-3-9. CDMA US Cellular TX


CONTINUOUS TX ON CONDITION
TX POWER IDX1 APPLIED
US Cellular CH : 363
RBW : 100KHz
VBW : 100KHz
SPAN : 10MHz
REF. LEV. : 10dBm
ATT. : 20dB







8-3-10. CDMA USPCS RX


CONTINUOUS RX ON
RF INPUT : 600CH
AMP : -65dBm







8-3-11. CDMA US Cellular RX


CONTINUOUS RX ON
RF INPUT : 363CH
AMP : -65dBm







8-3-12. GPS






8-3-13. Microphone Part






8-3-14. Speaker Part












8-3-15. Sensor


8-3-15-1 HRM Sensor






8-3-15-2 6-Axis Sensor







8-3-15-3 Barometer Sensor




8-3-15-4 Light Sensor



8-3-15-5 HALL IC Sensor





8-3-16. NFC

