


8. Level 3 Repair

8-1. Components Layout

MAIN PBA (TOP SIDE)




MAIN PBA (BOTTOM SIDE)




8. Level 3 Repair

SUB PBA (TOP SIDE)





SUB PBA (BOTTOM SIDE)




SM-A125F_REV0.3 Block Diagram

2020.10.16




2G	850/ 900/ 1800/ 1900	850/ 900/ 1800/ 1900	850/ 900/ 1800/ 1900
3G	1/ 2/ 4/ 5/ 8	1/ 2/ 4/ 5/ 8	1/ 2/ 4/ 5/ 8
TDD	38/ 40/ 41	38/ 40/ 41	38/ 40/ 41
FDD	1/ 2/ 3/ 4/ 5/ 7/ 8/ 12/ 17/ 26/ 28/ 66	1/ 2/ 3/ 4/ 5/ 7/ 8/ 12/ 17/ 26/ 28/ 66	1/ 2/ 3/ 4/ 5/ 7/ 8/ 12/ 17/ 26/ 28/ 66
SMA	1/ 3/ 5/ 7/ 8	1/ 3/ 5/ 7/ 8	1/ 3/ 5/ 7/ 8

Created date of PCB data : 2020/10/22 18:57:23



VX_Setup(2020-09-29)_HHP

Created date of PCB data : 2020/10/22 18:57:23



Created date of PCB data : 2020/10/19 19:00:21

[illegible]

Model :
Revision :
Manufacture Count :
Charge :
Contact :
Date :
Routing :
Resin :

Created date of PCB data : 2020/10/19 19:00:21




Model :
Revision :
Manufacture Count :
Charge :
Contact :
Date :
Routing :
Resin :

Model :
Revision :
Manufacture Count :
Charge :
Contact :
Date :
Routing :
Resin :

VX_Setup(2020-09-29)_HHP


Created date of PCB data : 2020/10/14 17:32:21



VX_Setup(2020-09-29) HHP



Created date of PCB data : 2020/10/14 17:32:21

Model :
Revision :
Manufacture Count :
Change :
Contact :
Date :
Routing :
Design :




8. Level 3 Repair

8-2. Flow chart of Troubleshooting.

	
Oscilloscope	Digital Multimeter
	
Power Supply	+ driver, ESD Safe Tweezer
	
8960 & Spectrum Analyzer	Soldering iron


8. Level 3 Repair

8-3-1. Power On




8. Level 3 Repair

8-3-2. Initial




8. Level 3 Repair

8-3-3. No Service




8. Level 3 Repair

8-3-4. SIM Part




8. Level 3 Repair

8-3-5. T-Flash Part




8. Level 3 Repair

8-3-6. Cable Charging Part




8. Level 3 Repair

8-3-7. OTG




8. Level 3 Repair

8-3-8-1. Accel. Sensor




8. Level 3 Repair

8-3-8-2. Fingerprint Sensor




8. Level 3 Repair

8-3-9-1. Microphone Part - Main MIC




8. Level 3 Repair

8-3-9-2. Microphone Part - Sub(2nd) MIC




8. Level 3 Repair

8-3-10. Speaker Part




8. Level 3 Repair

8-3-11. Receiver Part




8. Level 3 Repair

8-3-12. BT/WIFI




8. Level 3 Repair

8-3-13. GPS




8. Level 3 Repair

8-3-14. NFC




8. Level 3 Repair

8-3-15. FM radio part




8. Level 3 Repair

8-3-16. Display




8. Level 3 Repair

8-3-17. Quad Camera




8. Level 3 Repair

8-3-18. VT CAMERA




8. Level 3 Repair

8-3-19. Motor




8. Level 3 Repair

8-3-20. GSM 850/900/1800/1900, WCDMA B1/2/4/5/8, LTE B1/2/3/4/5/8/12/13/17/20/26/28/66 PRx




8. Level 3 Repair

8-3-21. LTE B7/38/40/41 PRx




8. Level 3 Repair

8-3-22. GSM 850/900/1800/1900, WCDMA B1/2/4/5/8, LTE B1/2/3/4/5/8/12/13/17/20/26/28/66 DRx




8. Level 3 Repair

8-3-23. LTE B7/38/40/41 DRx



8. Level 3 Repair

8-3-24. GSM 850/900/1800/1900, WCDMA B1/2/4/5/8, LTE B1/2/3/4/5/8/12/13/17/20/26/28/66 Tx



8. Level 3 Repair

8-3-25. LTE B7/38/40/41 Tx

