

ZB501KL RF_INSKU 教育訓練

Presented by:

Date: 2016/

Agenda

- Overview
- LTE Function Placement
- FA issue

Agenda

- Overview
- LTE Function Placement
- FA issue

ZB501KL Band_IN


ZB501KL

2G: 850/900/1800/1900 3G: 1/5/8

FDD-LTE: 1/3/5/8

TDD-LTE: B40

ZB501KL RF Overview



ZB501KL Placement

Bottom View

DRX
Spring

WIFI/BT/GPS
Spring

GPS


BT/WiFi/FM

2/3/4G


DTV

ZB501KL Placement

Top View





Key Components Location






Agenda

- Overview
- **LTE** Function Placement
- FA issue



LTE/WCDMA B1 TX





LTE/WCDMA B1 PRX






LTE/WCDMA B1 DRX





WCDMA B5 TX





WCDMA B5 PRX







WCDMA B5 DRX





LTE/WCDMA B8 TX





LTE/WCDMA B8 PRX





LTE/WCDMA B8 DRX



LTE B3 TX





LTE B3 PRX





Sub board Top

Sub board BOT



LTE B3 DRX





LTE B40 TX



LTE B40 PRX




LTE B40 DRX






- ACLR-

- Check GFL4809 Voltage.
- Check RLC around GFU4601 and GFU4801.




DCDC SKY87006-11






GSM 850 TX






GSM 850 PRX







GSM 900 TX



GSM 900 PRX



GSM 1800 TX



GSM 1800 PRX

GFU9802
GFU9805

GFCON981


GFCON4702

GFCON4703

GFU4701

GFU4901


GFU4501






Main board BOT

Sub board Top





Sub board BOT



GSM 1900 TX



GSM 1900 PRX



- XO Cal Fail-
 - PC8613 and PC8629 short.
- Internal Cal Fail
 - Check GFC4525



Agenda

- Overview
- LTE Function Placement
- FA issue

Antenna

- GSM/WCDMA/LTE TX & RX
 - Check Antenna Spring on sub-board
 - Check Antenna cable
 - Check Antenna Pattern
- LTE DRX
 - Check Antenna Spring on main board
 - Check Antenna Pattern

Wifi/BT 2.4G TRX



GPS


WFU5307
WFU5306

WFU5310

WFU5402

WFU5401

GFU4501



FM

Main board Top

CON2301



WFU5309

Main board BOT

