

Figure 71-42. Engine air management system ejector repair (sheet 1 of 12)




Figure 71-42. Engine air management system ejector repair (sheet 2)




Figure 71-42. Engine air management system ejector repair (sheet 3)





Figure 71-42. Engine air management system ejector repair (sheet 4)






Figure 71-42. Engine air management system ejector repair (sheet 5)





Figure 71-42. Engine air management system ejector repair (sheet 6)



OUTER SKIN LARGE REPAIRS

Figure 71-42. Engine air management system ejector repair (sheet 7)




Figure 71-42. Engine air management system ejector repair (sheet 8)





Figure 71-42. Engine air management system ejector repair (sheet 9)



FRAME, HAT SECTION CRACK REPAIR-CRACKS IN ATTACHMENT FLANGES

Figure 71-42. Engine air management system ejector repair (sheet 10)




Figure 71-42. Engine air management system ejector repair (sheet 11)




Figure 71-42. Engine air management system ejector repair (sheet 12)