



Garage loft · steel versus laminated-wood beam study

Support plan · roof removed



B2 · heavier storage along three walls



GRAVITY SCREEN — NOT A CONSTRUCTION SCHEDULE

Floor: 12 psf dead + 40 psf live in center
Storage bands: 125 psf in 3-ft north/east/west strips
Roof: 15 psf dead + 20 psf maintenance, plan area
Balcony: 15 psf dead + 60 psf live
Steel beam self-weight added separately

All exterior posts and P1–P4 credited as support sites.
Cabinet-frame capacities and foundations not established.
Roof loads require steel transfer framing to beam lines.
Steel buckling, connections, wind/seismic not checked.
LVL plots omit creep; selection screen includes it.