

ROOFING PROS USA



2863 Newcomb ct, Orlando, FL 32826


Prepared for you by Roofing Pros USA, LLC

Roofing Pros USA, LLC
7100 S Us Highway 17/92
Fern Park, FL 32730-2044

Abby Brewer
tel.407-960-6333
email:measurements@roofingprosusa.net

2863 Newcomb ct, Orlando, FL 32826

Report: 68714639



In this 3D model, facets appear as semi-transparent to reveal overhangs.

Claim Information

Reference ID: 095dd152-6910-41e1-97be-978e36c5d22f

PREPARED FOR

Contact: Abby Brewer
Company: Roofing Pros USA, LLC
Address: 7100 S Us Highway 17/92
Fern Park, FL 32730-2044
Phone: 407-960-6333

TABLE OF CONTENTS

Images	1
Length Diagram	4
Pitch Diagram	5
Area Diagram	6
Notes Diagram.....	7
Penetrations Diagram	8
Report Summary	9

MEASUREMENTS

Total Roof Area =1,592 sq ft
Total Roof Facets =4
Predominant Pitch =4/12
Number of Stories <=1
Total Ridges/Hips =59 ft
Total Valleys =22 ft
Total Rakes =85 ft
Total Eaves =88 ft
Estimated Attic=1,503 sq ft
Total Penetrations =4
Total Penetrations Perimeter = 12 ft
Total Penetrations Area = 3 sq ft

Measurements provided by www.eagleview.com**Certified Accurate**www.eagleview.com/Guarantee.aspx


2863 Newcomb ct, Orlando, FL 32826

Report: 68714639

IMAGES

The following aerial images show different angles of this structure for your reference.

Top View




2863 Newcomb ct, Orlando, FL 32826


Report: 68714639

IMAGES

North Side



South Side



2863 Newcomb ct, Orlando, FL 32826


Report: 68714639

IMAGES

East Side



West Side



2863 Newcomb ct, Orlando, FL 32826

Report: 68714639

LENGTH DIAGRAM

Total Line Lengths:

Ridges = 59 ft

Hips = 0 ft

Valleys = 22 ft



Rakes = 85 ft

Eaves = 88 ft

Flashing = 2 ft

Step flashing = 3 ft

Parapets = 0 ft



©2026 Eagle View Technologies, Inc., All Rights Reserved.


Note: This diagram contains segment lengths (rounded to the nearest whole number) over 5.0 Feet. In some cases, segment labels have been removed for readability. Plus signs preface some numbers to avoid confusion when rotated (e.g. +6 and +9).

2863 Newcomb ct, Orlando, FL 32826


Report: 68714639

PITCH DIAGRAM

Pitch values are shown in inches per foot, and arrows indicate slope direction. The predominant pitch on this roof is 4/12



© 2026 Eagle View Technologies, Inc., All Rights Reserved.




Note: This diagram contains labeled pitches for facet areas larger than 20.0 square feet. In some cases, pitch labels have been removed for readability. Blue shading indicates a pitch of 3/12 and greater.

2863 Newcomb ct, Orlando, FL 32826

Report: 68714639

AREA DIAGRAM

Total Area = 1,592 sq ft, with 4 facets.




Note: This diagram shows the square feet of each roof facet (rounded to the nearest Foot). The total area in square feet, at the top of this page, is based on the non-rounded values of each roof facet (rounded to the nearest square foot after being totaled).

2863 Newcomb ct, Orlando, FL 32826


Report: 68714639

NOTES DIAGRAM

Roof facets are labeled from smallest to largest (A to Z) for easy reference.



©2026 Eagle View Technologies, Inc., All Rights Reserved.



2863 Newcomb ct, Orlando, FL 32826

Report: 68714639

PENETRATIONS NOTES DIAGRAM


Penetrations are labeled from smallest to largest for easy reference.

Total Penetrations = 4

Total Penetrations Perimeter = 12 ft

Total Penetrations Area = 3 sq ft

Total Roof Area Less Penetrations = 1,589 sq ft



©2026 Eagle View Technologies, Inc., All Rights Reserved.

2863 Newcomb ct, Orlando, FL 32826

Report: 68714639

REPORT SUMMARY

All Structures

Areas per Pitch	
Roof Pitches	4/12
Area (sq ft)	1591.6
% of Roof	100%

The table above lists each pitch on this roof and the total area and percent (both rounded) of the roof with that pitch.

Structure Complexity		
Simple	Normal	Complex

Waste Calculation									
NOTE: This waste calculation table is for asphalt shingle roofing applications. All values in table below only include roof areas of 3/12 pitch or greater. For total measurements of all pitches, please refer to the Lengths, Areas, and Pitches section below.									
Waste %	0%	4%	7%	9%	11%	14%	19%	24%	29%
Area (Sq ft)	1592	1656	1704	1736	1768	1815	1895	1975	2054
Squares *	16.00	16.66	17.33	17.66	18.00	18.33	19.00	20.00	20.66
	Measured			Suggested					

* Squares are rounded up to the 1/3 of a square


Additional materials needed for ridge, hip, and starter lengths are not included in the above table. The provided suggested waste factor is intended to serve as a guide—actual waste percentages may differ based upon several variables that EagleView does not control. These waste factor variables include, but are not limited to, individual installation techniques, crew experiences, asphalt shingle material subtleties, and potential salvage from the site. Individual results may vary from the suggested waste factor that EagleView has provided. The suggested waste is not to replace or substitute for experience or judgment as to any given replacement or repair work.

Penetrations	1-2	3-4							
Area (sq ft)	0.2	1							
Perimeter (ft)	2	4							

Any measured penetration smaller than 3.0x3.0 Feet may need field verification. Accuracy is not guaranteed. The total penetration area is not subtracted from the total roof area.

2863 Newcomb ct, Orlando, FL 32826

Report: 68714639

All Structures Totals

 Total Roof Facets = 4
 Total Penetrations = 4

Lengths, Areas and Pitches

Ridges = 59 ft (2 Ridges)
 Hips = 0 ft (0 Hips).
 Valleys = 22 ft (2 Valleys)
 Rakes† = 85 ft (9 Rakes)
 Eaves/Starter‡ = 88 ft (7 Eaves)
 Drip Edge (Eaves + Rakes) = 173 ft (16 Lengths)
 Parapet Walls = 0 (0 Lengths).
 Flashing = 2 ft (1 Lengths)
 Step flashing = 3 ft (1 Lengths)
 Total Penetrations Area = 3 sq ft
 Total Roof Area Less Penetrations = 1,589 sq ft
 Total Penetrations Perimeter = 12 ft
 Predominant Pitch = 4/12
Total Area (All Pitches) = 1,592 sq ft

Property Location

 Longitude = -81.1732918
 Latitude = 28.5843951

Notes

This was ordered as a residential property. There were no changes to the structure in the past four years.

Online Maps

Online map of property

http://maps.google.com/maps?f=q&source=s_q&hl=en&geocode=&q=2863+Newcomb+ct,Orlando,FL,32826

Directions from Roofing Pros USA, LLC to this property

http://maps.google.com/maps?f=d&source=s_d&saddr=7100+S+Us+Highway+17/92,Fern+Park,FL,32730-2044&daddr=2863+Newcomb+ct,Orlando,FL,32826

† Rakes are defined as roof edges that are sloped (not level).

‡ Eaves are defined as roof edges that are not sloped and level.

2863 Newcomb ct, Orlando, FL 32826

Report: 68714639

IMPORTANT LEGAL NOTICE AND DISCLAIMER**Notice and Disclaimer**

No Warranty: The Copyrighted Materials are provided to you "as is," and you agree to use it at your own risk.

EagleView Technologies makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise, including but not limited to, content, quality, accuracy, completeness, effectiveness, reliability, fitness for a particular purpose, usefulness, use or results to be obtained from the Copyrighted Materials.

Contractors agree to always conduct a preliminary site survey to verify Roof Report ordered. In the event of an error in a Report, your sole remedy will be a refund of the fees paid by you to obtain this Report.