

PROPERTY CLAIMS NEXT STEPS

1. Contractor

- Select a contractor
 - Ask for references to ensure you have a contractor capable of the necessary repairs.
 - Consider hiring a contractor that is licensed, insured, and bonded.
 - Present the contractor with a copy of our estimate for review. In most cases your contractor will be able to work off the estimate we provide.
 - If your covered claim requires a water mitigation contractor, your policy owes a reasonable amount to complete this work. Should you choose to hire your own mitigation contractor, please have them contact the adjuster to discuss their findings and scope of recommended mitigation actions. This will reduce the likelihood of you incurring out of pocket expenses not covered by your policy.

2. Supplement

- After the estimate has been reviewed with your contractor and we have an agreed scope of work and price, and there are no differences, the repairs can begin. If any issues arise or additional damages are found after the work has begun, have your contractor contact us immediately so that these issues/damages can be reviewed and addressed prior to any work being completed.
- If you proceed with repairs before contacting us to resolve any issues/differences, you may jeopardize your right to collect additional payment under your policy which could result in out of pocket expenses.
- Most differences in the estimates tend to be small and can be settled over the phone or with additional photos. However, in some instances we may want to meet with you and your contractor again to resolve any concerns.
- Please send all claim communications via e-mail to claimdocuments@afics.com with the claim number in the Subject line.

3. Depreciation

- If your policy provides Replacement Cost coverage for an item, you must submit to us copies of the following document(s) applicable to your loss: final invoices (to include contractor's contact information), certificate of completion and/or receipts to repair, rebuild or replace the covered damages in order to recover any owed depreciation. Please forward this information to your adjuster once you have repaired or replaced your damaged property. Please include your claim number on all forms of correspondence.
- Depreciation is recovered on an "as incurred" basis. Up to the recoverable depreciation amount may be claimed upon completion of the work, based on the cost you incurred and subject to any applicable limits.
- Requirements for recovering depreciation vary state by state, therefore, please be sure to review your specific policy and all its endorsements to make sure you follow the necessary steps to obtain any recoverable depreciation.

Disclaimer

This FAQ sheet does not modify your policy language. Please refer to your policy for specific rights, terms and conditions or contact your adjuster.

PROPERTY CLAIM SETTLEMENT FAQs

Q: What is replacement cost value (RCV)?

A: Replacement cost value is the total cost to replace the damaged item with an item of like kind and quality.

Q: What is actual cash value (ACV)?

A: Actual cash value is based on the cost to repair or replace the damaged item with an item of like kind and quality, less depreciation. In other words, ACV is the value of the damaged item at the time of loss, not when the item was originally purchased.

Q: What is depreciation?

A: Depreciation is the reduction in the value of an asset with the passage of time based upon the age, life expectancy, and the condition of the item being replaced. In other words, it is the difference between RCV and ACV.

Q: What is a deductible?

A: A deductible is the amount you must pay for covered damages before an insurance company will pay a claim. You chose this deductible when obtaining your policy. Your claim adjuster will let you know who to pay this amount to or how it will change your settlement.

Q: How do I pay my deductible?

A: If you have a contractor or other repair professional doing the work, you will likely pay your deductible to them. Your deductible is subtracted from the total claim value and payment is made to you.

Q: How am I reimbursed?

A: Reimbursement for repair or replacement of your covered damaged items will be in the form of one or more payments depending on the type of coverage you chose.

Your policy may have replacement cost coverage on the structure or your personal property. If so, a “recoverable depreciation” amount will be listed on the estimate. Upon completion of the work, you may claim up to this amount based on the cost you incurred and subject to any applicable limits. You must assert your claim for recoverable depreciation within the time period identified in your policy - please refer to your policy language. Note that if you do the work yourself, the amount of recoverable depreciation will be impacted.

Q: Am I allowed to upgrade my damaged item(s)?

A: Yes, you are allowed to upgrade your damaged items; however, the policy provides coverage for what you had at the time of loss. Therefore, any upgrades you make will be at your own expense.

Q: Where do I send the repair bills or replacement receipts?

A: Please include your name, phone number and claim number with all documents and send to:

claimdocuments@afics.com

Q: What advice do you have for locating a contractor?

A: As the owner, you are always in control of the work being completed on your property. You may want to select a contractor that is insured and bonded and ask for references. Before repairs are started, present a copy of your adjuster's estimate to your contractor for agreement.

Q: What if my contractor's estimate is different from this estimate?

A: In most cases, your contractor will work off this estimate. If there are differences, we will review and work to resolve them with you and your contractor. *Should you choose to proceed with the repairs before contacting us to resolve any differences, you may jeopardize your right to collect additional monies.*

Continued on the reverse side.

PROPERTY CLAIM SETTLEMENT FAQs

Q: Why is my mortgage company listed on the payment?

A: An insurance policy is a contract with you, us, and any named interest (generally mortgage lenders) listed on the policy. We are required through the terms of this policy to protect their interests as well. Please contact your mortgage company to obtain the steps required to process the payment. These steps can vary dependent upon the amount of the payment and the differing procedures of each lender.

Disclaimer

This FAQ sheet does not modify your policy language. Please refer to your policy for specific rights, terms and conditions or contact your adjuster.

March 27, 2025

BRANDON HARTMAN AND HOLLY
HARTMAN
2115 Hunting Vly NW
North Canton, OH 44720-3910

Claim Number: 01008682015
Date of Loss: 3/16/2025

Summary For Coverage A - Dwelling

Replacement Cost Value	Less Recoverable Depreciation	Less Non Recoverable Depreciation	Actual Cash Value (ACV)
\$18,414.25	(\$225.21)	<\$5,507.20>	\$12,681.84
Less Deductible			(\$1,000.00)
Total ACV Settlement			\$11,681.84

Understanding Your Property Estimate

Unit of Measure

HR – Hour LF – Linear Foot EA – Each SQ – Square SF – Square Foot
SY – Square Yard DA – Day CY – Cubic Yard CF – Cubic Foot RM – Room

Estimate Cover Page.....

The estimate cover page provides the following information:

- A. Your adjuster's contact information
- B. Your claim number

***Important information about the claims process will be on the second page of your estimate.**

Estimate Details.....

The estimate details outline the damages covered by your policy, which is important to share with your contractor.


- C. **Description** – Details describing the action or item being estimated.
- D. **Quantity** – The number of units for an item.
- E. **Unit** – The cost of a single unit.
- F. **Replacement Cost Value (RCV)** – The estimated cost of repairing a damaged item or replacing an item with a similar one. RCV is calculated by multiplying Quantity x Unit.
- G. **Age/Life** – The current age and its life expectancy.
- H. **Depreciation** – Loss of value that has occurred over time due to factors such as age and wear and tear. If depreciation is recoverable, the amount shown will be in parenthesis. *For example (81.61)*
- I. **Non Recoverable Depreciation** – If depreciation is non-recoverable, the amount shown will be shown in brackets. *For example, <506.94>*
- J. **Actual Cash Value (ACV)** – The estimated value of the item or damage at the time of the loss. Generally, ACV is calculated as Replacement Cost Value (RCV) minus Depreciation.
- K. **Totals** – The total RCV, depreciation and ACV for that area.
- L. **Labor Minimum** – Additional labor to perform small repairs for a certain trade.

Your Estimate Summary.....

Each line of coverage in your estimate has a summary page that shows the total estimated cost (RCV and ACV) and the net claim amount for the coverage included in your policy. The example to the right shows both Dwelling and Other Structure coverage summaries.

- M. **Line Item Total** – The sum of all the line items for that particular coverage.
- N. **Replacement Cost Value** – The total RCV of all items for that coverage.
- O. **Actual Cash Value** – The total ACV of all items for that coverage.
- P. **Deductible** – This is the amount of the loss that you are responsible for. Some policies have different deductibles that could apply based on the type of loss you sustained. Please refer to your policy declarations page for further explanation.
- Q. **Net Claim** – The amount payable to you after depreciation and deductible have been applied. This amount can never be greater than your coverage limit.
- R. **Total Recoverable Depreciation** – The total amount of depreciation you can potentially recover.

A	Claim Rep.: Insurance Adjuster	A	Business: (111) 123-4567 E-mail: adjuster@insurance.com
	Estimator: Insurance Adjuster		Business: (111) 123-4567 E-mail: adjuster@insurance.com
B	Claim Number: 123456789	Policy Number: 123456789	Type of Loss: <NONE>
	Date Contacted: 1/8/2024 9:51 AM	Date Received: 1/3/2024 12:00 AM	
	Date of Loss: 1/1/2024 1:11 PM	Date Entered: 1/4/2024 3:34 PM	
	Date Inspected: 1/9/2024 1:38 PM		

Bedroom										Height: 8'
										
			447.99 SF Walls					191.99 SF Ceiling		
			639.98 SF Walls & Ceiling					191.99 SF Floor		
			21.33 SY Flooring					56.00 LF Floor Perimeter		
			56.00 LF Ceiling							
QUANTITY	UNIT	TAX	RCV	AGE/LIFE	USAGE	DEP %	DEPREC.	ACV		
1. Remove Carpet - Standard grade										
191.99 SF	0.20	0.00	38.40	5/10 yrs	Normal	NA	(0.00)	38.40		
2. Carpet - Standard grade										
220.79 SF	2.15	20.93	495.63	5/10 yrs	Normal	50%	(247.82)	247.81		
15 % waste added for Carpet - Standard grade.										
3. Paint the walls - two coats										
447.99 SF	0.60	4.84	273.63	5/15 yrs	Normal	33.33%	(91.21)	182.42		
4. Drywall patch / small repair, ready for paint										
1.00 EA	40.35	0.14	40.49	5/150 yrs	Normal	3.33%	(1.35)	39.14		
5. Contents - move out then reset										
1.00 EA	38.48	0.00	38.48	5/NA	Normal	0%	(0.00)	38.48		
Totals: Bedroom		25.91	886.63				340.38	546.25		
Total: Main Level		25.91	886.63				340.38	546.25		

Fence										
QUANTITY	UNIT	TAX	RCV	AGE/LIFE	USAGE	DEP %	DEPREC.	ACV		
6. R&R Vinyl (PVC) fence, 5'-6" high - full slat										
80.00 LF	35.07	94.85	2,900.45	4/150 yrs	Normal	2.67%	<67.81>	2,832.64		
Totals: Fence		94.85	2,900.45				67.81	2,832.64		

Labor Minimums Applied										
QUANTITY	UNIT	TAX	RCV	AGE/LIFE	USAGE	DEP %	DEPREC.	ACV		
7. Drywall labor minimum*										
1.00 EA	205.79	0.00	205.79	0/NA	Normal	0%	(0.00)	205.79		

Summary for Dwelling		
M	Line Item Total	1,273.37
	Material Sales Tax	37.06
N	Replacement Cost Value	\$1,310.43
	Less Depreciation	(171.60)
O	Actual Cash Value	\$1,138.83
P	Less Deductible	(500.00)
Q	Net Claim	\$638.83
R	Total Recoverable Depreciation	171.60
	Net Claim if Depreciation is Recovered	\$810.43

Summary for Other Structures		
	Line Item Total	1,832.00
	Material Sales Tax	46.42
I	Replacement Cost Value	\$1,878.42
	Less Non-recoverable Depreciation	<506.94>
	Actual Cash Value	\$1,371.48
	Net Claim	\$1,371.48

Note that not all details explained here may be applicable to your claim, policy, or state

Insured: BRANDON HARTMAN AND HOLLY
HARTMAN
2115 Hunting Vly NW
North Canton, OH 44720-3910

Phone: (330) 696-6700

Claim Rep.: Julie Fisher
Estimator: Julie Fisher

Claim Number: 01008682015

Policy Number: 410111379459

Type of Loss: LossCause

Coverage	Deductible	Policy Limit
Coverage A - Dwelling	\$1,000.00	\$447,700.00
Coverage B - Other Structures Blanket	\$0.00	\$5,000.00
Coverage C - Personal Property	\$0.00	\$335,800.00
Coverage D - Loss Of Use	\$0.00	\$134,400.00
Mine Subsidence - Loss of Use	\$0.00	\$134,400.00

Date Contacted: 3/24/2025 12:49 PM
Date of Loss: 3/16/2025 11:00 AM

Price List: OHCA8X_MAR25
Restoration/Service/Remodel

Sales Taxes:	Material Tax	@	0.000%
	Material Sales Tax	@	6.500%
	Cln Matl Tax	@	6.500%
	Cln&Carpet Svc Tax	@	6.500%

Estimate Recap For Coverage A - Dwelling

Description	RCV	Recoverable Depreciation	Non-recoverable Depreciation	ACV
House - Exterior - Siding	972.09	77.24	0.00	894.85
Source - HOVER Roof and Walls - Exterior - Roof1	17,442.16	147.97	5,507.20	11,786.99
	18,414.25	225.21	5,507.20	12,681.84

Exterior

ACV

Total: House	4.97	972.09	77.24	894.85
---------------------	-------------	---------------	--------------	---------------

Exterior



ACV

Page: 5

CONTINUED - Roof1

	QUANTITY	UNIT	TAX	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
6. Roofing felt - 15 lb.	13.50 SQ	45.69	7.41	624.23	0/20 yrs	Avg.	35% [%]	<218.48>	405.75
7. Ice & water barrier	1,243.00 SF	2.15	39.59	2,712.04	0/30 yrs	Avg.	35% [%]	<949.22>	1,762.82
8. Continuous ridge vent - shingle-over style	0.00 LF	12.31	0.00	0.00	0/35 yrs	Avg.	35% [%]	<0.00>	0.00
9. R&R Chimney flashing - average (32" x 36")	1.00 EA	594.41	7.35	601.76	0/35 yrs	Avg.	35% [%]	<210.61>	391.15
10. Drip edge	348.33 LF	3.45	24.91	1,226.65	0/35 yrs	Avg.	35% [%]	<429.33>	797.32
11. Flashing - pipe jack	1.00 EA	64.94	1.17	66.11	0/35 yrs	Avg.	35% [%]	<23.14>	42.97
12. Digital satellite system - Detach & reset	1.00 EA	42.52	0.00	42.52	0/NA	Avg.	35% [%]	<14.88>	27.64
13. Remove Additional charge for high roof (2 stories or greater)	11.84 SQ	6.72	0.00	79.56	0/NA	Avg.	35% [%]	<27.85>	51.71
14. Additional charge for high roof (2 stories or greater)	11.84 SQ	28.97	0.00	343.00	0/NA	Avg.	35% [%]	<120.05>	222.95
15. Dumpster load - Approx. 12 yards, 1-3 tons of debris	1.00 EA	351.67	0.00	351.67	0/NA	Avg.	35% [%]	<123.08>	228.59
16. R&R Cupola - Vinyl	1.00 EA	1,626.65	80.65	1,707.30	13/150 yrs	Avg.	8.67%	(147.97)	1,559.33
Totals: Roof1			370.60	17,442.16				5,655.17	11,786.99
Total: Exterior			370.60	17,442.16				5,655.17	11,786.99
Total: Source - HOVER Roof and Walls			370.60	17,442.16				5,655.17	11,786.99
Line Item Totals: BRANDON_HARTMAN_AND3			375.57	18,414.25				5,732.41	12,681.84

[%] - Indicates that depreciate by percent was used for this item

[M] - Indicates that the depreciation percentage was limited by the maximum allowable depreciation for this item

Grand Total Areas:

2,411.07	SF Walls	0.00	SF Ceiling	2,411.07	SF Walls and Ceiling
0.00	SF Floor	0.00	SY Flooring	499.23	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	0.00	LF Ceil. Perimeter
0.00	Floor Area	0.00	Total Area	0.00	Interior Wall Area
2,411.07	Exterior Wall Area	499.23	Exterior Perimeter of Walls		
2,593.19	Surface Area	25.93	Number of Squares	348.33	Total Perimeter Length
96.40	Total Ridge Length	7.65	Total Hip Length		

Coverage	Item Total	%	ACV Total	%
Coverage A - Dwelling	18,414.25	100.00%	12,681.84	100.00%
Coverage B - Other Structures Blanket	0.00	0.00%	0.00	0.00%
Coverage C - Personal Property	0.00	0.00%	0.00	0.00%
Coverage D - Loss Of Use	0.00	0.00%	0.00	0.00%
Mine Subsidence - Loss of Use	0.00	0.00%	0.00	0.00%
Total	18,414.25	100.00%	12,681.84	100.00%

Summary for Coverage A - Dwelling

Line Item Total	18,038.68
Material Sales Tax	375.57
Replacement Cost Value	\$18,414.25
Less Depreciation	(5,732.41)
Actual Cash Value	\$12,681.84
Less Deductible	(1,000.00)
Net Claim	\$11,681.84
Total Depreciation	5,732.41
Less Non-Recoverable Depreciation	<5,507.20>
Total Recoverable Depreciation	225.21
Net Claim if Depreciation is Recovered	\$11,907.05

Julie Fisher

Recap of Taxes

	Material Tax (0%)	Material Sales Tax (6.5%)	Cln Matl Tax (6.5%)	Cln&Carpet Svc Tax (6.5%)
Line Items	0.00	375.57	0.00	0.00
Total	0.00	375.57	0.00	0.00

Recap by Room

Estimate: BRANDON_HARTMAN_AND3

Area: House

Area: Exterior

Siding

Coverage: Coverage A - Dwelling

100.00% =

967.12

5.36%

967.12

Area Subtotal: Exterior

Coverage: Coverage A - Dwelling

100.00% =

967.12

5.36%

967.12

Area Subtotal: House

Coverage: Coverage A - Dwelling

100.00% =

967.12

5.36%

967.12

Area: Source - HOVER Roof and Walls

Area: Exterior

Roof1

Coverage: Coverage A - Dwelling

100.00% =

17,071.56

94.64%

17,071.56

Area Subtotal: Exterior

Coverage: Coverage A - Dwelling

100.00% =

17,071.56

94.64%

17,071.56

Area Subtotal: Source - HOVER Roof and Walls

Coverage: Coverage A - Dwelling

100.00% =

17,071.56

94.64%

17,071.56

Subtotal of Areas

Coverage: Coverage A - Dwelling

100.00% =

18,038.68

100.00%

18,038.68

Total

18,038.68

100.00%

Recap by Category with Depreciation

Items				RCV	Deprec.	ACV
GENERAL DEMOLITION				1,779.88	599.87	1,180.01
Coverage: Coverage A - Dwelling	@	100.00% =		1,779.88		
ROOFING				15,341.18	4,951.12	10,390.06
Coverage: Coverage A - Dwelling	@	100.00% =		15,341.18		
SIDING				917.62	72.56	845.06
Coverage: Coverage A - Dwelling	@	100.00% =		917.62		
Subtotal				18,038.68	5,623.55	12,415.13
Material Sales Tax				375.57	108.86	266.71
Coverage: Coverage A - Dwelling	@	100.00% =		375.57		
Total				18,414.25	5,732.41	12,681.84



1 1-Back-1.jpg

Taken By: HOVER



2

2-Back-Left-1.jpg

Taken By: HOVER



3 3-Back-Right-1.jpg

Taken By: HOVER



4 4-Front-1.jpg

Taken By: HOVER



5

5-Front-Left-1.jpg

Taken By: HOVER



6 6-Front-Right-1.jpg

Taken By: HOVER




7

7-Right-1.jpg


Taken By: HOVER



8 8-siding, install issues, squirrel? Date Taken: 3/27/2025




9 9-siding, install issues, squirrel? Date Taken: 3/27/2025




10 10-siding, install issues, squirrel? Date Taken: 3/27/2025



11 11-siding, install issues, squirrel? Date Taken: 3/27/2025




12 12-siding, install issues, squirrel? Date Taken: 3/27/2025




13 13-siding, install issues, squirrel? Date Taken: 3/27/2025



14 14-siding, install issues, squirrel? Date Taken: 3/27/2025



15 15-siding, install issues, squirrel? Date Taken: 3/27/2025



16 16-screen behind chewed also Date Taken: 3/27/2025



17 17-shed

Date Taken: 3/27/2025



18 18-shed

Date Taken: 3/27/2025

