

## TEST REPORT

No.: SHIN2608002943CM01\_EN

Issue Date: 2026-09-07

Page: 1 of 3

CUSTOMER NAME: CHONGQING XIANJU NEW MATERIAL CO. LTD  
ADDRESS: XINJIAN VILAGE, JIANGSHENG TOWN, DADUKOU DISTRICT,  
CHONGQING (2-1,JIANGQIAO INDUSTRIAL ZONE B) (F01 LINE  
PRODUCTION PLANT)

Sample Name : FIBER-REINFORCED COMPOSITE PROFILE

Product Specification : 60605

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

\*\*\*\*\*

SGS Ref. No. : NBIN2608000196CM01

Date of Receipt : 2026-08-27

Testing Period : 2026-08-27 ~ 2026-09-07

Test result(s) : For further details, please refer to the following page(s)  
(Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for and on behalf of  
SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.

Ziven Wang

Ziven Wang

Authorized signatory

Scan to see the report



SHIN2608002943CM01  
Verification:  
check.sgs.com.cn



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)

No.69, Block 1159, East Kang Qiao Road, Pudong District, Shanghai, China. 201319

中国·上海·浦东康桥东路1159弄69号 邮编:201319

t(86-21) 61196300 [www.sgsgroup.com.cn](http://www.sgsgroup.com.cn)

t(86-21) 61196300 [sgs.china@sgs.com](mailto:sgs.china@sgs.com)

## TEST REPORT

No.: SHIN2608002943CM01\_EN

Issue Date: 2026-09-07


Page: 2 of 3

### Summary of Results:

| No. | Test Item         | Test Method        | Result  | Conclusion |
|-----|-------------------|--------------------|---------|------------|
| 1   | Full Section Test | EN 13706-2 Annex D | 40.8GPa | N/A        |

Note: Pass : Meet the requirements;  
Fail : Does not meet the requirements;  
N/A : Not Apply to the judgment.

### Original Sample Photo:



Specimen

Cross-section



SGS-CTC (Shanghai) Technical Services (Shanghai) Co., Ltd.  
Commercial Construction Materials Laboratory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)

No.69, Block 1159, East Kang Qiao Road, Pudong District, Shanghai, China. 201319

中国·上海·浦东康桥东路1159弄69号 邮编:201319

t(86-21) 61196300 [www.sgsgroup.com.cn](http://www.sgsgroup.com.cn)

t(86-21) 61196300 [sgs.china@sgs.com](mailto:sgs.china@sgs.com)

# TEST REPORT

No.: SHIN2608002943CM01\_EN

Issue Date: 2026-09-07

Page: 3 of 3

Test Item: Full Section Test

Test Method: EN 13706-2 Annex D

Test Condition:

Specimen: 2160mm×90mm×90mm, 3pcs

Test span:1800mm

Test rate:9mm/min

Test Result:

| Test Item               | Test Result      |      |      |               |
|-------------------------|------------------|------|------|---------------|
|                         | Individual value |      |      | Average value |
| Full Section Test (GPa) | 41.2             | 41.1 | 40.1 | 40.8          |

Note: The test sample is cut from the original sample.

The test report shall only be used for clients' scientific research, teaching, internal quality control, product research and development, etc... and just for internal reference.

\*\*\*\*\*End of report\*\*\*\*\*



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)

No.69, Block 1159, East Kang Qiao Road, Pudong District, Shanghai, China. 201319

中国·上海·浦东康桥东路1159弄69号 邮编:201319

t(86-21) 61196300 [www.sgsgroup.com.cn](http://www.sgsgroup.com.cn)

t(86-21) 61196300 [sgs.china@sgs.com](mailto:sgs.china@sgs.com)