Site Inspection Report

Warehouse B, 300 Example Road (sample)

Summary

The inspection took place on March 12, 2026. The storage area, loading dock and fire exits were checked. Two minor issues were found and one item needs action within thirty days.

Area	Result
Storage area	Pass
Loading dock	Pass with notes
Fire exits	Action needed

Fictitious sample document for a Nutrient demo. All names and figures are invented.

Findings

No.	Finding	Priority	Due
F-01	Exit sign above door 3 is not lit	High	2026-04-11
F-02	Pallets stored close to the sprinkler line	Medium	2026-04-30
F-03	Dock bumper on bay 2 is worn	Low	2026-06-30

2

Site Inspection Report

Photos and sign-off

Photos



Photo 1: exit sign, door 3



Photo 2: bay 2 bumper

Sign-off

Inspector: Sam Placeholder. Site contact: Casey Demo. Next inspection: September 2026.

3