





2014 Suzuki Cultus



Car Detail



Exterior Condition



Legend

U1:Small Dent

A3:Big Scratch

B2: Dent with scratch (size like flat of the hand)

S1: Rust

B3: Big Dent with scratch (size like elbow)

U2:Dent

B1:Small dent with scratch (size like a thumb)

P: Paint marked

A1:Small Scratch

A2:Scratch

W1:Repair Mark/Wave (hardly detectable)

•: Minor Scratches/Dents



Body Frame Accident Checklist

100%

Radiator Core Support	Non-Accidented
Right Strut Tower Apron	Non-Accidented
Left Strut Tower Apron	Non-Accidented
Right Front Rail	Non-Accidented
Left Front Rail	Non-Accidented
Cowl Panel Firewall	Non-Accidented
Right A Pillar	Non-Accidented
Left A Pillar	Non-Accidented
Right B Pillar	Non-Accidented
Left B Pillar	Non-Accidented
Right C Pillar	Non-Accidented
Left C Pillar	Non-Accidented
Right D Pillar	Non-Accidented
Left D Pillar	Non-Accidented
Boot Floor	Non-Accidented
Boot Lock Pillar	Non-Accidented
Front Sub Frame	Non-Accidented
Rear Sub Frame	Non-Accidented

Engine / Transmission / Clutch			93%
Fluids/filters check		Mechanical check	
Engine Oil Level	Complete and Clean	Belts (AC)	Ok
Engine Oil Leakage	No Leakage	Belts (Fan)	Ok
Transmission Oil Level	Incomplete	Wires (Wiring Harness)	Ok
Transmission Oil Leakage	Leakage	Engine Valve Tappet Noise	No Noise
Clutch Cable	Ok	Engine Blow (Manual Check)	Not Present
Brake Oil Level	Complete and Clean	Engine Noise	No Noise
Brake Oil Leakage	No Leakage	Engine Vibration	No Vibration
Washer Fluid Level	Incomplete	Engine Mounts	Ok
Washer Fluid Leakage	No Leakage	Pulleys (Main, Adjuster)	Not Ok
Coolant Leakage	No Leakage	Gear Mounts	Ok
		Hoses	Damaged

Exhaust check	
Catalytic Convertor	Working Ok
Exhaust Sound	Ok
Exhaust Joints	Ok

Engine cooling system	
Radiator	Rusted or Damaged
Suction Fan	Working

Transmission check / power train

Engine electronics	
Starter Operation	Ok

Brakes	
Mechanical check	
Front Right Disc	Smooth
Front Left Disc	Smooth
Front Right Brake Pad	More than 50%
Front Left Brake Pad	More than 50%
Parking / Hand Brake	Ok

Suspension/Steering			93%
Front suspension		Rear suspension	
Right Ball Joint	Ok	Rear Right Bushes	No Damage Found
Left Ball Joint	Ok	Rear Left Bushes	No Damage Found
Right Tie Rod End	Ok	Rear Right Shock	Ok
Left Tie Rod End	Ok	Rear Left Shock	Ok
Right Rack End	Hit Impact or Play		
Left Rack End	Hit Impact or Play		
Front Right Boots	Ok		
Front Left Boots	Ok		
Front Right Bushes	Ok		
Front Left Bushes	Ok		
Front Right Shock	Ok		
Front Left Shock	Ok		

90%

Steering controls		
Steering Wheel Condition	Ok	
Horn	Working	
Lights Lever / Switch (High / Low Beams , Indicators)	Working	
Wiper / Washer Lever (Washer, Speeds)	Not Working	

Mirrors	
Right Side Mirror	Working
Left Side Mirror	Working

Seats	
Right Seat Adjuster Recliner	Working
Left Seat Adjuster Recliner	Working
Right Seat Adjuster Lear Track	Working
Left Seat Adjuster Lear Track	Working
Right Seat Belt	Working
Left Seat Belt	Working
Right Head Rest	Available & Working
Left Head Rest	Available Or Working
Glove Box	Working

Power / manual windows & central locking	
Front Right Power Window/Manual Lever	Working Properly
Fornt Left Power Window/Manual Lever	Working Properly
Rear Right Power Window/Manual Lever	Working Properly
Rear Left Power Window/Manual Lever	Working Properly
Window Safety Lock	Working

Dash / roof controls	
Interior Lightings	Not working
Dash Controls - A/C	Working
Dash Controls - De-Fog	Working
Dash Controls - Hazzard Lights	Not working
Dash Controls - Parking Button	Working
Audio/Video	Working with issues
Cigarette Lighter	Working
Trunk Release Lever / Button	Working
Fuel Cap Release Lever / Button	Working
Bonnet Release Lever / Button	Working

Poshish	
Roof Poshish	Perfect
Floor Mat	Perfect
Front Right Door Poshish	Perfect
Front Left Door Poshish	Perfect
Rear Right Door Poshish	Perfect
Rear Left Door Poshish	Perfect
Front Right Seat Poshish	Perfect
Front Left Seat Poshish	Perfect
Rear Seat Poshish	Perfect
Right Sunshade	Perfect
Left Sunshade	Perfect
Boot Carpet / Mat	Perfect
Boot Board	Damaged
Dashboard Condition	Perfect

Equipment	
Spare Tire	Present
Tools	Complete
Jack	Present

Ac/Heater

78%

Ac / heater check up	
AC Operational	Yes
AC Fitted	Yes
Blower	Excellent Air Throw
Condenser	Choked or Damaged
Compressor Operation	Ok
Cooling	Excellent
Heating	Moderate or Not Working

Electrical & Electronics			100%	
Computer check up		Battery		
Computer Check up / Malfunction	No Error	Voltage	8	
Check		Terminals Condition	Rusted	
Engine Emission Warning Light	Not Present	Charging	Ok	
Battery Warning Light	Not Present	Alternator Operation	Ok	
Oil Pressure Low Warning Light	Not Present	Alternator Operation	OK .	
Temperature Warning Light	Not Present	Instrument cluster	Instrument cluster	
		Gauges	Working	

Exterior & Body 56%

Car frame	
Trunk Lock	Ok
Front Windshield Condition	Ok
Rear Windshield Condition	Ok
Front Right Door Fittings	Ok
Front Left Door Fittings	Ok
Rear Right Door Fittings	Ok
Rear Left Door Fittings	Ok
Front Right Door Levers	Ok
Front Left Door Levers	Ok
Rear Right Door Levers	Ok
Rear Left Door Levers	Ok
Front Right Door Window	Ok
Front Left Door Window	Ok
Rear Right Door Window	Ok
Rear Left Door Window	Ok
Windscreen Wiper	Cleaning Properly

Exterior lights	
Right Headlight (Working)	Not Working
Left Headlight (Working)	Not Working
Right Headlight (Condition)	Repaired
Left Headlight (Condition)	Perfect
Right Taillight (Working)	Working
Left Taillight (Working)	Working
Right Taillight (Condition)	Perfect
Left Taillight (Condition)	Perfect
Number Plate Lights (Working)	Not Working
Number Plate Lights (Condition)	Foggy
Reverse Light (Working)	Working
Reverse Light (Condition)	Perfect
Windscreen Wiper Rubbers	Ok

Tyres 30% **Tyres** Front Right Tyre 53% (remaining life) Front Left Tyre 53% (remaining life) Rear Right Tyre 0% (remaining life) Rear Left Tyre 0% (remaining life) Spare Tyre 69% (remaining life) **Brand Name** Dunlop Tyre Size 175/70/R13 Rims Normal Wheel Caps **Not Present**

Test Drive

Engine Noise (While Driving)	No Noise
Engine Pick	Ok
Clutch Operation (While Driving)	Smooth
Gear Shifting (Manual)	Smooth
Drive Shaft Noise	No Noise
Brake Pedal Operation	Timely Response
Front Suspension (While Driving)	No Noise
Rear Suspension (While Driving)	No Noise
Steering Operation (While Driving)	Smooth
Steering Wheel Alignment (While Driving)	Not Centered
AC Operation (While Driving)	Perfect
Speedometer (While Driving)	Working



fahad - Vehicle Pictures





Chassis No

Odometer



2nd Floor, Saeed Alam Tower, 37 Commercial Zone, Liberty Market, Lahore.

www.pakwheels.com, info@pakeventures.com 042 111 WHEELS (943 357) /pakwheels

Comments

Plug wire weak. Sper tyre stepny minor band and damage.

Disclaimer:

In case of any query or concern regarding inspection please call 042 - 111 WHEELS (042-111 943 357).

This report is based on the condition of the vehicle on the date of certification and provides an approximate estimate of the condition on that date. Except where indicated, the parts were in working condition - this report does not take into account the condition of parts not visible or not inspected. PakWheels.com has relied on the odometer reading for kms driven as seen at the time of inspection and is not responsible for verifying its genuineness. The report is in no way a commitment on the condition of the car. All reports are subjective and PakWheels.com and its associates cannot be held liable in any way due to the use of this report.

 $Unless \ mentioned \ by \ the \ dealer, cars \ with \ W1 \ grade \ paint \ cannot \ be \ detected \ by \ the \ human \ eye, hence \ it \ can \ be \ possible \ for \ such \ paint \ to \ go \ undetected.$