



## **Power Spectral Density**


### **Result Table**


Mode	Channel	Meas.Level [dBm]	Verdict
11B	LCH	-14.629	PASS
11B	МСН	-14.765	PASS
11B	HCH	-13.534	PASS
11G	LCH	-17.097	PASS
11G	MCH	-17.687	PASS
11G	HCH	-17.998	PASS
11N20SISO	LCH	-17.810	PASS
11N20SISO	MCH	-17.424	PASS
11N20SISO	НСН	-18.339	PASS
11N40SISO	LCH	-23.865	PASS
11N40SISO	MCH	-23.117	PASS
11N40SISO	НСН	-22.520	PASS


### **Test Graph**












Report No.: TCT180604E003

## Appendix B: Photographs of Test Setup Product: NVR

Product: NVR Model: ADR42R Radiated Emission





Report No.: TCT180604E003

#### Conducted Emission
















































Report No.: TCT180604E003

Appendix C: Photographs of EUT Product: NVR

Product: NVR Model: ADR42R External Photos









Page 79 of 86



















Report No.: TCT180604E003


Product: NVR Model: ADR42R Internal Photos






## **TCT**






# TCT







### \*\*\*\*\*END OF REPORT\*\*\*\*

