








11N20SISO_HCH_Graphs



Pref/11N20SIS
O/HCH

























Power Spectral Density

Result Table

Mode	Channel	Meas.Level [dBm]	Verdict
11B	LCH	-3.854	PASS
11B	MCH	-3.531	PASS
11B	HCH	-3.452	PASS
11G	LCH	-8.329	PASS
11G	MCH	-6.787	PASS
11G	HCH	-8.558	PASS
11N20SISO	LCH	-9.022	PASS
11N20SISO	MCH	-5.683	PASS
11N20SISO	HCH	-8.797	PASS
11N40SISO	LCH	-13.436	PASS
11N40SISO	MCH	-13.044	PASS
11N40SISO	HCH	-12.979	PASS

Test Graph




11B/MCH




11B/HCH




11G/LCH




11G/MCH




11G/HCH




11N20SISO/LCH



11N20SISO/MCH




11N20SISO/HCH




11N40SISO/LCH



11N40SISO/MCH



11N40SISO/HCH



Appendix A: Photographs of Test Setup

Refer to the test report No. TCT190925E007

Appendix B: Photographs of EUT

Refer to the test report No. TCT190925E007

*******END OF REPORT*******