


Power Spectral Density


Result Table

Mode	Channel	Meas.Level [dBm]	Verdict
11B	LCH	-22.790	PASS
11B	MCH	-22.576	PASS
11B	HCH	-22.522	PASS
11G	LCH	-26.778	PASS
11G	MCH	-26.592	PASS
11G	HCH	-26.404	PASS
11N20SISO	LCH	-26.860	PASS
11N20SISO	MCH	-27.371	PASS
11N20SISO	HCH	-27.421	PASS
11N40SISO	LCH	-30.874	PASS
11N40SISO	MCH	-31.474	PASS
11N40SISO	HCH	-30.827	PASS


Test Graph




11B/MCH




11B/HCH




11G/LCH




11G/MCH




11G/HCH




11N20SISO/LCH




11N20SISO/MCH




11N20SISO/HCH



11N40SISO/LCH





Appendix B: Photographs of Test Setup

Refer to the test report No. TCT190524E001

Appendix C: Photographs of EUT

Refer to the test report No. TCT190524E001

*******END OF REPORT*******