


Test Report	17071411-FCC-R1
Page	41 of 61

Test Mode: Bluetooth Mode

30MHz -1GHz



Test Data

Horizontal Polarity Plot @3m


No.	P/L	Frequency	Reading	Detect	Ant_F	PA_G	Cab_L	Result	Limit	Margin	Height	Degr
	- , -			or								ee
		(MHz)	(dBuV/m)		(dB/m)	(dB)	(dB)	(dBuV/m)	(dBuV/m)	(dB)	(cm)	()
1	Н	38.3462	28.87	peak	15.11	22.27	0.78	22.49	40.00	-17.51	200	225
2	Н	76.7808	42.22	peak	7.66	22.41	0.99	28.46	40.00	-11.54	100	132
3	Н	139.8508	41.67	peak	12.61	22.41	1.27	33.14	43.50	-10.36	100	324
4	Н	210.7860	33.78	peak	11.95	22.36	1.57	24.94	43.50	-18.56	100	201
5	Н	306.7537	35.31	peak	13.74	22.27	1.82	28.60	46.00	-17.40	100	208
6	Н	410.3825	38.95	peak	15.91	21.99	2.03	34.90	46.00	-11.10	100	272



Test Report	17071411-FCC-R1
Page	42 of 61

30MHz -1GHz





Test Data

Vertical Polarity Plot @3m

No.	P/L	Frequency	Reading	Detect	Ant_F	PA_G	Cab_L	Result	Limit	Margin	Height	Degr
		(MHz)	(dBuV/m)	or	(dB/m)	(dB)	(dB)	(dBuV/m)	(dBuV/m)	(dB)	(cm)	()
1	V	37.8121	35.37	peak	15.50	22.27	0.78	29.38	40.00	-10.62	100	281
2	٧	57.9993	44.11	peak	7.52	22.40	0.76	29.99	40.00	-10.01	100	260
3	V	77.0505	49.73	QP	7.66	22.41	1.00	35.98	40.00	-4.02	100	179
4	V	88.0329	49.68	peak	7.92	22.34	1.00	36.26	43.50	-7.24	100	208
5	V	138.8735	37.34	peak	12.67	22.41	1.26	28.86	43.50	-14.64	100	159
6	V	374.6226	40.06	peak	15.17	22.08	2.03	35.18	46.00	-10.82	100	288



Test Report	17071411-FCC-R1
Page	43 of 61

Above 1GHz

Test Mode: Transmitting Mode

Frequency	Meter Reading	Antenna Factor	Cable loss	Preamp factor	Emission Level	Limits	Margin	Detector	Polarity
(MHz)	(dBµV)	(dB)	(dB)	(dB)	(dBµV/m)	(dBµV/m)	(dB)	(PK/AV)	(H/V)
((a.s.p. v)	. ,	, ,	. ,	e(Worst Cas	,	. ,	(14717)	(141)
2390	39.85	28.72	3.36	26.32	45.61	74	-28.39	peak	Vertical
4804	31.28	32.94	3.98	27.49	40.71	54	-13.29	Average	Vertical
4804	40.52	32.94	3.98	27.49	49.95	74	-24.05	peak	Vertical
7206	31.78	25.28	5.51	27.94	34.63	54	-19.37	Average	Vertical
7206	41.23	25.28	5.51	27.94	44.08	74	-29.92	peak	Vertical
2390	40.09	28.72	3.36	26.32	45.85	74	-28.15	peak	Horizontal
4804	31.27	32.94	3.98	27.49	40.70	54	-13.30	Average	Horizontal
4804	41.86	32.94	3.98	27.49	51.29	74	-22.71	peak	Horizontal
7206	31.93	25.28	5.51	27.94	34.78	54	-19.22	Average	Horizontal
7206	43.36	25.28	5.51	27.94	46.21	74	-27.79	peak	Horizontal
'		Middl	e Channe	:GFSK Mo	de(Worst Ca	se)-2441MI	Hz		
4882	30.09	32.11	4.04	27.53	38.71	54	-15.29	Average	Vertical
4882	40.27	32.11	4.04	27.53	48.89	74	-25.11	peak	Vertical
7323	31.18	24.33	5.58	27.96	33.13	54	-20.87	Average	Vertical
7323	41.38	24.33	5.58	27.96	43.33	74	-30.67	peak	Vertical
4882	30.63	32.11	4.04	27.53	39.25	54	-14.75	Average	Horizontal
4882	41.54	32.11	4.04	27.53	50.16	74	-23.84	peak	Horizontal
7323	33.75	24.33	5.58	27.96	35.70	54	-18.30	Average	Horizontal
7323	42.38	24.33	5.58	27.96	44.33	74	-29.67	peak	Horizontal
		High	Channel:	GFSK Mod	e(Worst Cas	se)-2480MH	Z		
2483.5	40.21	28.79	3.48	26.34	46.14	74	-27.86	peak	Vertical
4960	30.87	31.32	4.12	27.58	38.73	54	-15.27	Average	Vertical
4960	40.44	31.32	4.12	27.58	48.30	74	-25.70	peak	Vertical
7440	31.19	24.38	5.68	27.99	33.26	54	-20.74	Average	Vertical
7440	41.35	24.38	5.68	27.99	43.42	74	-30.58	peak	Vertical
2483.5	41.38	28.79	3.48	26.34	47.31	74	-26.69	peak	Horizontal
4960	31.73	31.32	4.12	27.58	39.59	54	-14.41	Average	Horizontal
4960	41.55	31.32	4.12	27.58	49.41	74	-24.59	peak	Horizontal
7440	32.54	24.38	5.68	27.99	34.61	54	-19.39	Average	Horizontal



Test Report	17071411-FCC-R1
Page	44 of 61

Note:

- 1, The testing has been conformed to 10*2480MHz=24,800MHz
- 2, All other emissions more than 30 dB below the limit
- 3, X-Axis, Y-Axis and Z-Axis were investigated. The results above show only the worst case.
- 4, The radiated spurious test above 18GHz is subcontracted to SIEMIC (Nanjing-China) Laboratories. and found 30dB below the limit at least.



Test Report	17071411-FCC-R1
Page	45 of 61

Annex A. TEST INSTRUMENT

Instrument	Model	Serial#	Cal Date	Cal Due	In use
AC Line Conducted					
EMI test receiver	ESCS30	8471241027	09/15/2017	09/14/2018	~
Line Impedance	LI-125A	191106	09/23/2017	09/22/2018	•
Line Impedance	LI-125A	191107	09/23/2017	09/22/2018	~
ISN	ISN T800	34373	09/23/2017	09/22/2018	
Transient Limiter	LIT-153	531118	08/30/2017	08/29/2018	
RF conducted test					
Agilent ESA-E SERIES	E4407B	MY45108319	09/15/2017	09/14/2018	~
Power Splitter	1#	1#	08/30/2017	08/29/2018	>
DC Power Supply	E3640A	MY40004013	09/15/2017	09/14/2018	~
Radiated Emissions					
EMI test receiver	ESL6	100262	09/15/2017	09/14/2018	~
Positioning Controller	UC3000	MF780208282	11/17/2017	11/16/2018	~
OPT 010 AMPLIFIER	04475	0707400400	00/00/0047	00/00/0040	_
(0.1-1300MHz)	8447E	2727A02430	08/30/2017	08/29/2018	~
Microwave Preamplifier					
(1 ~ 26.5GHz)	8449B	3008A02402	03/23/2017	03/22/2018	~
(1 20.001.12)					
Horn Antenna	BBHA9170	3145226D1	09/27/2017	09/26/2018	~
Active Antenna	AL-130	121031	10/12/2017	10/11/2018	V
(9kHz-30MHz)	AL-130	12 103 1	10/12/2017	10/11/2010	14
Bilog Antenna					_
(30MHz~6GHz)	JB6	A110712	09/19/2017	09/18/2018	>
Double Ridge Horn	AH-118	71283	09/22/2017	09/21/2018	V
Antenna (1 ~18GHz)	A11-110	7 1200	0012212011	00/21/2010	T.
Universal Radio	CMU200	121393	09/23/2017	09/22/2018	V
Communication Tester	CIVIUZUU	121393	03/23/2017	0312212010	



Test Report	17071411-FCC-R1
Page	46 of 61

Annex B. EUT And Test Setup Photographs

Photograph: EUT External Photo Annex B.i.

EUT - Front View



EUT - Rear View





Test Report	17071411-FCC-R1
Page	47 of 61

EUT - Top View



EUT - Bottom View





Test Report	17071411-FCC-R1
Page	48 of 61

EUT - Left View




EUT - Right View





Test Report	17071411-FCC-R1
Page	49 of 61

Annex B.ii. Photograph: EUT Internal Photo






Cover Off - Top View 2






Test Report	17071411-FCC-R1
Page	50 of 61

Battery - Front View




Battery - Rear View






Test Report	17071411-FCC-R1	
Page	51 of 61	

Mainboard - Front View




Mainboard - Rear View






Test Report	17071411-FCC-R1	
Page	52 of 61	

Small board - Front View




Small board - Rear View






Test Report	17071411-FCC-R1	
Page	53 of 61	

Connected board - Front View




Connected board - Rear View





Test Report	17071411-FCC-R1
Page	54 of 61

BT - Antenna View






Test Report	17071411-FCC-R1
Page	55 of 61


Annex B.iii. Photograph: Test Setup Photo




Conducted Emissions Test Setup Front View



Conducted Emissions Test Setup Side View



Radiated Spurious Emissions Test Setup Below 1GHz



Radiated Spurious Emissions Test Setup Above 1GHz




Test Report	17071411-FCC-R1
Page	56 of 61

Annex C. TEST SETUP AND SUPPORTING EQUIPMENT

Annex C.ii. TEST SET UP BLOCK


Block Configuration Diagram for AC Line Conducted Emissions





Test Report	17071411-FCC-R1
Page	57 of 61


Block Configuration Diagram for Radiated Emissions (Below 1GHz).





Test Report	17071411-FCC-R1	
Page	58 of 61	

Block Configuration Diagram for Radiated Emissions (Above 1GHz) .





Test Report	17071411-FCC-R1
Page	59 of 61

Annex C. il. SUPPORTING EQUIPMENT DESCRIPTION

The following is a description of supporting equipment and details of cables used with the EUT.

Supporting Equipment:

Manufacturer	Equipment Description	Model	Serial No
Lenovo	Laptop	E40	LR-1EHRX
DCA	Adapter	E2164A	N/A

Supporting Cable:

Cable type	Shield Type	Ferrite Core	Length	Serial No
N/A	N/A	N/A	N/A	N/A



Test Report	17071411-FCC-R1
Page	60 of 61

Annex D. User Manual / Block Diagram / Schematics / Partlist

Please see the attachment



Test Report	17071411-FCC-R1
Page	61 of 61

Annex E. DECLARATION OF SIMILARITY

N/A